N5769X

1962 Cessna 320

Damage History Records

Aircraft S/N: 320-0069



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

INSPECTION RECORD

OCTOBER 2011 HOBBS: 1459.0 N5769X CESSNA 320 S/N 320-0069

CHANGED ENGINE OIL SEE ENGINE LOGS FOR DETAILS. COMPLIED WITH AD 2000-01-16, IAW PARA. (B) VISUAL INSPECTION, NEXT DUE BY HOBBS: 1509.0 OR 10-2012. SERVICED TIRES AND BRAKE MASTER CYLINDERS. SERVICED BATTERYS. GROUND RVN-UP FOR LEAK AND OPERATIONAL CHECK GOOD.

STEVEN R. JOHNSON A&P 585568445

AUGUST 2, 2012 HOBBS: 1469.5 AFTT: 4392.0 N5769X CESSNA 320 S/N 320-0069

THE AIRCRAFT WAS DISASSEMBLED FOLLOWING A GEAR UP LANDING. THE AIRFRAME WAS REASSEMBLED FOR REPAIR. THE WINGS, HORIZONTAL STABILIZER, VERTICAL STABILIZER, RUDDER AND ELEVATORS WERE INSTALLED USING NEW HARDWARE. ALL CONTROL SURFACES WERE RIGGED, CABLE TENSIONS SET AND TRAVELS CHECKED. THE LANDING GEAR WAS CHECKED FOR RIGGING AND OPERATED IN NORMAL AND EMERGENCY MODES WHILE ON JACKS WITH ALL FUNCTIONS SATISFACTORY. THE FLAPS WERE RIGGED AND TRAVELS CHECKED. ALL ELECTRICAL CONNECTIONS BETWEEN THE FUSELAGE AND THE WINGS AND TAIL WERE REPAIRED, RESTORED AND FUNCTION CHECKED. ALL FLUID LINES BETWEEN THE FUSELAGE AND WINGS WERE RESTORED AND FUNCTION CHECKED. THE BRAKE SYSTEMS WAS BLED AND SERVICED WITH 5606 FLUID. THE ENGINES WERE REMOVED FOR INSPECTION AND REINSTALLED (SEE ENGINE LOGBOOKS FOR DETAILS). THE PROPELLERS WERE REMOVED FOR OVERHAUL BY N.M. PROPELLER, CRS# N5PR141Y (SEE PROPELLER LOGBOOK FOR DETAILS) AND REINSTALLED. A J. P. INSTRUMENTS MODEL EDM-760 TWIN ENGINE ANALYZER WAS INSTALLED IAW WITH THE MANUFACTURES INSTALLATION MANUAL DATED 7/20/99 REV NC UNDER STC SA00729SE (SEE FAA FORM 337 DATED 8/28/2012). THE GEAR SWITCH WAS REMOVED AND REPLACED WITH A NEW MS25125-7 SWITCH. THE DME AND TRANSPONDER ANTENNAS WERE REMOVED AND REPLACED WITH NEW CI-105 ANTENNAS. THE COMM ANTENNA ON THE BELLY WAS REMOVED AND REPLACED WITH A NEW CI-122 ANTENNA. THE AILERON TRIM BOTTOM CABLE P/N 0860207-22 WAS REPLACED DUE TO FRAYING. ALL HEATING AND FRESH AIR HOSES WERE REMOVED AND REPLACED WITH NEW SCAT HOSE.

Page 1 of 3 18

INSPECTION RECORD F.A.R. 43.11-91.409

| | | 1.4.1. 43.11-31.403 |
|------|--|--|
| DATE | AIRCRAFT TIME IN SERVICE | KIND OF INSPECTION - STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE |
| | | |
| | E LEFT BELLY S TE P/N 0813011 THE AIRCRAFT NEW HARDWA LOWER LEFT E REMOVED UCTURAL REP DWARE. TH NLG DOOR: VICEABLE PAR 000-59 BRACK H NEW HINGES TH MLG INBOA AIR MANUAL AI E RH INBOARD 0825000-3 WEF FORM 337 DAT E RH OUTBOA | AFT NOSE SKIN P/N 0813000-129, THE LOWER RIGHT AFT NOSE SKIN P/N 0811250-148 DUE TO DAMAGE AND REPLACED WITH NEW CESSNA SKINS IAW THE AIRCRAFT PAIR MANUAL AND AC 43-13 1B, USING THE FACTORY RIVET PATTERN AND NEW S P/N 0813300-1 & 0813300-2 WERE REMOVED DUE TO DAMAGE AND REPLACED WITH TS. REPAIRED BOTH CENTER HINGE ATTACH POINTS ON THE AIRFRAME WITH 2 NEW P/N ETS AND DOUBLERS. REMOVED AND REPLACED BOTH CENTER HINGES P/N 0843538-3 |
| | | |
| | | |

INICDECTION DECODO * THE FLAP ACTUATING SYSTEM WAS REPAIRED BY REPLACING 3 BELLCRANKS (P/N 0862100-10, P/N 0862100-11 AND P/N 0862100-13) AND A FLAP BRACKET P/N 0822275-79. *THE BELLY BEACON WAS REMOVED AND REPLACED WITH A NEW FAA/PMA APPROVED WHELEN STROBE DATE ASSEMBLY P/N 01-0770029-29. *THE 3 LEFT INBOARD COWL FLAP LOUVERS P/N 0851766-4 & -2 WERE REMOVED AND REPLACED WITH NEW CESSNA PARTS. *THE REAR SPAR UPPER AFT FITTING P/N 0811276-3 WAS REMOVED AND REPLACED WITH A SERVICEABLE PART. *THE LEFT WING LOWER FILLET P/N0800056-5 WAS REMOVED AND REPLACED WITH A FABRICATED PART IAW THE AIRCRAFT STRUCTURAL REPAIR MANUAL AND AC 43-13 1B, USING THE FACTORY SCREW PATTERN AND NEW HARDWARE. *THE LEFT NOSE JACK PAD P/N 0811500-1 WAS REPLACED WITH A SERVICEABLE PART. THE FOLLOWING ITEMS WERE REMOVED: *BOTH MASTEN ENGINE ANALYZERS. *OUTSIDE AIR TEMPERATURE INDICATING SYSTEM. THE ABOVE REPAIRS WERE ACCOMPLISHED IAW THE CESSNA 320 MAINTENANCE MANUAL, STRUCTURAL REPAIR MANUAL, ILLUSTRATED PARTS CATALOGUE AND AC 43.13-1B. THE REPAIRS WERE PAINTED TO MATCH THE AIRCRAFT. THE AIRCRAFT WAS WEIGHED AND A NEW WEIGHT AND BALANCE FORM WAS COMPLETED. I CERTIFY THAT THIS AIRFRAME IS AIRWORTHY FOR RETURN TO SERVICE IN REGARDS TO THE WORK PERFORMED. Page 3 of 3 TIMOTHY BOURGOINE CRS# J7BR555 **BODE AVIATION WO# 6374** August 28, 2012 Hobbs: 1469.5 N5769X Cessna 320 S/N: 320-0069 Removed existing audio panel, associated wiring and installed a serviceable Garmin GMA 340 audio panel. Replaced all microphone and headset jacks. Operational check good. Aircraft reweighed as stated in the logbook entry dated August 28, 2012. All work performed IAW with AC 43.13-1B, AC 43.13-2B and Garmin GMA 340 Audio Panel Installation Manual. I certify that this aircraft is airworthy and approved for return to service with respect to the work performed. Josh Frick CRS: J7BR555Y _-WO 6374

| YEAR 20 | | RECORDING TACH | TODAY'S FLIGHT | TOTAL TIME IN | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name. Rating and Certificate Number of |
|------------|---|--|---|--|--|
| DATE | Augus N5769 | t 28, 2012 Hob X L/H Engine | bs reads 1 TCM TSIO | 469.5 TSMOH -470-B sn# 992 | 467.4 Total time 3490.0 82-1-B |
| | counted Counted overhal Aircraft Inc. who manual main is removed and fur publication and results Service N5769 Reinstoiled et good. | erweight bushing erweights reconsuled, see Airon 1 Specialties Reassembled Reassembled System compation no. X420 Splaced all harded overhauled wow 13421. St. Installed netalled propeller engine and serion R. Johnson A. | ngs installer nditioned staft Special | d, TCM MSB see Aircraft Spatties Services ac. wo# 210671 as overhauled new counterwenuts. Installed adapter with obleaned fuel injuneto 500 hour inew. Reinstalled aum pump, sid all baffling ar mounts, bolts haul, see New 12 quarts of Aircraft Services. | ge for inspection IAW TCM SB 96-11B. Crankshaft reconditioned, new 96-10A complied with, see Aircraft Specialties Services, Inc. wo# 210671. Decialties Services, Inc. wo# 210671. Camshaft reconditioned and lifters Inc. wo# 210671. Connecting rods and rocker arms reconditioned, see Inc. All remaining steel parts magnafluxed, see Aircraft Specialties Services, by Divico Inc. see wo# 100640. Engine reassembled IAW TCM Overhaul light pins, plates and snap rings. Installed all new gear bolts, rod bearings, all new locktabs, gaskets, packings and seals. Reinstalled cylinders as verhauled starter shaft and new 654565M015 spring. Reinstalled alternator ectors. Disassembled magnetos and overhauled IAW TCM ignition systems inspection completed. Installed new distributor gears kits, greased bearings and magnetos and timed to engine. Cleaned gapped and tested spark plugs are defined propeller governor after overhaul, see R&D Propeller and remaining plumbing. Installed this engine in L/H position of Cessna 320 and locktabs. Installed overhauled Turbo tailpipe see Knisley wo# 141169. Mexico Aircraft Propeller wo# 4015. Installed new oil filter CH48104-1. Preferoshell 50 wt. detergent oil. Ground run-up for leak and operational check |
| | | | | | |
| | | | | 100 | |
| | | | 40 | | |
| | | | | | |
| | | | | | |
| | | | | | |

MAINTENANCE & SERVICE HISTORY

| Date 2017 | Total Propeller Time | Time Since Overhaul | Description of Work | Authorized Signatures Repairman and Station Certificate Numbers |
|-----------|--|---|--|---|
| 7-20 | | 0.0 | | |
| , | and the same of th | | | |
| N: | 5PR141Y AND WAS ISPECTED IAW WI | s reinstalled. See n Th an <mark>annual inspec</mark> t | OVERHAULED BY NEW MEXICO AIRCF MAP WO# 4015. I CERTIFY THAT THIS ION AND HAS BEEN DETERMINED AIRW | PROPELLER HAS BEEN |
| \$ | | RUN-UP FOR LEAK AND (CRS#J7BR555Y WO# 637 | OPERATIONAL CHECK GOOD. | |
| S | TEVEN JOHNSON | CRS#J7BR555Y WO# 633 | 74 SIMM | |
| S | TEVEN JOHNSON | CRS#J7BR555Y WO# 637 os: 1566.9 TSMOH: 97.4 | 74 | Bode Aviation INC |
| S | TEVEN JOHNSON | CRS#J7BR555Y WO# 633 | 74 | |
| Oc N5 | tober 19, 2013 hobb 769X L/H Propeller 0 hour/Annual inspec | CRS#J7BR555Y WO# 637 DS: 1566.9 TSMOH: 97.4 Hartzell HC-A2MVF-2 s/n | Total 1300.8 Y2912 rdance with far 43 appendix d, using Cest this propeller has been inspected IAW with | Bode Aviation INC CRS J7BR555Y sna model 320 inspection |

| D | ATE RECORDING TOTAL DESCRIPTION OF INSPECTIONS THE | DATE C |
|---|--|--------|
| _ | August 28, 2012 Hobbs reads 1469.5 TSMOH 0.0 Total time 3980.4 N5769X R/H Engine TCM TSIO-470-B sn# 99479-2-R | RIES.) |
| | This engine overhauled IAW TCM Overhaul Manual no. X-30033. Engine disassembled due to propeller strike for inspection IAW TCM SB 96-11B. Crankshaft reconditioned, new counterweight bushings installed, TCM MSB 96-10A complied with, see Aircraft Specialties Services, Inc. wo# 210577. Counterweights reconditioned see Aircraft Specialties Services, Inc. wo# 210577. Crankshaft and lifters reconditioned, see Aircraft Specialties Services, Inc. wo# 210577. All remaining steel parts magnafluxed, see Aircraft Specialties Services, Inc. wo# 210577. Crankcase was overhauled by Divico Inc. see wo# 100636. Engine reassembled IAW TCM Overhaul manual no. X- 30033. using all new counterweight pins, plates and snap rings. Installed all new gear bolts, rod bearings, main bearings rod bolts and nuts. Installed all new locktabs, gaskets, packings and seals. Installed 6 each new TCM 658184A3 cylinder assemblies (manufacture dates March and April 2012 see TCM form 8130). Overhauled starter adapter with all new bearings, overhauled starter shaft and new 539800M030 spring. Installed overhauled starter pr# 646275-1 sn# H-M060450. Installed new Aero-Classics engine oil cooler pn# 8000531 sn# 1371064. Fuel system not overhauled at this time. Cleaned fuel injectors. Disassembled magnetos and overhauled IAW TCM ignition systems publication no. X42002-3. Magneto 500 hour inspection completed. Installed new distributor gears kits, greased bearings and replaced all hardware with new. Reinstalled magnetos and timed to engine. Installed all new RHB 32E spark plugs. Installed overhauled G455 vacuum pump, sn# 49421. Installed propeller governor after overhaul, see R&D Propeller Service wo# 13422. Repaired all engine baffleing as required and reinstalled. Reinstalled alternator as removed. Installed this engine in R/H position of Cessna 320 N5769X. Installed new engine mounts, bolts and locktabs. Reinstalled this engine in R/H position of Cessna 320 N5769X. Installed new engine mounts, bolts and locktabs. Reinstalled propeller after overhaul, see | |
| - | | |
| - | 27 NOVEMBER 2012 HOBBS: 1495.7 TSO 26.2 N5769X R/H ENGINE TCM TSIO-470-B S/N 99479-2-R | |
| - | DRAINED ENGINE OIL, REMOVED AND REPLACED OIL FILTER. SERVICED WITH 11 QTS. OF AEROSHELL 80 NON-DETERGENT. GROUND RUN-UP FOR LEAK AND OPERATIONAL CHECK GOOD. | |
| • | STEVEN R. JOHNSON A&P 585568445 | |

MAINTENANCE & SERVICE HISTORY

| Date 2012 | Total Propeller Time | Time Since Overhaul | Description of Work | Authorized Signatures Repairman and Station Certificate Numbers |
|-----------|--|--|--|---|
| 7-20 | | 0,0 | | |
| THIS N5PF | PROPELLER WAR R141Y AND WAS ECTED IAW WITH | reinstalled. See ni An <mark>annual inspecti</mark> | VF-2 S/N Y2908 VERHAULED BY NEW MEXICO AIRCRAFT MAP WO# 4016. I CERTIFY THAT THIS PRO ON AND HAS BEEN DETERMINED AIRWORT PERATIONAL CHECK GOOD. | OPELLER HAS BEEN |
| | /EN JOHNSON CR | S#J7BR555Y WO# 637 | 4 SHIN | |
| — STEV | | S#J7BR555Y WO# 637- | | Bode Aviation INC |
| Octobe | r 19, 2013 hobbs: 1 | | I 1300.8 | Bode Aviation INC CRS J7BR555Y |