

N207RA

2014 Cessna 208B

CESCOM Maintenance Reports

Aircraft S/N: 208B-5098



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
E140-190415 E1	REVIEW PT6A-140 EMM REV 10.1			MTH		-			
P006-210201 P1	REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35 RPLB			MTH HRS	22-Mar-2021 3753.6	-			
051001	RENEWAL AIRWORTHINESS			MTH HRS LDG	30-Nov-2021 3812.4 6488		12	30-Nov-2022	-5 m 24 d
									Over Due
053400	REPLACE PITOT AND STATIC HOSES			MTH	09-Mar-2014		120	31-Mar-2024	10 m 7 d
053401	UPDATE G1000 NAV DATA RPLB			DAYS HRS LDG	23-Mar-2023 4001.7 6734		28	20-Apr-2023	-1 m 4 d
									Over Due
053700	REPLACE VACUUM HOSES			MTH	09-Mar-2014		120	31-Mar-2024	10 m 7 d
055001	ACCOMPLISH HARD OR OVERWEIGHT LANDING CHECK			MTH	09-Mar-2014		O/C		
055002	ACCOMPLISH OVERSPEED (AIRSPEED) CHECK			MTH	09-Mar-2014		O/C		
055003	ACCOMPLISH SEVERE AIR TURBULENCE OR SEVERE MANEUVERS			MTH	09-Mar-2014		O/C		
055004	ACCOMPLISH LIGHTNING STRIKE CHECK			MTH	09-Mar-2014		O/C		
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK			MTH	09-Mar-2014		O/C		
055006	ACCOMPLISH HIGH DRAG/SIDE LOADS DUE TO GROUND HANDLING CHECK			MTH	09-Mar-2014		O/C		
5-15-01	INSPECTION DOCUMENT 01 RPLB			MTH HRS LDG	23-Mar-2023 4001.7 6734	8	12	31-Mar-2024	10 m 7 d
B262001 FORWARD	WEIGHT CHECK FIRE EXTINGUISHER PORTABLE RPLB		C352TS Y-649628	MTH	23-Mar-2023	-5	12	31-Mar-2024	10 m 7 d
5-15-02	INSPECTION DOCUMENT 02 RPLB			MTH HRS LDG	23-Mar-2022 3883.3 6574		24	31-Mar-2024	10 m 7 d
5-15-03	INSPECTION DOCUMENT 03 RPLB			MTH HRS LDG	28-May-2022 3940.2 6638	-60	48	31-Mar-2026	34 m 7 d
5-15-04	INSPECTION DOCUMENT 04 RPVM			MTH HRS LDG	31-Mar-2020 3628.8 6166	-22	72	31-Mar-2026	34 m 7 d
B262005 FORWARD	RESTORATION FIRE EXTINGUISHER PORTABLE (INTERNAL INSPECTION) RPVM		C352TS Y-649628	MTH HRS LDG	31-Mar-2020 3628.8 6166	-89	72	31-Jan-2026	32 m 7 d
5-15-05	INSPECTION DOCUMENT 05 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH HRS LDG	09-Mar-2014 0 0		144		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262003 FORWARD	HYDROSTATIC TEST FIRE EXTINGUISHER PORTABLE *CF	MTH C352TS Y-649628	01-Jan-2014		144		31-Jan-2026	32 m 7 d
5-15-06	INSPECTION DOCUMENT 06 RPLB	MTH	23-Mar-2023	-31	12		29-Feb-2024	9 m 5 d
		HRS	4001.7		200		4201.7	200
		LDG	6734					
5-15-07	INSPECTION DOCUMENT 07 RPLB	MTH	01-Jul-2022	-20	12		30-Jun-2023	1 m 6 d
		HRS	3965		400		4365	363.3
		LDG	6673					
5-15-08	INSPECTION DOCUMENT 08 RPLB	MTH	15-Jan-2022	14	24		31-Jan-2024	8 m 7 d
		HRS	3841.8		400		4241.8	240.1
		LDG	6530					
5-15-09	INSPECTION DOCUMENT 09 RPLB	MTH	23-Mar-2023	6	12		31-Mar-2024	10 m 7 d
		HRS	4001.7		800		4801.7	800
		LDG	6734					
5-15-10	INSPECTION DOCUMENT 10 RPLB	MTH	23-Mar-2023	-15	24		31-Mar-2025	22 m 7 d
		HRS	4001.7		800		4801.7	800
		LDG	6734					
5-15-11	INSPECTION DOCUMENT 11 RPLB	MTH	18-Mar-2022	11	24		31-Mar-2024	10 m 7 d
		HRS	3880.2		1600		5480.2	1478.5
		LDG	6571					
5-15-12	INSPECTION DOCUMENT 12	MTH	02-Mar-2019		60		31-Mar-2024	10 m 7 d
		HRS	3179.5	10	1600		4789.5	787.8
		LDG	5366					
5-15-13	INSPECTION DOCUMENT 13	MTH	09-Mar-2014					
		HRS	0		20000		20000	15998.3
5-15-14	INSPECTION DOCUMENT 14	MTH	09-Mar-2014					
		HRS	0		5000		5000	998.3
5-15-15	INSPECTION DOCUMENT 15	MTH	09-Mar-2014					
		HRS	0		7500		7500	3498.3
5-15-16	INSPECTION DOCUMENT 16	MTH	09-Mar-2014					
		HRS	0		12500		12500	8498.3
5-15-17	INSPECTION DOCUMENT 17	MTH	09-Mar-2014					
		HRS	0		16500		16500	12498.3
5-15-18	INSPECTION DOCUMENT 18	MTH	09-Mar-2014					
		HRS	0		17500		17500	13498.3
5-15-19	INSPECTION DOCUMENT 19	MTH	09-Mar-2014					
		LDG	0		25000		25000	18266
5-15-20	INSPECTION DOCUMENT 20 RPLB	MTH	04-Nov-2022		12		30-Nov-2023	6 m 6 d
		HRS	3989.7					
		LDG	6716					
5-15-21	INSPECTION DOCUMENT 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) RPLB	MTH	16-Nov-2020		24			
		HRS	3673.1					
		LDG	6209					
B341103 LEFT HAND	FUNCTION CHECK PITOT/STATIC SYSTEM (91.411) RPLB	MTH	04-Nov-2022		24		30-Nov-2024	18 m 6 d
		HRS	3989.7					
		LDG	6716					
B341103 RIGHT HAND	FUNCTION CHECK PITOT/STATIC SYSTEM (91.411) RPLB	MTH	04-Nov-2022		24		30-Nov-2024	18 m 6 d
		HRS	3989.7					
		LDG	6716					
B341103 STANDBY	CALIBRATION TEST ALTIMETER (FAR 91.411) RPLB	MTH	04-Nov-2022		24		30-Nov-2024	18 m 6 d
		HRS	3989.7					
		LDG	6716					
5-15-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) RPLB	MTH	16-Nov-2020		24			
		HRS	3673.1					
		LDG	6209					



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B345001 NO. 1	CALIBRATION TEST TRANSPONDER (FAR 91.413) RPLB			011-00779-10 89128030	MTH 04-Nov-2022		24		30-Nov-2024	18 m 6 d
B345001 NO. 2	CALIBRATION TEST TRANSPONDER (FAR 91.413) RPLB			011-00779-10 89127200	MTH 04-Nov-2022		24		30-Nov-2024	18 m 6 d
5-15-23	INSPECTION DOCUMENT 23				MTH 09-Mar-2014		N/R			
5-15-24	INSPECTION DOCUMENT 24				MTH 09-Mar-2014		N/R			
5-15-25	INSPECTION DOCUMENT 25				MTH 09-Mar-2014 HRS 0		20000		20000	15998.3
B243301	FUNCTIONAL CHECK BATTERY CONCORD SEALED LEAD ACID BATTERY (CAPACITY CHECK) MNL			RG380E/40B 41114653	MTH 27-Jun-2021 HRS 3790 LDG 6464		6		31-Dec-2021	-16 m 24 d
5-15-MA	INSPECTION DOCUMENT MA				MTH 09-Mar-2014 HRS 0		10000		10000	5998.3
5-15-MB	INSPECTION DOCUMENT MB (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 09-Mar-2014 HRS 0 LDG 0		N/A			
5-15-MD	INSPECTION DOCUMENT MD				MTH 09-Mar-2014 LDG 0		15000		15000	8266
5-15-ME	INSPECTION DOCUMENT ME				MTH 09-Mar-2014 HRS 0		5000		5000	998.3
5-15-MF	INSPECTION DOCUMENT MF				MTH 09-Mar-2014 HRS 0		20000		20000	15998.3
5-15-MG	INSPECTION DOCUMENT MG				MTH 09-Mar-2014 HRS 0		5000		5000	998.3
5-15-MH	INSPECTION DOCUMENT MH				MTH 09-Mar-2014 HRS 0		10000		10000	5998.3
5-15-MI	INSPECTION DOCUMENT MI				MTH 09-Mar-2014 HRS 0		5000		5000	998.3
5-15-MJ	INSPECTION DOCUMENT MJ				MTH 09-Mar-2014 HRS 0		5000		5000	998.3
5-15-MK	INSPECTION DOCUMENT MK				MTH 09-Mar-2014 HRS 0		20000		20000	15998.3
5-15-ML	INSPECTION DOCUMENT ML				MTH 09-Mar-2014 HRS 0		20000		20000	15998.3
055010 E1	PERFORMANCE DETERIORATION				MTH 09-Mar-2014		A/R			
055020 E1	ENGINE OVERSPEED				MTH 09-Mar-2014		A/R			
055030 E1	ENGINE OVERTEMPERATURE				MTH 09-Mar-2014		A/R			
055040 E1	ENGINE OVERTORQUE				MTH 09-Mar-2014		A/R			
055050 E1	INADVERTENT CUT-OFF AND RELIGHT DURING TAXI				MTH 09-Mar-2014		A/R			
055060 E1	ENGINE IMMERSION IN WATER				MTH 09-Mar-2014		A/R			
055070 E1	DROPPED ENGINE OR COMPONENT DURING HANDLING				MTH 09-Mar-2014		A/R			

Over Due



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
055080 E1	FOREIGN OBJECT DAMAGE (FOD), MATERIAL INGESTION		MTH	09-Mar-2014		A/R			
055090 E1	BIRD STRIKE/SOFT MATERIAL INGESTION		MTH	09-Mar-2014		A/R			
055100 E1	CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER		MTH	09-Mar-2014		A/R			
055110 E1	PROPELLER SUDDEN STOPPAGE OR STRIKE		MTH	09-Mar-2014		A/R			
055120 E1	PROPELLER LIGHTNING STRIKE		MTH	09-Mar-2014		A/R			
055130 E1	PROPELLER ELECTRICAL LEADS SHORTING		MTH	09-Mar-2014		A/R			
055140 E1	HEAVY/HARD LANDING		MTH	09-Mar-2014		A/R			
055150 E1	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH		MTH	09-Mar-2014		A/R			
055160 E1	SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS		MTH	09-Mar-2014		A/R			
055170 E1	LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE		MTH	09-Mar-2014		A/R			
055180 E1	OIL PRESSURE FOLLOWS THROTTLE		MTH	09-Mar-2014		A/R			
055190 E1	CONTAMINATION BY FIRE EXTINGUISHING AGENTS		MTH	09-Mar-2014		A/R			
055200 E1	AUDIBLE RUBBING, BINDING OR SCRAPING		MTH	09-Mar-2014		A/R			
055210 E1	PROPELLER WINDMILLING AFTER IN-FLIGHT SHUTDOWN		MTH	09-Mar-2014		A/R			
055220 E1	CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL		MTH	09-Mar-2014		A/R			
055230 E1	STARTER-GENERATOR REPLACEMENT		MTH	09-Mar-2014		A/R			
055240 E1	INSPECTION OF MAIN OIL FILTER SECONDARY SCREEN		MTH	09-Mar-2014		A/R			
057010 E1	MINOR INSPECTION	RPLB	MTH	29-Mar-2022		12		31-Mar-2023	-1 m 24 d
				HRS 3897.3		200		(4097.3)4097.3	95.6
				LDG 6587					
									Over Due
610000 P1	OVERHAUL	UNK	MTH	03-Nov-2021		60		30-Nov-2026	42 m 6 d
				HRS 3798.6		3000		(4473.8)6798.6	2796.9
611010 P1	PERIODIC INSPECTION		MTH	28-Mar-2023		12		31-Mar-2024	10 m 7 d
				HRS 4001.7		400		(2076.9)4401.7	400
611025 P1	APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS		MTH						
						A/R			



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
619000 P1	PRE-FLIGHT CHECKS			MTH 25-Mar-2016		A/R			
619010 P1	OPERATIONAL CHECKS			MTH 25-Mar-2016		A/R			
619020 P1	OVERSPEED/OVERTORQUE			MTH 25-Mar-2016		A/R			
619030 P1	LIGHTNING STRIKE			MTH 25-Mar-2016		A/R			
619040 P1	FOREIGN OBJECT STRIKE/GROUND STRIKE			MTH 25-Mar-2016		A/R			
619050 P1	FIRE/HEAT DAMAGE			MTH 25-Mar-2016		A/R			
619060 P1	SUDDEN STOPPAGE			MTH 25-Mar-2016		A/R			
619070 P1	ENGINE OIL CONTAMINATION			MTH 25-Mar-2016		A/R			
619080 P1	LONG TERM STORAGE			MTH 25-Mar-2016		A/R			
710010 E1	OVERHAUL ENGINE			MTH 09-Mar-2014 HRS 0		4000		10-Feb-2023 (4200)4200	-3 m 14 d 198.3 Over Due
710020 E1	INSPECT HOT SECTION	RPLB		MTH 13-Feb-2018 HRS 1995.4 LDG 3029		2000		(3995.4)3995.4	-6.3 Over Due
710030 E1	BORESCOPE INSPECT HOT SECTION	RPLB		MTH 07-Jan-2022 HRS 3841.8 LDG 6530		400		(4241.8)4241.8	240.1
710050 E1	DO A COMPRESSOR DESALINATION WASH			MTH 17-Dec-2020 HRS 3687.6 LDG 6227		A/R			
710051 E1	DO A TURBINE DESALINATION WASH			DAYS 09-Mar-2014		A/R			
710055 E1	PERFORM PERFORMANCE RECOVERY WASH			DAYS 06-May-2021		A/R			
720010 E1	PERFORM CORROSION INHIBITION PROCEDURE			MTH 09-Mar-2014		A/R			
725016 E1	INSPECT COMPRESSOR TURBINE DISK AND BLADE SET			MTH HRS		4000		10-Feb-2023 (4200)4200	-3 m 14 d 198.3 Over Due
731025 E1	CLEAN/LEAK/FUNCTIONAL TEST FUEL MANIFOLD AND NOZZLES			MTH 06-May-2019 HRS 3431.7 LDG 5821		400		(3831.7)3831.7	-170 Over Due
731040 E1	GENERAL VISUAL INSPECTION FUEL PUMP INLET SCREEN	RPLB	3040760 012610	MTH 21-Mar-2021 HRS 3753.6 LDG 6381		600		(4353.6)4353.6	351.9
733010 E1	GENERAL VISUAL INSPECTION PNEUMATIC P3 FILTER DRAIN VALVE	RPLB		MTH 01-Jul-2022 HRS 3965 LDG 6673		200		(4165)4165	163.3



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
733020 E1	CLEAN/REPLACE PNEUMATIC P3 FILTER DEPENDING ON CONDITION	RPLB		MTH 01-Jul-2022 HRS 3965 LDG 6673		100		(4065)4065	63.3
733040 E1	CLEAN/REPLACE PNEUMATIC P3 PERMANENT FILTER BASED ON CONDITION, SERVICE EXPERIENCE OR ENVIRONMENT. SHIP TO AN APPROVED OVERHAUL FACILITY FOR ULTRASONIC CLEANING.			MTH 06-Feb-2019 HRS 3080.6 LDG 5184		1000		(4080.6)4080.6	78.9
741010 E1	DO A VISUAL INSPECTION OF THE IGNITION EXCITER	RPLB		MTH 21-Mar-2021 HRS 3753.6 LDG 6381	-101.4	400		(4052.2)4052.2	50.5
741025 E1 4 O'CLOCK	GENERAL VISUAL INSPECTION SPARK IGNITER	RPLB	CH34055 NSN	MTH 21-Mar-2021 HRS 3753.6 LDG 6381		400		(4153.6)4153.6	151.9
741035 E1 9 O'CLOCK	GENERAL VISUAL INSPECTION SPARK IGNITER	RPLB	CH34055 NSN	MTH 21-Mar-2021 HRS 3753.6 LDG 6381		400		(4153.6)4153.6	151.9
741050 E1	DO A VISUAL INSPECTION OF THE IGNITION CABLES	RPLB		MTH 21-Mar-2021 HRS 3753.6 LDG 6381	-101.4	400		(4052.2)4052.2	50.5
742010 E1	DO A FUNCTIONAL CHECK OF THE IGNITION CABLE	RPLB		MTH 21-Mar-2021 HRS 3753.6 LDG 6381	-101.4	400		(4052.2)4052.2	50.5
750020 E1	GENERAL VISUAL INSPECTION OF THE COMPRESSOR BLEED VALVE		3049038-03 8059	MTH 17-May-2019 HRS 3439.1 LDG 5837		600		(4039.1)4039.1	37.4
760000 E1	DOWNLOAD ECTM	RPLB		DAYS 23-Mar-2023 HRS 4001.7 LDG 6734		10		02-Apr-2023	-1 m 22 d
790010 E1	OIL CHANGE	RPLB		MTH 21-Mar-2021 HRS 3753.6 LDG 6381		O/C			Over Due
790050 E1	REPLACE OIL FILTER	RPLB		MTH 09-Dec-2021 HRS 3813.4 LDG 6490		1000		(4813.4)4813.4	811.7
790070 E1	GENERAL VISUAL INSPECTION AGB INTERNAL SCAVENGE OIL PUMP INLET SCREEN	RPLB		MTH 04-Nov-2022 HRS 3989.7 LDG 6716		6		31-May-2023	7 d
790090 E1	GENERAL VISUAL INSPECTION CHIP DETECTOR FOR DEBRIS	RPLB	PN SN-UNKNOWN	MTH 01-Jul-2022 HRS 3965 LDG 6673		200		(4165)4165	163.3



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
210856	CABIN TEMP CONTROL			1H102-2 12BJ114	MTH 09-Mar-2014		O/C	0		
210858	PRESSURE REGULATOR			1H75-21 11BJ175	MTH 09-Mar-2014		O/C	0		
210860	MIXER MUFFLER ASSEMBLY			2613421-1 NSN	MTH 09-Mar-2014		O/C	0		
215001 AFT	EVAPORATOR 2601275			1134200-28 811	MTH 09-Mar-2014		O/C	0		
215001 LEFT	EVAPORATOR MNL			1250327-3 NSN	MTH 28-Mar-2015 LDG 265		O/C	0 0 0		
215001 RIGHT	EVAPORATOR 2601275			1134380-4 989	MTH 09-Mar-2014		O/C	0		
215003	CONDENSOR			1134305 1303	MTH 09-Mar-2014		O/C	0		
215004	HIGH PRESSURE SWITCH			1250232-7 729	MTH 09-Mar-2014		O/C	0		
215008	COMPRESSOR			4292U1 00256311370	MTH 09-Mar-2014		O/C	0		
221001 NO. 1	GSA 80 TORQUE (ROLL) SERVO			011-00877-20 19Z007227	MTH 09-Mar-2014		O/C	0		
221001 NO. 2	GSA 80 TORQUE (YAW) SERVO			011-00877-20 19Z007233	MTH 09-Mar-2014		O/C	0		
221002 NO. 1	GSA 81 (PITCH) TORQUE SERVO			011-00878-20 1A1009841	MTH 09-Mar-2014		O/C	0		
221002 NO. 2	GSA 81 (PITCH) TORQUE SERVO			011-00878-20 1A1009845	MTH 09-Mar-2014		O/C	0		
221003 AILERON	SERVO MOUNT ROLL			011-02490-04 1GK009872	MTH 09-Mar-2014		O/C	0		
221003 ELEVATOR	SERVO MOUNT PITCH			011-02490-04 1GK009403	MTH 09-Mar-2014		O/C	0		
221003 RUDDER	SERVO MOUNT YAW			011-02490-05 1GK009409	MTH 09-Mar-2014		O/C	0		
221003	SERVO MOUNT TRIM			011-02490-06 1GK009411	MTH 09-Mar-2014		O/C	0		
230008 PILOT	PILOT AUDIO PANEL GMA1347			011-00809-00 47115238	MTH 09-Mar-2014		O/C	0		
230010 LEFT	VHF ANTENNA *CF			CI268-60 418569	MTH 09-Mar-2014		O/C	0		
230010 RIGHT	VHF ANTENNA			CI268-60 441351	MTH 09-Mar-2014		O/C	0		
240000	GENERATOR CONTROL UNIT			51539-012N P2275	MTH 09-Mar-2014		O/C	0		
240125	ALTERNATOR CONTROL ASSEMBLY			2618510-10 467	MTH 09-Mar-2014		O/C	0		
240220	OVERVOLTAGE SENSOR			C593005-0101 80K93415	MTH 09-Mar-2014		O/C	0		
240301	STARTER GENERATOR RPLB			200SGL153Q 3798XL	MTH 17-Nov-2020 HRS 3669 LDG 6205		2000	0	5669	1667.3
240401	ALTERNATOR 9910592-2			ASG12000-2 H-N070361	MTH 09-Mar-2014		O/C	0		
240501	BATTERY LEAD ACID			RG380E/40B 41114653	MTH 20-Dec-2020 HRS 3690.8 LDG 6232		O/C			
243000 AFT	POWER CONVERTER			0518021-3 2013080055	MTH 09-Mar-2014		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
243000 FORWARD	POWER CONVERTER			0518021-3 2013010690	MTH 09-Mar-2014		O/C	0		
243003	EMERGENCY POWER CONTROL CABLE			38047100 NSN	MTH 09-Mar-2014		O/C	0		
255004	SEALED TANK ASSEMBLY - NO POD			2616017-841-35 SN-UNKNOWN	MTH 09-Mar-2014		O/C	0		
256010	ELT TRANSMITTER ARTEX C406-N			453-5060 14616	MTH 09-Mar-2014		O/C	0		
256015	REPLACE ELT BATTERY RPVM			452-0133 379163-035	MTH 05-Apr-2019 HRS 3335.9 LDG 5645		DUE DUE DUE DUE	0 0	01-Nov-2023	5 m 8 d
Expiration Date: 01-Nov-2023										
256020	ELT ANTENNA C406-N			110-338 404710	MTH 09-Mar-2014		O/C	0		
260101 FORWARD	FIRE EXTINGUISHER	*CF		C352TS Y-649628	MTH 09-Mar-2014		O/C	0		
260105	FIRE DETECTION CABLE			244-20922 134503	MTH 09-Mar-2014		O/C	0		
260201 NO. 1	FIRE DETECTION CABLE			644-13403485 134509	MTH 09-Mar-2014		O/C	0		
260201 NO. 2	FIRE DETECTION CABLE			644-03603416 133815	MTH 09-Mar-2014		O/C	0		
260225	FIRE BOX			477-90008 1325-257	MTH 09-Mar-2014		O/C	0		
270101 LEFT INBOARD FORWARD	FLAP BELLCRANK			2622258-1 SN-UNKNOWN	MTH 06-May-2019 HRS 3431.7 LDG 5821		A/R			
270101 RIGHT INBOARD FORWARD	FLAP BELLCRANK			2622311-16 1545	MTH 09-Mar-2014 LDG 0			0 0	40000	33266
270102 BOTTOM	FLAP BELLCRANK BEARING			KP5A-H NSN	MTH 09-Mar-2014 LDG 0			0 0	10000	3266
270102 TOP	FLAP BELLCRANK BEARING			KP5A-H NSN	MTH 09-Mar-2014 LDG 0			0 0	10000	3266
270103	FLAP BELLCRANK BOLT			AN5-77 NSN	MTH 09-Mar-2014 LDG 0			0 0	10000	3266
270601	AILERON TRIM ACTUATOR			2661615-10 NSN	MTH 09-Mar-2014		O/C	0		
271401 LEFT	ELEVATOR TRIM ACTUATOR 2660017-1			2661215-9 NSN	MTH 09-Mar-2014		O/C	0		
271401 RIGHT	ELEVATOR TRIM ACTUATOR 2660017-1			2661215-9 NSN	MTH 09-Mar-2014		O/C	0		
271502	FLAP ACTUATOR ASSEMBLY 9910586-4			D145-00-46-3 1836	MTH 09-Mar-2014		O/C	0		
271508 AFT	FLAP ACTUATOR MOTOR			C145-350 NSN	MTH 09-Mar-2014		O/C	0		
271508 FWD	FLAP ACTUATOR MOTOR			C145-350 NSN	MTH 09-Mar-2014		O/C	0		
271700	FLAP ACT ASSY SWITCH			2662021-4 NSN	MTH 09-Mar-2014		O/C	0		
271903	STALL WARNING LIFT TRANSDUCER RPLL			799-1 113	MTH 20-Apr-2016 HRS 867.5 LDG 1100		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
273000 AFT 273001	ELEVATOR PUSHROD			2634027-3	MTH 09-Mar-2014			0		
				589	LDG 0		40000	0	40000	33266
273000 FORWARD 273001	ELEVATOR PUSHROD			2613440-5	MTH 09-Mar-2014			0		
				823	LDG 0		40000	0	40000	33266
275101	POTENTIOMETER			RV2NAYSD502C	MTH 09-Mar-2014		A/R	0		
				NSN						
277001	RUDDER GUST LOCK KIT			4111-1	MTH 09-Mar-2014		O/C	0		
				100005						
280005	LED PNL-FUEL SEL W/O OXYGEN			92-1117-1	MTH 09-Mar-2014		O/C	0		
				0033						
280347	FUEL PRESSURE SWITCH			S2615-4	MTH 10-Sep-2015		O/C	0		
	MNL			0270	HRS 476.7			0		
					LDG 549					
280348	WBA FUEL DELAY RELAY			2677106-804	MTH 09-Mar-2014		O/C	0		
				1154						
280389	FUEL SHUTOFF VALVE			72DA0358	MTH 09-Mar-2014		O/C	0		
				NSN						
280414	ELEC FUEL BOOST PUMP			2C6-10	MTH 09-Mar-2014		O/C	0		
				SN-UNKNOWN						
280418	PUMP EJECTOR			68E101-19	MTH 09-Mar-2014		O/C	0		
				SN-UNKNOWN						
280421	FUEL CHECK VALVE			6C172	MTH 09-Mar-2014		O/C	0		
				SN-UNKNOWN						
280433	LW FUEL WARN SWITCH			GF5500-82	MTH 09-Mar-2014		O/C	0		
				SN-UNKNOWN						
280500	FUEL TO ENGINE HOSE			S2808-8B0520	MTH 09-Mar-2014		120	0	31-Mar-2024	10 m 7 d
	AE3663726H0520			NSN						
280600	MOTIVE FLOW HOSE			S2808-6-0330	MTH 09-Mar-2014		120	0	31-Mar-2024	10 m 7 d
	AE3663724G0330			NSN						
280702 L1	FUEL LEVEL SENSOR			76-207-11	MTH 09-Mar-2014		O/C	0		
	*CF			AAR0110						
280702 L2	FUEL LEVEL SENSOR			76-207-12	MTH 09-Mar-2014		O/C	0		
				AAR0110						
280702 R1	FUEL LEVEL SENSOR			76-207-11	MTH 09-Mar-2014		O/C	0		
	*CF			AAR0111						
280702 R2	FUEL LEVEL SENSOR			76-207-12	MTH 09-Mar-2014		O/C	0		
				AAR0102						
280713 NO. 1	LOW FUEL LEVEL SWITCH			GF5500-81	MTH 09-Mar-2014		O/C	0		
				1341536						
280713 NO. 2	LOW FUEL LEVEL SWITCH			GF5500-81	MTH 09-Mar-2014		O/C	0		
				1323404						
280719	FUEL TOTALIZER INDICATOR			DSF1546-4	MTH 09-Mar-2014		O/C	0		
	9910338-4			NSN						
280726	FUEL FLOW TRANSDUCER			TFF2905-13	MTH 09-Mar-2014		O/C	0		
	9910338-6			AAR044						
283010	FUEL CONDITION CONTROL CABLE			38047200	MTH 09-Mar-2014		O/C	0		
				NSN						
284001	SIGNAL CONDITIONER			85-292-5	MTH 09-Mar-2014		O/C	0		
				AAR0063						
300009	DE-ICE PRESS SWITCH			3D3535-15	MTH 09-Mar-2014		O/C	0		
				NSN						
313104	FLIGHT DATA RECORDER			PN	MTH 09-Mar-2014		N/A	0		
				SN-UNKNOWN						
313106	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY			PN			N/A			
				SN-UNKNOWN						



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
320003	NOSE GEAR SPRING SUPPORT ASSEMBLY		MTH 09-Mar-2014			0		
AFT		2643055-5 23733033N	LDG 0		40000	0	40000	33266
320003	NOSE GEAR SPRING SUPPORT ASSEMBLY		MTH 09-Mar-2014			0		
FORWARD		2643103-1 23759410J	LDG 0		40000	0	40000	33266
320004	NOSE GEAR SPRING FORK ASSY	2643031-7 23925908	MTH 09-Mar-2014 LDG 0		40000	0	40000	33266
320007	SHIMMY DAMPER	SE-1070-6 LK02514	MTH 09-Mar-2014		O/C	0		
320008	NOSE GEAR DRAG LINK SPRING	2643062-804-1 23925908	MTH 09-Mar-2014 LDG 0		15000	0	15000	8266
320009	NOSE GEAR ASSEMBLY 22 X 8.00	2643100-20 23989295	MTH 09-Mar-2014 LDG 0		40000	0	40000	33266
320012	MAIN GEAR SPRING	2641013-17	MTH 09-Mar-2014			0		
LEFT		23548207C	LDG 0		31500	0	31500	24766
320012	MAIN GEAR SPRING	2641013-17	MTH 09-Mar-2014			0		
RIGHT		23485445H	LDG 0		31500	0	31500	24766
320013	MAIN LANDING GEAR CENTER SPRING	2694007-9 23720341C	MTH 09-Mar-2014 LDG 0		31500	0	31500	24766
320014	MLG TRUNNION ASSEMBLY	2641012-13	MTH 09-Mar-2014			0		
LEFT		23490733F	LDG 0		31500	0	31500	24766
320014	MLG TRUNNION ASSEMBLY	2641012-14	MTH 09-Mar-2014			0		
RIGHT		23555885F	LDG 0		31500	0	31500	24766
320015	MLG ATTACH PIN	2641008-2	MTH 09-Mar-2014			0		
LEFT		23969653A	LDG 0		31500	0	31500	24766
320015	MLG ATTACH PIN	2641008-2	MTH 09-Mar-2014			0		
RIGHT		23969653C	LDG 0		31500	0	31500	24766
320016	MLG AXLE FITTINGS	2641010-7	MTH 09-Mar-2014			0		
LEFT		23654578F	LDG 0		31500	0	31500	24766
320016	MLG AXLE FITTINGS	2641010-7	MTH 09-Mar-2014			0		
RIGHT		23654577N	LDG 0		31500	0	31500	24766
320301	MLG TIRE	110T01-3	MTH 12-Feb-2019		O/C	0		
LEFT	301-490-030	72782575	HRS 3109.3 LDG 5237			0		
320301	MLG TIRE	202052	MTH 04-Dec-2020		O/C			
RIGHT		90802628	HRS 3684.4 LDG 6222					
320302	MAIN WHEEL	040-17900	MTH 09-Mar-2014		O/C	0		
LEFT	C163001-1001	NSN						
320302	MAIN WHEEL	040-17900	MTH 09-Mar-2014		O/C	0		
RIGHT	C163001-1001	NSN						
320801	NOSE WHEEL	40-177A	MTH 09-Mar-2014		O/C	0		
		NSN						
320802	NLG TIRE	228K61-1	MTH 07-May-2019		O/C	0		
	C262030-0101	71912385	HRS 3431.7 LDG 5821			0		
321000	MSTR CYLINDER BRAKE	2682001-1	MTH 09-Mar-2014		O/C	0		
LEFT		NSN						
321000	MSTR CYLINDER BRAKE	2682001-1	MTH 09-Mar-2014		O/C	0		
RIGHT		NSN						
321086	MLG AXLE	1004395	MTH 14-Jun-2014			0		
LEFT	UNK	SN-UNKNOWN	HRS 5.4 LDG 5		31500	0	31505	24771



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
321086 RIGHT	MLG AXLE	UNK		1004395 SN-UNKNOWN	MTH 14-Jun-2014 HRS 5.4 LDG 5		31500	0	31505	24771
321101 LEFT	BRAKE ASSEMBLY			030-18200 NSN	MTH 09-Mar-2014		O/C	0		
321101 RIGHT	BRAKE ASSEMBLY			030-18200 NSN	MTH 09-Mar-2014		O/C	0		
321102 LEFT	BRAKE CYLINDER			061-11800 NSN	MTH 09-Mar-2014		O/C	0		
321102 RIGHT	BRAKE CYLINDER			061-11800 NSN	MTH 09-Mar-2014		O/C	0		
321106 LEFT	BRAKE PRESSURE PLATE			073-08500 NSN	MTH 09-Mar-2014		O/C	0		
321106 RIGHT	BRAKE PRESSURE PLATE			073-08500 NSN	MTH 09-Mar-2014		O/C	0		
321107 LEFT	MLG BRAKE LINING			066-03300 SN-UNKNOWN	MTH 10-Jul-2019 HRS 3550.1 LDG 6022		O/C			
321107 RIGHT	MLG BRAKE LINING			066-03300 SN-UNKNOWN	MTH 10-Jul-2019 HRS 3550.1 LDG 6022		O/C			
321108 LEFT	BRAKE DISC			164-22201 NSN	MTH 09-Mar-2014		O/C	0		
321108 RIGHT	BRAKE DISC			164-22201 NSN	MTH 09-Mar-2014		O/C	0		
321110 LEFT	BRAKE BACKING PLATE			074-06600 NSN	MTH 09-Mar-2014		O/C	0		
321110 RIGHT	BRAKE BACKING PLATE			074-06600 NSN	MTH 09-Mar-2014		O/C	0		
321118 LEFT	TORQUE PLATE			075-17100 NSN	MTH 09-Mar-2014		O/C	0		
321118 RIGHT	TORQUE PLATE			075-17100 NSN	MTH 09-Mar-2014		O/C	0		
321201	PARKING BRAKE CONTROL ASSEMBLY			S1779-3 NSN	MTH 09-Mar-2014		O/C	0		
330312	GRAPHIC SIGN			100-9042-03 13J459	MTH 09-Mar-2014		O/C	0		
330701 RIGHT	RIGHT LANDING LIGHT			4553 NSN	MTH 09-Mar-2014		O/C	0		
330701	LEFT LANDING LIGHT			4553 NSN	MTH 09-Mar-2014		O/C	0		
330702 RIGHT	RIGHT TAXI LIGHT			4626 NSN	MTH 09-Mar-2014		O/C	0		
330702	LEFT TAXI LIGHT			4626 NSN	MTH 09-Mar-2014		O/C	0		
331001	LED PANEL SWITCH 9910616-9			92-1045-9 0059	MTH 09-Mar-2014		O/C	0		
331002	LED ALT STAT PANEL			92-1044-4 0109	MTH 09-Mar-2014		O/C	0		
332010	CONTROL QUADRANT LED PANEL 9910640-4 *CF			92-1113-4 0112	MTH 09-Mar-2014		O/C	0		
332011	CIRCUIT BREAKER LED BACKLIFT PANEL 9910641-2			92-1114-2 0113	MTH 09-Mar-2014		O/C	0		
332012	SWITCH LED PANEL 9910642-1			92-1115-1 0106	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
332013	STANDBY FLAPS LED PANEL 9910643-1	92-1116-1 0124	MTH 09-Mar-2014		O/C	0		
334002 LEFT	NAV LIGHTS & STROBES- L WING TIP TIP	01-0790613-92 00233	MTH 09-Mar-2014		O/C	0		
334002 RIGHT	NAV LIGHTS & STROBES- R WING TIP TIP MNL	01-0790613-91 00314	MTH 05-Mar-2015 HRS 216.4 LDG 216		O/C	0 0 0		
334003	WING INSPECTION LIGHT	WIL200-01 208000123	MTH 09-Mar-2014		O/C	0		
334004 LEFT	LED TAXI LIGHT/WING LED EDGE LIGHT	01-0771424-25 04436	MTH 09-Mar-2014		O/C	0		
334004 RIGHT	LED TAXI LIGHT/WING LED EDGE LIGHT	01-0771424-25 04544	MTH 09-Mar-2014		O/C	0		
334005 L/H	WING LEAD EDGE LANDING LIGHT	01-0790623-20 04132	MTH 09-Mar-2014		O/C	0		
334005 R/H	WING LEAD EDGE LANDING LIGHT	01-0790623-20 03906	MTH 09-Mar-2014		O/C	0		
334401	LED ANTI-COLLISION LIGHT	01-0771055-19 00209	MTH 09-Mar-2014		O/C	0		
340007	ALTIMETER RADAR KRA-405B	066-01153-0101 KRA405B-14903	MTH 09-Mar-2014		O/C	0		
340008 STANDBY	ALTIMETER	5934PAD-3DA.657 502525	MTH 09-Mar-2014 HRS 1.3 LDG 1		O/C	0 0 0		
340020	TAWS-B UNLOCK DATA CARD	010-00330-51 NSN	MTH 09-Mar-2014		O/C	0		
340021	(MFD) MULTI FUNCTION DISPLAY S3325-10	EA5175-29PTL-CES T56254B	MTH 09-Mar-2014		O/C	0		
340022 RIGHT	ATTITUDE GYRO MNL	1U149-015-15 T96687Q	MTH 05-Jan-2016 HRS 687.6 LDG 842		O/C			
340025 NO. 1	ADF RECEIVER S3100-406	066-1072-04 86937	MTH 09-Mar-2014		O/C	0		
340026 LEFT	ADF ANTENNA KA-44B	071-1234-00 KA44B-A92631	MTH 09-Mar-2014		O/C	0		
340028	DME RECEIVER KN 63 DME	3910329-3 36252	MTH 09-Mar-2014		O/C	0		
340031	TORQUE INDICATOR	2606011-6 H13-10493	MTH 09-Mar-2014		O/C	0		
340035 NO. 1	TRANSPONDER RPLL S3100-474	011-00779-10 89128030	MTH 02-Sep-2016 HRS 907.1 LDG 1158		O/C			
340035 NO. 2	TRANSPONDER RPLL S3100-474	011-00779-10 89127200	MTH 02-Sep-2016 HRS 907.1 LDG 1158		O/C			
340047 3	DME/TRANSPONDER ANTENNA	CI110-41-30 440905	MTH 09-Mar-2014		O/C	0		
340047 AFT	OMNI ANTENNA	CI110-41-30 440907	MTH 09-Mar-2014		O/C	0		
340047 LEFT	ANTENNA NAV	D120167 442232	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
340047 NO. 2	TRANSPONDER ANTENNA	CI110-41-30 442064	MTH 09-Mar-2014		O/C	0		
340047 RIGHT	ANTENNA NAV	D120167 442242	MTH 09-Mar-2014		O/C	0		
340048A NO. 1	DME ANTENNA	CI110-41-30 442063	MTH 09-Mar-2014		O/C	0		
340052	CARD ADAPTER GNS430	010-00330-42 NSN	MTH 09-Mar-2014		O/C	0		
340056 AFT	RADAR ALTIMETER ANTENNA	S67-2002 543-70258	MTH 09-Mar-2014		O/C	0		
340056 FWD	RADAR ALTIMETER ANTENNA	S67-2002 543-70315	MTH 09-Mar-2014		O/C	0		
340059	DUPLEXING ANTENNA	CI1125-TNC 443469	MTH 09-Mar-2014		O/C	0		
340060	MARKER BEACON ANT	CI102 440197	MTH 09-Mar-2014		O/C	0		
340083 LEFT	GPS ANTENNA	CI428-410 442890	MTH 09-Mar-2014		O/C	0		
340083 RIGHT	GPS ANTENNA	CI428-200 443295	MTH 09-Mar-2014		O/C	0		
340100 NO. 2	CONFIG MODULE KCM805	071-00112-0200 18170	MTH 09-Mar-2014		O/C	0		
340151	DIRECTIONAL ANTENNA KA815	071-01599-0100 26842	MTH 09-Mar-2014		O/C	0		
340308 LEFT	TUBE PITOT S2625-4	PST300-2SW-C A0229	MTH 09-Mar-2014		O/C	0		
340308 RIGHT	TUBE PITOT S2625-4	PST300-2SW-C A0219	MTH 09-Mar-2014		O/C	0		
340424	VACCUM REGULATOR	C482001-0402 12BJ120	MTH 09-Mar-2014		O/C	0		
340501	COMPASS ASSEMBLY	C660501-0103 NSN	MTH 09-Mar-2014		O/C	0		
340608 NO. 1	OAT PROBE	011-00978-00 47927343	MTH 09-Mar-2014		O/C	0		
340608 NO. 2	OAT PROBE GTP 59	011-00978-00 47923358	MTH 09-Mar-2014		O/C	0		
342004 CENTER	GDU 1040A DISPLAY	011-00916-10 86817255	MTH 09-Mar-2014		O/C	0		
342004 LEFT	GDU 1040A DISPLAY	011-00916-10 86817253	MTH 09-Mar-2014		O/C	0		
342004 RIGHT	GDU 1040A DISPLAY	011-00916-10 86815560	MTH 15-May-2019		O/C	0		
344001	WEATHER RADAR GWX68	011-00883-20 47204674	MTH 09-Mar-2014		O/C	0		
344017	TAS PROCESSOR	066-01152-0101 KTA810-4084	MTH 09-Mar-2014		O/C	0		
344018 NO. 1	AHRS UNIT S3100-517/S3100-483	011-00868-10 42025132	MTH 09-Mar-2014		O/C	0		
344018 NO. 2	AHRS UNIT S3100-517/S3100-483	011-00868-10 42025136	MTH 09-Mar-2014		O/C	0		
344019 LEFT	GMU MAGNETOMETER	011-00870-10 1CM011283	MTH 09-Mar-2014		O/C	0		
344019 RIGHT	GMU MAGNETOMETER	011-00870-10 1CM011376	MTH 09-Mar-2014		O/C	0		
344020 LEFT	AIR DATA COMPUTER	011-00882-10 20616512	MTH 09-Mar-2014		O/C	0		
			HRS 1.3			0		
			LDG 1			0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
344020 RIGHT	AIR DATA COMPUTER			011-00882-10 20606635	MTH 20-Dec-2020 HRS 3690.8 LDG 6232		O/C			
344021	AFCS MODE CONTROLLER			011-01020-10 22006908	MTH 09-Mar-2014		O/C	0		
345005	RADIO PHONE ANTENNA			S65-5366-715 784-1382	MTH 09-Mar-2014		O/C	0		
345604 LEFT	GIA63W INTERGRATED AVIONICS UNIT			011-01105-20 1HQ009472	MTH 09-Mar-2014		O/C	0		
345604 RIGHT	GIA63W INTERGRATED AVIONICS UNIT			011-01105-20 1HQ009511	MTH 09-Mar-2014		O/C	0		
350301 CENTER	OXYGEN 50.67 CU FT AND 116.95 CU FT CYLINDER			PN SN-UNKNOWN			N/A			
370102	VACUUM SYSTEM CENTRAL AIR FILTER DISCARD RPLB			AAD-9-18-1 NSN	MTH 16-Jun-2022 HRS 3958.4 LDG 6663		12 400	0 0	30-Jun-2023 4358.4	1 m 6 d 356.7
370103	VACUUM RELIEF VALVE FILTER DISCARD RPLB			B3-5-1 NSN	MTH 16-Jun-2022 HRS 3958.4 LDG 6663		12 400	0 0	30-Jun-2023 4358.4	1 m 6 d 356.7
370110	AIR EJECTOR			19E32-2A N133052	MTH 09-Mar-2014		O/C	0		
550502	ASSEMBLY RUDDER			2633000-41-2 23980887	MTH 09-Mar-2014		O/C	0		
551010	HORIZONTAL ASSEMBLY STABILIZER			2632000-848 23949258	MTH 09-Mar-2014		O/C	0		
552001 LEFT	ASSEMBLY ELEVATOR RPLL			2634000-869-1 24567972	MTH 28-Jun-2016 HRS 907.1 LDG 1158		O/C			
552001 RIGHT	ASSEMBLY ELEVATOR			2634000-870-1 23953121	MTH 09-Mar-2014		O/C	0		
553003	VERTICAL ASSEMBLY STABILIZER			2631000-828-4 23975991	MTH 09-Mar-2014		O/C	0		
560203 LEFT	WINDSHIELD ASSY, (LH) --			2613088-5 NSN	MTH 09-Mar-2014		O/C	0		
560203 RIGHT	WINDSHIELD ASSY, (RH) --			2613088-2 NSN	MTH 09-Mar-2014		O/C	0		
570000 RIGHT	RIGHT WING STRUT			PN SN-UNKNOWN	MTH 09-Mar-2014		O/C	0		
570000	LEFT WING STRUT			PN SN-UNKNOWN	MTH 09-Mar-2014		O/C	0		
575001 LEFT	ASSEMBLY FLAP			2625000-61-1 23545720	MTH 09-Mar-2014		O/C	0		
575001 RIGHT	ASSEMBLY FLAP			2625000-62-1 23914090	MTH 09-Mar-2014		O/C	0		
576001 LEFT	ASSEMBLY AILERON			2624000-857-1 23993872	MTH 09-Mar-2014		O/C	0		
576001 RIGHT	ASSEMBLY AILERON			2624000-858-1 23993875	MTH 09-Mar-2014		O/C	0		
610006	PROPELLER SLIPRING			D40260 NSN	MTH 09-Mar-2014		O/C	0		
61PR1 NO. 1	PROPELLER RPLB			HC-B3TN-3AF BUA33576	MTH 30-Sep-2018 HRS 2643.5 LDG 4262		PP/C PP/C PP/C PP/C	320		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
612006 E1	PROPELLER GOVERNOR			3074154-01 19071185	MTH 09-Mar-2014 HRS 0		4000	0	(4000)4000	-1.7 Over Due
612020 E1	PROPELLER OVERSPEED GOVERNOR			3076510-01 19017245	MTH 09-Mar-2014 HRS 0		4000	0	(4000)4000	-1.7 Over Due
611101 P1	NO. 1 PROPELLER BLADE UNK			T10890CN-2 L66810	MTH 03-Nov-2021 HRS 3798.6		O/C	68 1473.8		
611102 P1	NO. 2 PROPELLER BLADE UNK			T10890CN-2 L66816	MTH 03-Nov-2021 HRS 3798.6		O/C	68 1473.8		
611103 P1	NO. 3 PROPELLER BLADE UNK			T10890CN-2 L66814	MTH 03-Nov-2021 HRS 3798.6		O/C	68 1473.8		
710002	ENGINE MOUNT ASSEMBLY			2651040-2 CES-13-110	MTH 09-Mar-2014		O/C	0		
710005	ENGINE MOUNT RING			2651022-20-1 PZL/13/010	MTH 09-Mar-2014		O/C	0		
710033	T#5 TRIM STICK	MNL		3031417CL40 NSN	MTH 10-Sep-2015 HRS 476.7 LDG 549		O/C	0 0		
71EN1 NO. 1	ENGINE			3076226-01 PCE-VA0103	MTH 09-Mar-2014		E/C	0		
721120 E1	FIRST STAGE REDUCTION SUN GEAR			3076454-01 PKAAA520750	MTH 09-Mar-2014		O/C	0		
721125-01 E1 NO.1	41 TEETH, FIRST STAGE REDUCTION PLANET GEAR			3076360 PKAAA516549	MTH 09-Mar-2014		O/C	0		
721125-02 E1 NO.2	41 TEETH, FIRST STAGE REDUCTION PLANET GEAR			3076360 PKAAA516551	MTH 09-Mar-2014		O/C	0		
721125-03 E1 NO.3	41 TEETH, FIRST STAGE REDUCTION PLANET GEAR			3076360 PKAAA516568	MTH 09-Mar-2014		O/C	0		
721140 E1	FIRST STAGE CARRIER SPLINED ADAPTER			3077966-01 PKAAA505022	MTH 09-Mar-2014		O/C	0		
721141 E1	FIRST STAGE REDUCTION RING GEAR			3077381-01 PKAAA519787	MTH 09-Mar-2014		O/C	0		
721142 E1	FIRST STAGE REDUCTION CARRIER SET			3078629-01 PKAAA507941	MTH 09-Mar-2014		O/C	0		
721150 E1	SECOND STAGE REDUCTION SUN GEAR			3077973-01 PKAAA527102	MTH 09-Mar-2014		O/C	0		
721155 E1	SECOND STAGE REDUCTION CARRIER			3077979-01 PKAAA498607	MTH 09-Mar-2014		O/C	0		
721160 E1	PROPELLER REDUCTION GEARBOX FRONT HOUSING ASSY			3078469-01 RWA23E354	MTH 09-Mar-2014		O/C	0		
721161 E1	REDUCTION GEARBOX COUPLING			3076484-01 PKAAA511898	MTH 09-Mar-2014		O/C	0		
721162 E1	PROPELLER REDUCTION GEARBOX REAR HOUSING			3078468-01 RWA20E538	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
721165 E1	SECOND STAGE REDUCTION RING GEAR	3076918-01 PKAAA515160	MTH 09-Mar-2014		O/C	0		
721171-01 E1 NO.1	SECOND STAGE REDUCTION PLANET GEAR	3076363 PKAAA520110	MTH 09-Mar-2014		O/C	0		
721171-02 E1 NO.2	SECOND STAGE REDUCTION PLANET GEAR	3076363 PKAAA520117	MTH 09-Mar-2014		O/C	0		
721171-03 E1 NO.3	SECOND STAGE REDUCTION PLANET GEAR	3076363 PKAAA520131	MTH 09-Mar-2014		O/C	0		
721171-04 E1 NO.4	SECOND STAGE REDUCTION PLANET GEAR	3076363 PKAAA520134	MTH 09-Mar-2014		O/C	0		
721171-05 E1 NO.5	SECOND STAGE REDUCTION PLANET GEAR	3076363 PKAAA520138	MTH 09-Mar-2014		O/C	0		
721175 E1	FIRST STAGE REDUCTION CARRIER	3078628-01 PKAAA507941	MTH 09-Mar-2014		O/C	0		
721180 E1	ROLLER FLANGED BEARING	3076655-01 FAA1313109	MTH 09-Mar-2014		O/C	0		
721184 E1	PROPELLER SHAFT AND SLEEVE SET	3076470-01 EAAD000D720	MTH 09-Mar-2014		O/C	0		
721185 E1	PROPELLER SHAFT ASSY	3077383-01 EAAD000D720	MTH 09-Mar-2014		O/C	0		
721190 E1	PROPELLER HOUSING ASSEMBLY FLANGED BALL BEARING	3076621-01 FCN390583	MTH 09-Mar-2014		O/C	0		
722040 E1	COMPRESSOR INLET CASE ASSEMBLY	3077326-01 FWAA000A089	MTH 09-Mar-2014		O/C	0		
723020 E1	COMPRESSOR REAR HUB COUPLING	3076558-01 PKAAA530386	MTH 09-Mar-2014		O/C	0		
723060 E1	CENTRIFUGAL IMPELLER	3027798 EAAD000E097	MTH 09-Mar-2014		ACCC YC	19000	0	12266
723080 E1	COMBUSTION CHAMBER LINER	3076302-01 A003CF14	MTH 09-Mar-2014		O/C	0		
723090 E1	GAS GENERATOR CASE ASSEMBLY	3076837-01 RWA11E368	MTH 09-Mar-2014		O/C	0		
723110 E1	COMPRESSOR ROTOR	3076420-01 EAAD000D632	MTH 09-Mar-2014		ACCC YC	29000	0	22266
723210 E1	COMPRESSOR (3RD STAGE) DISK	3040213 A0034E8B	MTH 09-Mar-2014		ACCC YC	29000	0	22266
723220 E1	COMPRESSOR (2ND STAGE) DISK	3040312 A003CA5N	MTH 09-Mar-2014		ACCC YC	29000	0	22266
723225 E1	FRONT COMPRESSOR STUB SHAFT	3055649-01 RWA20E127	MTH 09-Mar-2014		O/C	0		
723230 E1	COMPRESSOR ROTOR STUB SHAFT	3055000-01 PKAAA525771	MTH 09-Mar-2014		ACCC YC	29000	0	22266
723260 E1	COMPRESSOR FLANGED ROLLER BEARING	3073900-01 AEB176503	MTH 09-Mar-2014		O/C	0		
725010 E1	COMPRESSOR TURBINE DISK	3076856-01 A003D3H6	MTH 09-Mar-2014		ACCC YC	16000	0	9266



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725020-01 E1 NO.1	COMPRESSOR TURBINE BLADE			3076601-01 HWKM9999	MTH 09-Mar-2014		O/C	0		
725020-02 E1 NO.2	COMPRESSOR TURBINE BLADE			3076601-01 HWKN0004	MTH 09-Mar-2014		O/C	0		
725020-03 E1 NO.3	COMPRESSOR TURBINE BLADE			3076601-01 HWKN0011	MTH 09-Mar-2014		O/C	0		
725020-04 E1 NO.4	COMPRESSOR TURBINE BLADE			3076601-01 HWKN0034	MTH 09-Mar-2014		O/C	0		
725020-05 E1 NO.5	COMPRESSOR TURBINE BLADE			3076601-01 HWKN0057	MTH 09-Mar-2014		O/C	0		
725020-06 E1 NO.6	COMPRESSOR TURBINE BLADE			3076601-01 HWKN0065	MTH 09-Mar-2014		O/C	0		
725020-07 E1 NO.7	COMPRESSOR TURBINE BLADE			3076601-01 HWKN0139	MTH 09-Mar-2014		O/C	0		
725020-08 E1 NO.8	COMPRESSOR TURBINE BLADE			3076601-01 HWKN0140	MTH 09-Mar-2014		O/C	0		
725020-09 E1 NO.9	COMPRESSOR TURBINE BLADE			3076601-01 HWLF9599	MTH 09-Mar-2014		O/C	0		
725020-10 E1 NO.10	COMPRESSOR TURBINE BLADE			3076601-01 HWLF9631	MTH 09-Mar-2014		O/C	0		
725020-11 E1 NO.11	COMPRESSOR TURBINE BLADE			3076601-01 HWLM0597	MTH 09-Mar-2014		O/C	0		
725020-12 E1 NO.12	COMPRESSOR TURBINE BLADE			3076601-01 HWLM0600	MTH 09-Mar-2014		O/C	0		
725020-13 E1 NO.13	COMPRESSOR TURBINE BLADE			3076601-01 HWLM0601	MTH 09-Mar-2014		O/C	0		
725020-14 E1 NO.14	COMPRESSOR TURBINE BLADE			3076601-01 HWLM0605	MTH 09-Mar-2014		O/C	0		
725020-15 E1 NO.15	COMPRESSOR TURBINE BLADE			3076601-01 HWLM0607	MTH 09-Mar-2014		O/C	0		
725020-16 E1 NO.16	COMPRESSOR TURBINE BLADE			3076601-01 HWLM4238	MTH 09-Mar-2014		O/C	0		
725020-17 E1 NO.17	COMPRESSOR TURBINE BLADE			3076601-01 HWLM4241	MTH 09-Mar-2014		O/C	0		
725020-18 E1 NO.18	COMPRESSOR TURBINE BLADE			3076601-01 HWLP6951	MTH 09-Mar-2014		O/C	0		
725020-19 E1 NO.19	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7588	MTH 09-Mar-2014		O/C	0		
725020-20 E1 NO.20	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7592	MTH 09-Mar-2014		O/C	0		
725020-21 E1 NO.21	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7599	MTH 09-Mar-2014		O/C	0		
725020-22 E1 NO.22	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7603	MTH 09-Mar-2014		O/C	0		
725020-23 E1 NO.23	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7604	MTH 09-Mar-2014		O/C	0		
725020-24 E1 NO.24	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7614	MTH 09-Mar-2014		O/C	0		
725020-25 E1 NO.25	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7623	MTH 09-Mar-2014		O/C	0		
725020-26 E1 NO.26	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7632	MTH 09-Mar-2014		O/C	0		
725020-27 E1 NO.27	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7637	MTH 09-Mar-2014		O/C	0		
725020-28 E1 NO.28	COMPRESSOR TURBINE BLADE			3076601-01 HWLP7640	MTH 09-Mar-2014		O/C	0		
725020-29 E1 NO.29	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9600	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725020-30 E1 NO.30	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9602	MTH 09-Mar-2014		O/C	0		
725020-31 E1 NO.31	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9605	MTH 09-Mar-2014		O/C	0		
725020-32 E1 NO.32	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9609	MTH 09-Mar-2014		O/C	0		
725020-33 E1 NO.33	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9611	MTH 09-Mar-2014		O/C	0		
725020-34 E1 NO.34	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9614	MTH 09-Mar-2014		O/C	0		
725020-35 E1 NO.35	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9615	MTH 09-Mar-2014		O/C	0		
725020-36 E1 NO.36	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9637	MTH 09-Mar-2014		O/C	0		
725020-37 E1 NO.37	COMPRESSOR TURBINE BLADE			3076601-01 HWLP9652	MTH 09-Mar-2014		O/C	0		
725020-38 E1 NO.38	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0612	MTH 09-Mar-2014		O/C	0		
725020-39 E1 NO.39	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0614	MTH 09-Mar-2014		O/C	0		
725020-40 E1 NO.40	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0617	MTH 09-Mar-2014		O/C	0		
725020-41 E1 NO.41	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0629	MTH 09-Mar-2014		O/C	0		
725020-42 E1 NO.42	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0633	MTH 09-Mar-2014		O/C	0		
725020-43 E1 NO.43	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0665	MTH 09-Mar-2014		O/C	0		
725020-44 E1 NO.44	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0672	MTH 09-Mar-2014		O/C	0		
725020-45 E1 NO.45	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0673	MTH 09-Mar-2014		O/C	0		
725020-46 E1 NO.46	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0677	MTH 09-Mar-2014		O/C	0		
725020-47 E1 NO.47	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0683	MTH 09-Mar-2014		O/C	0		
725020-48 E1 NO.48	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0697	MTH 09-Mar-2014		O/C	0		
725020-49 E1 NO.49	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0717	MTH 09-Mar-2014		O/C	0		
725020-50 E1 NO.50	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0726	MTH 09-Mar-2014		O/C	0		
725020-51 E1 NO.51	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0729	MTH 09-Mar-2014		O/C	0		
725020-52 E1 NO.52	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0744	MTH 09-Mar-2014		O/C	0		
725020-53 E1 NO.53	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0745	MTH 09-Mar-2014		O/C	0		
725020-54 E1 NO.54	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0746	MTH 09-Mar-2014		O/C	0		
725020-55 E1 NO.55	COMPRESSOR TURBINE BLADE			3076601-01 HWLR0764	MTH 09-Mar-2014		O/C	0		
725020-56 E1 NO.56	COMPRESSOR TURBINE BLADE			3076601-01 HWLR2356	MTH 09-Mar-2014		O/C	0		
725020-57 E1 NO.57	COMPRESSOR TURBINE BLADE			3076601-01 HWLR2357	MTH 09-Mar-2014		O/C	0		
725020-58 E1 NO.58	COMPRESSOR TURBINE BLADE			3076601-01 HWLR2362	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725030 E1	POWER TURBINE DISK			3076855-01 YUAA016A530	MTH 09-Mar-2014 ACCC YC		16000	0		9266
725031 E1	POWER TURBINE VANE RING			3049382CL03 HLA372AB	MTH 09-Mar-2014		O/C	0		
725035-01 E1 NO.1	POWER TURBINE BLADE			3076290-01 YWA4618	MTH 09-Mar-2014		O/C	0		
725035-02 E1 NO.2	POWER TURBINE BLADE			3076290-01 YWA5065	MTH 09-Mar-2014		O/C	0		
725035-03 E1 NO.3	POWER TURBINE BLADE			3076290-01 YWA5067	MTH 09-Mar-2014		O/C	0		
725035-04 E1 NO.4	POWER TURBINE BLADE			3076290-01 YWA5072	MTH 09-Mar-2014		O/C	0		
725035-05 E1 NO.5	POWER TURBINE BLADE			3076290-01 YWA5085	MTH 09-Mar-2014		O/C	0		
725035-06 E1 NO.6	POWER TURBINE BLADE			3076290-01 YWA5100	MTH 09-Mar-2014		O/C	0		
725035-07 E1 NO.7	POWER TURBINE BLADE			3076290-01 YWA5101	MTH 09-Mar-2014		O/C	0		
725035-08 E1 NO.8	POWER TURBINE BLADE			3076290-01 YWA5103	MTH 09-Mar-2014		O/C	0		
725035-09 E1 NO.9	POWER TURBINE BLADE			3076290-01 YWA5105	MTH 09-Mar-2014		O/C	0		
725035-10 E1 NO.10	POWER TURBINE BLADE			3076290-01 YWA5112	MTH 09-Mar-2014		O/C	0		
725035-11 E1 NO.11	POWER TURBINE BLADE			3076290-01 YWA5115	MTH 09-Mar-2014		O/C	0		
725035-12 E1 NO.12	POWER TURBINE BLADE			3076290-01 YWA5124	MTH 09-Mar-2014		O/C	0		
725035-13 E1 NO.13	POWER TURBINE BLADE			3076290-01 YWA5131	MTH 09-Mar-2014		O/C	0		
725035-14 E1 NO.14	POWER TURBINE BLADE			3076290-01 YWA5135	MTH 09-Mar-2014		O/C	0		
725035-15 E1 NO.15	POWER TURBINE BLADE			3076290-01 YWA5150	MTH 09-Mar-2014		O/C	0		
725035-16 E1 NO.16	POWER TURBINE BLADE			3076290-01 YWA5162	MTH 09-Mar-2014		O/C	0		
725035-17 E1 NO.17	POWER TURBINE BLADE			3076290-01 YWA5164	MTH 09-Mar-2014		O/C	0		
725035-18 E1 NO.18	POWER TURBINE BLADE			3076290-01 YWA5235	MTH 09-Mar-2014		O/C	0		
725035-19 E1 NO.19	POWER TURBINE BLADE			3076290-01 YWA5239	MTH 09-Mar-2014		O/C	0		
725035-20 E1 NO.20	POWER TURBINE BLADE			3076290-01 YWA5246	MTH 09-Mar-2014		O/C	0		
725035-21 E1 NO.21	POWER TURBINE BLADE			3076290-01 YWA5261	MTH 09-Mar-2014		O/C	0		
725035-22 E1 NO.22	POWER TURBINE BLADE			3076290-01 YWA5263	MTH 09-Mar-2014		O/C	0		
725035-23 E1 NO.23	POWER TURBINE BLADE			3076290-01 YWA5270	MTH 09-Mar-2014		O/C	0		
725035-24 E1 NO.24	POWER TURBINE BLADE			3076290-01 YWA5280	MTH 09-Mar-2014		O/C	0		
725035-25 E1 NO.25	POWER TURBINE BLADE			3076290-01 YWA5286	MTH 09-Mar-2014		O/C	0		
725035-26 E1 NO.26	POWER TURBINE BLADE			3076290-01 YWA5288	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725035-27 E1 NO.27	POWER TURBINE BLADE			3076290-01 YWA5289	MTH 09-Mar-2014		O/C	0		
725035-28 E1 NO.28	POWER TURBINE BLADE			3076290-01 YWA5295	MTH 09-Mar-2014		O/C	0		
725035-29 E1 NO.29	POWER TURBINE BLADE			3076290-01 YWA5296	MTH 09-Mar-2014		O/C	0		
725035-30 E1 NO.30	POWER TURBINE BLADE			3076290-01 YWA5319	MTH 09-Mar-2014		O/C	0		
725035-31 E1 NO.31	POWER TURBINE BLADE			3076290-01 YWA5321	MTH 09-Mar-2014		O/C	0		
725035-32 E1 NO.32	POWER TURBINE BLADE			3076290-01 YWA5355	MTH 09-Mar-2014		O/C	0		
725035-33 E1 NO.33	POWER TURBINE BLADE			3076290-01 YWA5371	MTH 09-Mar-2014		O/C	0		
725035-34 E1 NO.34	POWER TURBINE BLADE			3076290-01 YWA5380	MTH 09-Mar-2014		O/C	0		
725035-35 E1 NO.35	POWER TURBINE BLADE			3076290-01 YWA5391	MTH 09-Mar-2014		O/C	0		
725035-36 E1 NO.36	POWER TURBINE BLADE			3076290-01 YWA5398	MTH 09-Mar-2014		O/C	0		
725035-37 E1 NO.37	POWER TURBINE BLADE			3076290-01 YWA5401	MTH 09-Mar-2014		O/C	0		
725035-38 E1 NO.38	POWER TURBINE BLADE			3076290-01 YWA5528	MTH 09-Mar-2014		O/C	0		
725035-39 E1 NO.39	POWER TURBINE BLADE			3076290-01 YWA5536	MTH 09-Mar-2014		O/C	0		
725035-40 E1 NO.40	POWER TURBINE BLADE			3076290-01 YWA5547	MTH 09-Mar-2014		O/C	0		
725035-41 E1 NO.41	POWER TURBINE BLADE			3076290-01 YWA5556	MTH 09-Mar-2014		O/C	0		
725055 E1	POWER TURBINE SHAFT			3011095 RWA20E720	MTH 09-Mar-2014		O/C	0		
725060 E1	POWER TURBINE SHAFT COUPLING			3076545-01 PKAAA524403	MTH 09-Mar-2014		O/C	0		
725075 E1	T5 THERMOCOUPLE ASSEMBLY BUS BAR			3027629 HR28106	MTH 09-Mar-2014		O/C	0		
725095 E1	POWER TURBINE SHAFT FLANGED ROLLER BEARING			3073900-01 AEB0176543	MTH 09-Mar-2014		O/C	0		
725100 E1	POWER TURBINE SHAFT BALL BEARING			3073901-01 AEB0174587	MTH 09-Mar-2014		O/C	0		
725110 E1	TURBINE VANE RING			3055781CLO2 HLAA614	MTH 09-Mar-2014		O/C	0		
725115 E1	SINGLE PORT TURBINE EXHAUST DUCT			3076239-01 RWA24E949	MTH 09-Mar-2014		O/C	0		
726001 E1	STARTER GENERATOR DRIVE GEARSHAFT			3076506-01 PKAAA514091	MTH 09-Mar-2014		O/C	0		
726010 E1	ACCESSORY GEARBOX DRIVE GEARSHAFT			3076608-01 PKAAA519158	MTH 09-Mar-2014		O/C	0		
726015 E1	ACCESSORY GEARBOX COUPLING SHAFT			3076505-01 PKAAA522939	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
726020-01 E1	ACCESSORY GEARBOX DRIVE GEARSHAFT FORWARD FLANGED ROLLER BEARING	3112368-01 MTH FAA1314326	09-Mar-2014		O/C	0		
726020-02 E1	ACCESSORY GEARBOX DRIVE GEARSHAFT AFT FLANGED ROLLER BEARING	3112368-01 MTH FAA1314327	09-Mar-2014		O/C	0		
726020-03 E1	FUEL CONTROL DRIVE FORGING SPUR GEARSHAFT FORWARD FLANGED ROLLER BEARING	3112368-01 MTH FAA1314328	09-Mar-2014		O/C	0		
726020-04 E1	FUEL CONTROL DRIVE FORGING SPUR GEARSHAFT AFT FLANGED ROLLER BEARING	3112368-01 MTH FAA1314349	09-Mar-2014		O/C	0		
726020-05 E1	ACCESSORY DRIVE SPUR GEARSHAFT FORWARD FLANGED ROLLER BEARING	3112368-01 MTH FAA1314354	09-Mar-2014		O/C	0		
726020-06 E1	ACCESSORY DRIVE SPUR GEARSHAFT AFT FLANGED ROLLER BEARING	3112368-01 MTH FAA1314355	09-Mar-2014		O/C	0		
726020-07 E1	ACCESSORY DRIVE SPUR GEARSHAFT (55 TEETH) FORWARD FLANGED ROLLER BEARING	3112368-01 MTH FAA1314356	09-Mar-2014		O/C	0		
726020-08 E1	ACCESSORY DRIVE SPUR GEARSHAFT (55 TEETH) AFT FLANGED ROLLER BEARING	3112368-01 MTH FAA1314357	09-Mar-2014		O/C	0		
726020-09 E1	SCAVENGE PUMP SPUR GEARSHAFT FORWARD FLANGED ROLLER BEARING	3112368-01 MTH FAA1314358	09-Mar-2014		O/C	0		
726020-10 E1	SCAVENGE PUMP SPUR GEARSHAFT AFT FLANGED ROLLER BEARING	3112368-01 MTH FAA1314359	09-Mar-2014		O/C	0		
726020-11 E1	STARTER GENERATOR DRIVE GEARSHAFT FORWARD FLANGED ROLLER BEARING	3112368-01 MTH FAA1314360	09-Mar-2014		O/C	0		
726030 E1	STARTER GENERATOR DRIVE GEARSHAFT AFT FLANGED ROLLER BEARING	3107449-01 MTH FCN386629	09-Mar-2014		O/C	0		
731010 E1	FUEL PUMP	3040760 MTH 012610	09-Mar-2014	HRS 0		0	(4500)4500	498.3
731035 E1	FUEL PUMP DISCHARGE FILTER ELEMENT RPLB	3059778-01 MTH NSN	21-Mar-2021	HRS 3753.6 LDG 6381	600	0	(4353.6)4353.6	351.9
731036 E1	FUEL PUMP INLET FILTER ELEMENT RPLB	26281 MTH NSN	03-Apr-2017	HRS 1190.6 LDG 1710	O/C			
731060 E1	FUEL/OIL HEAT EXCHANGER	3076422-05 MTH WAA47369	09-Mar-2014	HRS 0	4000	0	(4000)4000	-1.7 Over Due
731070 E1	FLOW DIVIDER AND FUEL DUMP VALVE MNL	3023670 MTH MO349	21-May-2015	HRS 403.3 LDG 455	4000	62	(4341.3)4341.3	339.6
731075 E1	FUEL WASTE EJECTOR	3076527-01 MTH D0102	09-Mar-2014		O/C	0		
731090 E1	FUEL CONTROL UNIT	3076428-03 MTH 18997982	09-Mar-2014	HRS 0	4000	0	(4000)4000	-1.7 Over Due
731096 E1	OIL HEAT EXCHANGER FUEL FILTER ELEMENT RPLB	3059779-01 MTH NSN	21-Mar-2021	HRS 3753.6 LDG 6381	600	0	(4353.6)4353.6	351.9



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731110 E1	TORQUE LIMITER			3055738-01 C79679	MTH 09-Mar-2014		O/C	0		
731130 E1	MOTIVE FLOW SHUT-OFF VALVE			3078381-01 BCAAAA00184	MTH 09-Mar-2014		O/C	0		
740010 E1 NO. 1	IGNITION EXCITER			PN-UNKNOWN SN-UNKNOWN	MTH 26-Aug-2019 HRS 3552 LDG 6027		4000	0	(7552)7552	3550.3
741020 E1 4 O'CLOCK	SPARK IGNITER			CH34055 NSN	MTH 09-Mar-2014		O/C	0		
741030 E1 9 O'CLOCK	SPARK IGNITER			CH34055 NSN	MTH 09-Mar-2014		O/C	0		
750010 E1	COMPRESSOR BLEED VALVE			3049038-03 8059	MTH 17-May-2019 HRS 3439.1 LDG 5837		4000	1283	(6156.1)6156.1	2154.4
760202	THROTTLE QUADRANT			C100460 75	MTH 09-Mar-2014		O/C	0		
770006	P3 FILTER			3031781 NSN	MTH 09-Mar-2014		O/C	0		
770009	GAS GENERATOR SPEED SENSOR/N1 TACHOMETER 9912034-1			22A703 107447	MTH 09-Mar-2014		O/C	0		
770011 NO. 1	TORQUE VENT & PRESSURE HOSE S2808-4-0113			AE3663161E0113 NSN	MTH 09-Mar-2014		120	0	31-Mar-2024	10 m 7 d
770011 NO. 2	TORQUE VENT & PRESSURE HOSE S2808-4-0113			AE3663161E0113 NSN	MTH 09-Mar-2014		120	0	31-Mar-2024	10 m 7 d
770015	PROPELLER SPEED SENSOR/P1 TACHOMETER 9912034-1			22A703 107259	MTH 09-Mar-2014		O/C	0		
770100	OIL PRESSURE HOSE AE3663163E0230			S2808-4B0230 NSN	MTH 09-Mar-2014		120	0	31-Mar-2024	10 m 7 d
773012	TRQ PRESSURE TRANSDUCER --			3049260-3 14060363	MTH 27-Sep-2017 HRS 1648.3 LDG 2450		O/C	0 0 0		
774002	ENGINE INTERFACE	RPLB		011-00831-00 46706800	MTH 01-Mar-2022 HRS 3876.8 LDG 6568		O/C			
77-12-00-2-3 E1	TORQUE PRESSURE TRANSDUCER			PN SN-UNKNOWN	MTH 09-Mar-2014		A/R	0		
770030 E1	T5 THERMOCOUPLE WIRING HARNESS			3117924-01 NRA31760	MTH 09-Mar-2014		O/C	0		
780201	SECONDARY EXHAUST DUCT ASSEMBLY MNL			2654008-205 NSN	MTH 23-Dec-2015 HRS 625.2 LDG 761		O/C			
790001	OIL COOLER			380345000 T0121	MTH 09-Mar-2014		O/C	0		
790003	OIL FILTER			3059257-01 NSN	MTH 09-Mar-2014		O/C	0		
791000	OIL COOLER RETURN HOSE			AE3663163K0600 NSN	MTH 09-Mar-2014		120	0	31-Mar-2024	10 m 7 d
791020	ENGINE OIL BREATHER VENT HOSE RPLB			R221520 NSN	MTH 12-Jul-2021 HRS 3790 LDG 6464		120 3600	0 0	31-Jul-2031 7390	98 m 7 d 3388.3
792000	OIL COOLER SUPPLY HOSE S2808-12B0600			AE3663163K0600 NSN	MTH 09-Mar-2014		120	0	31-Mar-2024	10 m 7 d
792003	OIL PRESSURE SWITCH ASSEMBLY			2653049-3 NSN	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
792020	OIL COOLER CHECK VALVE (CHECK VALVE ASSEMBLY REPAIR) RESTORATION (AIRPLANES 208B-2197, AND 208B5000 AND ON)	RPLB		PN SN-UNKNOWN	MTH 04-Sep-2021 HRS 3795.5 LDG 6470	-601.37	1800	0	4994.13	992.43
793011	TEMPERATURE SENSOR			3037603 NR04125	MTH 09-Mar-2014		O/C	0		
793010 E1	TEMPERATURE SENSOR			3037603 NR04125	MTH 09-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CAL-99-01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SB CAB11-5 R01	TIME LIMITS/MAINTENANCE CHECKS - NEW 208/208B TASK-BASED INSPECTION PROGRAM			OPTIONAL MTH			-			
	MOC :									
SB CAB11-5 R02	TIME LIMITS/MAINTENANCE CHECKS - NEW 208/208B TASK-BASED INSPECTION PROGRAM			OPTIONAL			-			
	MOC :									
SL CAL-05-01 R01	TIME LIMITS/MAINTENANCE CHECKS - INSPECTION DOCUMENT 0A FOR 14 CFR PART 91.409 (A) AND (B)			INFORMATIONAL			-			
	MOC :									
SL CAL-05-01	TASK-BASED INSPECTION PROGRAM - TASK 0A FOR 14CFR PART 91.409 (A) AND (B)			INFORMATIONAL			-			
	MOC :									
SL CAL-05-02	TIME LIMITS/MAINTENANCE CHECKS - NEW C100490-1 OIL COOLER CHECK VALVE (CHECK VALVE ASSEMBLY REPAIR) RESTORATION INTERVAL IMPLEMENTATION GRACE PERIOD			INFORMATIONAL			-			
	MOC :									
COM SE-TP-003	SINGLE ENGINE TURBOPROP COMMUNIQUE - TASK BASED INSPECTION PROGRAM CONVERSION, CARAVAN PTT SWITCH CAP REPLACEMENT, ROSEN SUNVISOR						-			
	MOC :									
COM SE-TP-007	INSPECTION PROGRAMS / BASE SOFTWARE CARDS AND SOFTWARE UNLOCK CARDS			MTH			-			
	MOC :									
SB CAB09-7 R01	GARMIN G1000 SYNTHETIC VISION INSTALLATION FOR AIRPLANES NOT EQUIPPED WITH NXI			OPTIONAL			-			
	MOC :									
SL CAL-20-01	LISTING OF NONDESTRUCTIVE TESTING FACILITIES			INFORMATIONAL			-			
	MOC :									
SL SEL-20-01 R01	LISTING OF NONDESTRUCTIVE TESTING FACILITIES			INFORMATIONAL			-			
	MOC :									
SL SEL-20-01	LISTING OF NONDESTRUCTIVE TESTING FACILITIES			INFORMATIONAL			-			
	MOC :									
SB CAB-21-03	AIR CONDITIONING - R134A AIR CONDITIONER SYSTEM INSTALLATION FOR AIRPLANES EQUIPPED WITH G1000 AND 675 SHP ENGINE			OPTIONAL			-			
	MOC :									
SB CAB-21-04	AIR CONDITIONING - R134A AIR CONDITIONER SYSTEM INSTALLATION FOR AIRPLANES EQUIPPED WITH G1000 AND 867 SHP ENGINE			OPTIONAL			-			
	MOC :									
SB CAB-21-05	AIR CONDITIONING - REPLACEMENT OF P3 HEATER (FLOW) CONTROL VALVE			OPTIONAL			-			
	MOC :									
SB CAB-21-06	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR DRIVE BELT INSTALLATION			OPTIONAL			-			
	MOC :									
SB CAB-24-02	ELECTRICAL POWER - GENERATOR CONTROL UNIT (GCU) WIRING IMPROVEMENTS			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB CAB-24-04	ELECTRICAL POWER - PLACARD INSTALLATION FOR STANDBY ALTERNATOR									
			RECOMMENDED	MTH			-			
	MOC :									
SL CAL-24-03	ELECTRICAL POWER - SUPPLEMENTS TO ADDRESS ELECTRICAL REQUIREMENTS FOR OPERATION OF SINGLE-ENGINE PASSENGER-CARRYING AIRCRAFT FOR COMPENSATION OR HIRE									
				INFORMATIONAL			-			
	MOC :									
SL CAL-24-04	ELECTRICAL POWER - INSPECT ELECTRICAL GROUND STUDS IN THE ENGINE COMPARTMENT FOR CORRECT PAINT AND SEALANT APPLICATION									
			RECOMMENDED				-			
	MOC :									
SL CAL-24-05	ELECTRICAL POWER - WIRE BUNDLE ID TAG INSPECTION				MTH 13-Jun-2021					Complete
	RPLB		RECOMMENDED		HRS 3790					
					LDG 6464					
	MOC : COMPLIED WITH									
COM SE-TP-004	SINGLE-ENGINE TURBOPROP COMMUNIQUE - (AFFECTS MULTIPLE SYSTEMS/SUBSYSTEMS)				MTH 20-Jan-2019					Complete
					HRS 3014.6					
					LDG 5053					
	MOC : COMPLIED WITH									
SB CAB-25-03	EQUIPMENT/FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER ELT 1000 INSTALLATION									
			OPTIONAL				-			
	MOC :									
SL CAL-25-02	EQUIPMENT/FURNISHINGS - CREW SEAT FRAME INSPECTION AND WELD REPAIR									
			RECOMMENDED				-			
	MOC :									
SB CAB-26-01	FIRE PROTECTION - REPLACEMENT OF THE HALON TYPE 1211 PORTABLE FIRE EXTINGUISHERS									
			OPTIONAL				-			
	MOC :									
SB CAB-27-01	RUDDER TRIM INSPECTION				MTH 01-May-2015					Complete
	MNL		MANDATORY		HRS 364.9					
					LDG 401					
	MOC : COMPLIED WITH - NOT APPLICABLE									
SB CAB-27-03	FLIGHT CONTROLS - INSPECTION OF AILERON CABLE INTERFERENCE				MTH 02-Sep-2016					Complete
	RPLL		MANDATORY		HRS 985.4					
					LDG 1283					
	MOC : COMPLIED WITH - C/OUT FLIGHT CONTROLS - INSPECTION OF AILERON CABLE INTERFERENCE IAW SB CAB 27-03 , SATISFACTORY									
SB CAB-27-05	FLIGHT CONTROLS - FLAP FOLLOW-UP BARREL WASHER INSTALLATION									
			RECOMMENDED	MTH			-			
	MOC :									
SB CAB-27-06	FLIGHT CONTROLS - ELEVATOR TORQUE TUBE INSPECTION FOR LOOSE RIVETS									
							-			
	MOC :									
SL CAL-27-05	FLIGHT CONTROLS - ELEVATOR PRE-FLIGHT CHECK FOR FREE PLAY									
			INFORMATIONAL				-			
	MOC :									
SL CAL-27-06	FLIGHT CONTROLS - INSTALL MISSING CATERPILLAR GROMMETS IN THE BULKHEAD CUTOUTS									
			RECOMMENDED				-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CAL-27-07 R01	FLIGHT CONTROLS - REPLACE AILERON TRIM TAB PUSHROD ASSEMBLIES									
			MANDATORY							
	MOC :									
SL CAL-27-07	FLIGHT CONTROLS - REPLACE AILERON TRIM TAB PUSHROD ASSEMBLIES									
			MANDATORY	MTH						
	MOC :									
SL CAL-27-09	FLIGHT CONTROLS - REMOVE AND REINSTALL INVERTED LEFT AILERON TRIM TAB PUSHRODS									
			RECOMMENDED							
	MOC :									
SL CAL-27-10	FLIGHT CONTROLS - INSPECTION OF THE ELEVATOR UP TRAVEL RIGGING									
			MANDATORY	MTH						
	MOC :									
STC SA3649NM	FABRICATION AND INSTALLATION OF AERO TWIN, INC. RUDDER GUST LOCK KIT NO. AT-RL-1001.									
				MTH 09-Mar-2014						Complete
				HRS 1.3						
				LDG 1						
	MOC : COMPLIED WITH - STC SA3649NM, AERO TWIN RUDDER GUST LOCK KIT, P/N AT-RL-1001 WAS INCORPORATED DURING PRODUCTION.									
SL CAL-28-01 R01	FUEL - INSPECTION/ REPLACEMENT OF LEFT LOW FUEL LEVEL SWITCH COVER ASSEMBLY									
		RPLL	MANDATORY	MTH 11-Aug-2017						Complete
				HRS 713.9						
				LDG 884						
	MOC : COMPLIED WITH - C/OUT INSP. IAW SL CAL-28-01 R1 FUEL INSPECTION / REPLACEMENT OF LEFT LOW FUEL LEVEL SWITCH COVER ASSEMBLY. SATISFACTORY									
SL CAL-28-01	FUEL - INSPECTION / REPLACEMENT OF LEFT LOW FUEL LEVEL SWITCH COVER ASSEMBLY (SUPERSEDED BY CAL-28-01 R01)									
		MNL	MANDATORY	MTH 12-Jan-2016						Complete
				HRS 713.9						
				LDG 884						
	MOC : COMPLIED WITH - NEXT DUE WILL BE NOVEMBER 2016									
SL CAL-28-02	FUEL - FUEL LINE COVER ASSEMBLIES SEALANT INSPECTION									
			MANDATORY							
	MOC :									
SB CAB-30-03	TKS FILL CAP PLACARD REPLACEMENT									N/A
		MNL	RECOMMENDED	MTH 02-Sep-2015						
				HRS 476.4						
				LDG 549						
	MOC : NOT APPLICABLE - NOT APPLICABLE									
SB CAB-30-05 R01	SINGLE FILTER ELEMENT FOR TKS AIRCRAFT									
			OPTIONAL							
	MOC :									
SB CAB-30-07	TKS ICE WARNING PLACARD REPLACEMENT									N/A
		MNL	MANDATORY	MTH 02-Sep-2015						
				HRS 476.4						
				LDG 549						
	MOC : NOT APPLICABLE - NOT APPLICABLE									
SL CAL-30-01 R03	ICE AND RAIN PROTECTION - TRANSMITTAL OF CAV AEROSPACE SERVICE LETTER SL 13120-10-30-001 CESSNA 208B CARAVAN TKS ICE PROTECTION SYSTEM FILTER ELEMENT REPLACEMENT (SUPERSEDED BY CAL-30-01 R04)									
			INFORMATIONAL							
	MOC :									
SL CAL-30-01 R04	ICE AND RAIN PROTECTION - TRANSMITTAL OF CAV AEROSPACE SERVICE LETTER SL 13120-10-30-001 CESSNA 208B CARAVAN TKS ICE PROTECTION SYSTEM FILTER ELEMENT REPLACEMENT									
			INFORMATIONAL							
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CAL-30-02	ICE AND RAIN PROTECTION - TRAVEL TUBE BRACKET WELDMENT REPLACEMENT								
			INFORMATIONAL						
	MOC :								
ASB HC--30-358 R02 PARA E(1) P1	INSPECTION ANTI-ICE - TRAVEL TUBE BRACKET WELDMENT REPLACEMENT OF BRACKET WELDMENT			MTH 03-Nov-2021					N/A
	MOC : NOT APPLICABLE								
ASB HC--30-358 R02 PARA E(2) P1	REPLACEMENT ANTI-ICE - TRAVEL TUBE BRACKET WELDMENT REPLACEMENT OF BRACKET (TERMINATING ACTION)			MTH 03-Nov-2021					N/A
	MOC : NOT APPLICABLE								
ASB HC--30-358 R02 P1	ANTI-ICE - TRAVEL TUBE BRACKET WELDMENT REPLACEMENT			MTH 03-Nov-2021					N/A
	MOC : NOT APPLICABLE								
SL HC--30-259 R14 P1	PROPELLER - HARTZELL PROPELLER INC. MOUNTED ICE PROTECTION COMPONENTS			MTH 03-Nov-2021					N/A
	MOC : NOT APPLICABLE								
SL HC--30-259 R15 P1	HARTZELL PROPELLER INC. MOUNTED ICE PROTECTION COMPONENTS								
	MOC :								
SL HC--30-260 R22 P1	DE-ICE BOOTS, ANTI-ICING BOOTS, AND AIRFRAME MOUNTED ICE PROTECTION SYSTEM COMPONENTS			MTH 03-Nov-2021					N/A
	MOC : NOT APPLICABLE								
SL HC--30-260 R23 P1	DE-ICE BOOTS, ANTI-ICING BOOTS, AND AIRFRAME MOUNTED ICE PROTECTION SYSTEM COMPONENTS								
	MOC :								
SB CAB-31-01 R01	INDICATING/RECORDING SYSTEMS - CVDR INSTALLATION (SUPERSEDED BY CAB-31-01 R02)								
			OPTIONAL						
	MOC :								
SB CAB-31-01 R02	INDICATING/RECORDING SYSTEMS - CVDR INSTALLATION								
			OPTIONAL						
	MOC :								
SB CAB-31-01	INDICATING / RECORDING SYSTEMS - CVDR INSTALLATION (SUPERSEDED BY CAB-31-01 R01)								
			OPTIONAL						
	MOC :								
SB CAB-32-04	LANDING GEAR - MAIN LANDING GEAR TRUNNION AND FAIRING INSPECTION			MTH 16-Jan-2017					N/A
		RPLB	MANDATORY	HRS 1125.6					
				LDG 1607					
	MOC : NOT APPLICABLE								
SB CAB-32-05	LANDING GEAR - NOSE LANDING GEAR FAIRING INSPECTION			MTH 14-Apr-2017					N/A
		RPLB	MANDATORY	HRS 1219.6					
				LDG 1750					
	MOC : NOT APPLICABLE								
SL CAL-32-02	TRANSMITTAL OF PARKER SERVICE BULLETIN SB7105								
			INFORMATIONAL						
	MOC :								
SL CAL-32-04	LANDING GEAR - BRAKE CYLINDER INSPECTION			MTH 03-Feb-2022					Complete
			MANDATORY	HRS 3854.6					
				LDG 6539					
	MOC : COMPLIED WITH - SATISFACTORY.								



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl	Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
COM SE-TP-002	SINGLE-ENGINE TURBOPROP COMMUNIQUÉ - MAIN LANDING GEAR (MLG) BUILDUP-SPARES ASSEMBLY									
	MOC :									
SB CAB-33-01	LIGHTS - LED BEACON INSTALLATION		OPTIONAL							-
	MOC :									
SB CAB-33-02	LIGHTS - LED NAVIGATION AND ANTI-COLLISION LIGHT ASSEMBLIES INSTALLATION		OPTIONAL							-
	MOC :									
SB CAB-33-04	LIGHTS - LED LANDING AND TAXI RECOGNITION LIGHT INSTALLATION		OPTIONAL							-
	MOC :									
SB CAB-33-05	LIGHTS - LED COURTESY LIGHT INSTALLATION		OPTIONAL							-
	MOC :									
SB CAB-33-06	LIGHTS - LED WING INSPECTION LIGHT INSTALLATION		OPTIONAL							-
	MOC :									
SB CAB-33-07	LIGHTS - LED NAV/ANTI-COLLISION LIGHT WIRING MODIFICATION		RECOMMENDED	MTH						-
	MOC :									
SL CAL-33-01	LIGHTS - FERRULE INSTALLATION		RECOMMENDED							-
	MOC :									
SB CAB-34-03 R01	NAVIGATION - GARMIN G1000 SYSTEM SOFTWARE UPGRADE TO VERSION 0767.25		RECOMMENDED							-
	MOC :									
SB CAB-34-03	NAVIGATION - GARMIN G 1000 SYSTEM SOFTWARE UPGRADE TO VERSION 0767.23	RPLB	RECOMMENDED		MTH 10-Apr-2018					-
					HRS 2193.9					
					LDG 3361					
	MOC : DECLINED									
SB CAB-34-04 R01	NAVIGATION - GARMIN G1000 ADS-B OUT ACTIVATION		OPTIONAL							-
	MOC :									
SB CAB-34-04	NAVIGATION - GARMIN G1000 ADS-B OUT ACTIVATION		OPTIONAL							-
	MOC :									
SB CAB-34-06	NAVIGATION - INSTALL KRA-405B RADAR ALTIMETER		OPTIONAL							-
	MOC :									
SB CAB-34-11	NAVIGATION - STALL WARNING HORN REPLACEMENT									-
	MOC :									
SB CAB09-11 R01	GARMIN G1000 AVIONICS CHARTVIEW OPTION		OPTIONAL							-
	MOC :									
SL CAL-34-02	NAVIGATION - REPLACEMENT OF NONCONFORMING DIAPHRAGM ASSEMBLIES IN AFFECTED ALTIMETERS	RPLB	MANDATORY		MTH 13-Jun-2017					-
					HRS 1403					N/A
					LDG 2043					
	MOC : NOT APPLICABLE									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CAL-34-03 R01	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL									
				INFORMATIONAL						
	MOC :									
SL CAL-34-03 R02	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 1612 REVISION E, 2020 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL									
				INFORMATIONAL						
	MOC :									
SL CAL-34-03 R03	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 1612 REVISION F, 2020 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL									
				INFORMATIONAL						
	MOC :									
SL CAL-34-03	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL (SUPERSEDED BY CAL-34-03 R01)									
				INFORMATIONAL						
	MOC :									
SL CAL-34-04	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS)									
				INFORMATIONAL						
	MOC :									
SL CAL-35-01 PART A	PERFORM OXYGEN - ALTITUDE COMPENSATED REGULATOR INSPECTION THE OPERATIONAL TEST OF THE ALTITUDE COMPENSATED REGULATOR(S)	MANDATORY	MTH	02-Dec-2014						N/A
	RPLL		HRS	132.6						
			LDG	103						
	MOC :			NOT APPLICABLE - DUE TO NON OXYGEN SYSTEM INSTALLED						
SL CAL-35-01 PART B	INSPECTION OXYGEN - ALTITUDE COMPENSATED REGULATOR INSPECTION OF THE ALTITUDE COMPENSATED REGULATOR(S)	MANDATORY	MTH	02-Dec-2014						N/A
	RPLL		HRS	132.6						
			LDG	103						
	MOC :			NOT APPLICABLE - DUE TO NON OXYGEN SYSTEM INSTALLED						
SL CAL-35-01	OXYGEN - ALTITUDE COMPENSATED REGULATOR INSPECTION	MANDATORY	MTH	02-Dec-2014						N/A
	RPLL		HRS	132.6						
			LDG	103						
	MOC :			NOT APPLICABLE - DUE TO NON OXYGEN SYSTEM INSTALLED						
SB CAB-36-01 R01	PNEUMATIC - VENTILATION AND DRAINAGE IMPROVEMENTS - TAILCONE									
				OPTIONAL						
	MOC :									
SB CAB-36-01	PNEUMATIC - VENTILATION AND DRAINAGE IMPROVEMENTS - TAILCONE (SUPERSEDED BY CAB-36-01 R01)									
				OPTIONAL						
	MOC :									
SB CAB-55-01	STABILIZERS - INSPECTION / MODIFICATION OF GAP BETWEEN VERTICAL FORWARD SPAR CAPS AND CANTED BULKHEAD	MANDATORY	MTH	22-Sep-2015						Complete
	MNL		HRS	479.5						
			LDG	555						
	MOC :			COMPLIED WITH						
SB CAB-57-02	SPAR FITTING AND ATTACH BRACKET INSPECTION	MANDATORY	MTH	24-Aug-2015						Complete
	MNL		HRS	476.4						
			LDG	549						
	MOC :			COMPLIED WITH						



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CAL-57-03 R01	WINGS - IDENTIFICATION PLATE INSPECTION/REPLACEMENT MANDATORY MTH				-			
MOC :								
SL CAL-57-03	WINGS - IDENTIFICATION PLATE INSPECTION/REPLACEMENT (SUPERSEDED BY CAL-57-03 R01) RPLB MANDATORY MTH 13-Jun-2017				-			N/A
HRS 1403								
LDG 2043								
MOC : NOT APPLICABLE								
SL CAL-57-04	WINGS - CORRECT IMPROPERLY TORQUED AFT SPAR ATTACH BOLTS MANDATORY				-			
MOC :								
SL CAL-61-02	PROPELLER - INSPECTION RPLL MANDATORY MTH 06-Nov-2014				-			Complete
HRS 122.9								
LDG 90								
MOC : COMPLIED WITH - PERFORMED PROPELLER - INSPECTION, SERVICE LETTER SLCAL-61-02 PROVIDES PARTS AND INSTRUCTIONS TO DO AN INSPECTION OF THE PROPELLER MOUNTING BOLT WASHERS.								
SL CAL-61-03	PROPELLER - MCCAULEY TKS NOZZLE BRACKET INSPECTION/REPLACEMENT MANDATORY				-			
MOC :								
SL CAL-61-04	PROPELLER - B-40755A SPRAY HEAD ASSEMBLY REPLACEMENT MANDATORY				-			
MOC :								
SL CAL-61-05	PROPELLER - TRANSMITTAL OF MCCAULEY SERVICE LETTER SL2022-1 MCCAULEY B-6422 AND B-4743 ACTUATING LINK ASSEMBLY INSPECTION MANDATORY MTH				12		16-Aug-2023	2 m 23 d
HRS								
DUE								
100								
4076.4								
74.7								
MOC :								
SL SEL-61-01	PROPELLER GOVERNOR INSPECTION IN ACCORDANCE WITH MCCAULEY ASB273 RPLB MANDATORY MTH 22-Mar-2021				-			N/A
HRS 3753.6								
LDG 6381								
MOC : NOT APPLICABLE								
SB 137A P1	REPLACEMENT OF A-282 INNER CLAMP SCREW UNK		MTH 03-Nov-2021		-			Complete
HRS 3798.6								
MOC : COMPLIED WITH								
ASB HC--61-279 R04 P1	PROPELLER - PROPELLER MOUNTING BOLT INSPECTION UNK		MTH 03-Nov-2021		-			Complete
HRS 3798.6								
MOC : COMPLIED WITH								
ASB HC--61-313 R03 P1	PROPELLER - COUNTERWEIGHT SLUG BOLT INSPECTION UNK		MTH 03-Nov-2021		-			Complete
HRS 3798.6								
MOC : COMPLIED WITH								
ASB HC--61-337 R01 P1	A-880-1 PISTON NUT INSPECTION UNK		MTH 03-Nov-2021		-			Complete
HRS 3798.6								
MOC : COMPLIED WITH								
ASB HC--61-381 R01 PARA (E)(1) P1	ACCOMPLISH PROPELLER - BLADE BEARING RACES OVERHAUL THE PROPELLER AND INSTALL ALL NEW A-1851 BLADE RETENTION BEARINGS (WHICH INCLUDE THE BEARING BALLS) IN ACCORDANCE WITH HARTZELL PROPELLER INC. STEEL HUB TURBINE PROPELLER MAINTENANCE MANUAL 118F (61-10-18). (NEW PROPELLERS AND PROPELLERS THAT HAD ALL NEW A-1851-() BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)		MTH 03-Nov-2021		-			Complete
HRS 3798.6								
MANDATORY								
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB HC--61-381 R01 P1	ACCOMPLISH PROPELLER - BLADE BEARING RACES OVERHAUL THE PROPELLER AND INSTALL ALL NEW A-1851 BLADE RETENTION BEARINGS (WHICH INCLUDE THE BEARING BALLS) IN ACCORDANCE WITH HARTZELL PROPELLER INC. STEEL HUB TURBINE PROPELLER MAINTENANCE MANUAL 118F (61-10-18) (PROPELLERS THAT HAD ANY OVERHAULED A-1851-) BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)							
		MANDATORY						
	MOC :							
ASB HC--61-381 R01 P1	ACCOMPLISH PROPELLER - BLADE BEARING RACES INSPECT THE A-1851- () BLADE RETENTION BEARINGS AND B-6144-2 BEARING BALLS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS IN THIS ALERT SERVICE BULLETIN (PROPELLERS THAT HAD ANY OVERHAULED A-1851- () BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)							
		MANDATORY						
	MOC :							
ASB HC--61-381 R01 P1	ACCOMPLISH PROPELLER - BLADE BEARING RACES OVERHAUL THE PROPELLER AND INSTALL ALL NEW A-1851 BLADE RETENTION BEARINGS (WHICH INCLUDE THE BEARING BALLS) IN ACCORDANCE WITH HARTZELL PROPELLER INC. STEEL HUB TURBINE PROPELLER MAINTENANCE MANUAL 118F (61-10-18). (PROPELLERS THAT HAD ANY OVERHAULED A-1851- () BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)							
		MANDATORY						
	MOC :							
ASB HC--61-381 R01 P1	ACCOMPLISH PROPELLER - BLADE BEARING RACES INSTALL ALL NEW A-1851 BLADE RETENTION BEARINGS (WHICH INCLUDE THE BEARING BALLS) IN ACCORDANCE WITH HARTZELL PROPELLER INC. STEEL HUB TURBINE PROPELLER MAINTENANCE MANUAL 118F (61-10-18). (PROPELLERS THAT HAD ANY OVERHAULED A-1851- () BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)							
		MANDATORY						
	MOC :							
ASB HC--61-381 R01 P1	PROPELLER - BLADE BEARING RACES	MANDATORY	MTH 03-Nov-2021 HRS 3798.6					Complete
	MOC : COMPLIED WITH							
ASB HC--61-399 R01 P1	PROPELLERS OVERHAULED BY CHINA FLYING DRAGON GENERAL AVIATION							
	MOC :							
ASB HC--61-399 P1	PROPELLERS OVERHAULED BY CHINA FLYING DRAGON GENERAL AVIATION	RPLB	MTH 13-Sep-2022 HRS 3978.6					N/A
	MOC : NOT APPLICABLE							
ASB HC--61-402 P1	TRINITY SPECIALIZED SERVICES/MID AMERICA PROPELLER		DAYS HRS		60 10		07-May-2023 (1719.78)4044.58	-17 d 42.88 Over Due
	MOC :							
SB HC--61-136 REV I P1	BLADES - ADDITIONAL OVERHAUL AND INSPECTION PROCEDURES FOR SINGLE- AND DOUBLE-SHOULDER BLADE BORES	UNK	MTH 03-Nov-2021 HRS 3798.6					Complete
	MOC : COMPLIED WITH							
SB HC--61-261 P1	R01 PROPELLER - HUB REPLACEMENT, BLADE AND BLADE CLAMP INSPECTION	UNK	MTH 03-Nov-2021 HRS 3798.6					Complete
	MOC : COMPLIED WITH							
SB HC--61-280 P1	PROPELLER - A-1464 LINK PIN UNIT	UNK	MTH 03-Nov-2021 HRS 3798.6					Complete
	MOC : COMPLIED WITH							



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB HC--61-294 R01 P1	PROPELLER - LINK ARM INSPECTION	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SB HC--61-363 R01 P1	INTRODUCTION OF A-2051-1 BOLT WITH THREE-DIRECTION SAFETY WIRE HOLES	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SB HC--61-374 R01 P1	BLADE BEARING RACE INSPECTION CRITERIA	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SL HC--61-165 P1	PROPELLER - ABNORMAL VIBRATION OR GREASE LEAKAGE	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SL HC--61-167 P1	PROPELLER - INTRODUCTION OF LINKARM BUSHING	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SL HC--61-172 R01 P1	HARTZELL POLICY - NEW FEE FOR PARTS EVALUATION	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SL HC--61-177 P1	BALL BEARINGS - NEW PART NUMBER/USAGE	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SL HC--61-185 R03 P1	TACHOMETERS		RECOMMENDED	MTH 03-Nov-2021		-			N/A
MOC : NOT APPLICABLE									
SL HC--61-187 R04 P1	PROPELLER - ALTERNATE LUBRICATION FITTINGS					-			
MOC :									
SL HC--61-187 R05 P1	PROPELLER - ALTERNATE LUBRICATION FITTINGS					-			
MOC :									
SL HC--61-188 P1	PROPELLER - BLADE/CLAMP SEALING ON AGRICULTURAL AIRCRAFT	UNK	RECOMMENDED	MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SL HC--61-217 P1	PROPELLER - REPLACEMENT OF HARDWARE AT PROPELLER OVERHAUL	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SL HC--61-244 P1	PROPELLER - SPARE PARTS RELEASE	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									
SL HC--61-248 P1	PROPELLER - NEW 101224() AND 101225() START LOCK BRACKETS	UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL HC--61-249 P1	PROPELLER - SPINNER BULKHEADS AFFECTED BY BRAZILIAN AD UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-253 P1	INSPECTION OF STEEL HUB PROPELLERS INSTALLED ON AGRICULTURAL AIRCRAFT UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-254 P1	PROPELLER - PROPELLER OPERATING RESTRICTIONS UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-256 P1	PROPELLER - SPARE PARTS RELEASE UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-258 R01 P1	PROPELLERS - BLADE CLAMP SEALING PROCEDURE UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-270 P1	PROPELLER - PART NUMBER STAMPING UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SB HC-SL-61-277 R04 P1	GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS OPTIONAL				-			
MOC :								
SL HC--61-277 R05 P1	GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS OPTIONAL				-			
MOC :								
SL HC--61-277 R06 P1	GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS OPTIONAL				-			
MOC :								
SL HC--61-324 P1	BLADE - ALUMINUM BLADE FIELD REPAIR UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-329 P1	PROPELLER BLADES - BLADE PAINT UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-343 P1	PRODUCT CATEGORY - LUBRICATION PROCEDURE UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-351 P1	ALTERNATE BOLT (A-2051-1) FOR ATTACHING THE SPINNER MOUNTING PLATE UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH								
SL HC--61-353 P1	PROPELLER - AEROSHELL GREASE 5		MTH 03-Nov-2021		-			N/A
MOC : NOT APPLICABLE								



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL HC--61-355 P1	BLADE - COMPOSITE BLADE MINOR REPAIR KITS				-			
	MOC :							
SL HC--61-356 P1	PRIMER SEALER COLOR CHANGE		MTH 03-Nov-2021		-			N/A
	MOC : NOT APPLICABLE							
SL HC--61-359 P1	POLANE PAINT (SILVER) CM163 UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
	MOC : COMPLIED WITH							
SL HC--61-362 P1	PROPELLER - A-1851-T BLADE RETENTION BEARINGS UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
	MOC : COMPLIED WITH							
SL HC--61-364 P1	PROPELLER - CORROSION INHIBITOR ON COUNTERWEIGHTS UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
	MOC : COMPLIED WITH							
SL HC--61-366 P1	PROPELLER - NYCO GN3058 GREASE UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
	MOC : COMPLIED WITH							
SL HC--61-367 R01 P1	107995-() COUNTERWEIGHT MOUNTING BOLTS UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
	MOC : COMPLIED WITH							
SB HC-SL-61-370 P1	BETA SYSTEM CLEANING PROCEDURE UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
	MOC : COMPLIED WITH							
SL HC--61-372 P1	HARTZELL PROPELLER INC. BLADE DECALS				-			
	MOC :							
SL HC--61-373 P1	SPLIT BEARING RACE ADHESIVE				-			
	MOC :							
SL HC--61-374 P1	ONLINE PRODUCT REGISTRATION				-			
	MOC :							
SL HC--61-61Y R14 P1	PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS FOR HARTZELL PROPELLER INC. AVIATION COMPONENTS - PROPELLERS, GOVERNORS, ACCUMULATORS, AND PROPELLER DAMPER ASSEMBLIES UNK		MTH 03-Nov-2021 HRS 3798.6		-			Complete
	MOC : COMPLIED WITH							
SL CAL-71-12	TRANSMITTAL OF P&WC S.I.L. NO. PT6A-196R1, S.I.L. NO. GEN-123R2, S.I.L. NO. GEN-134, PT6A SPB NO. 185, PT6A SPB NO. 186, S.B. NO. 1002R29, S.B. NO. 1455R3, S.B. NO. 1521R5, S.B. NO. 1568R7, S.B. NO. 1588R2, S.B. NO. 1731, S.B. NO. 1733 INFORMATIONAL				-			
	MOC :							
SL CAL-71-13	TRANSMITTAL OF P&WC S.I.L. NO. GEN-PT6-034, S.B. NO. 1447R4, S.B. NO. 1703R10, S.B. NO. 1705R1, S.B. NO. 1722R1, S.B. NO. 1729, S.B. NO. 1737 INFORMATIONAL				-			
	MOC :							
SL CAL-71-14	POWER PLANT - TRANSMITTAL OF P&WC S.I.L. NO. PT6A-221 INFORMATIONAL				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CAL-71-15	ENGINE MOUNT INSPECTION FOR SUFFICIENT PAINT COVERAGE	MNL	RECOMMENDED	MTH 02-Sep-2015 HRS 476.4 LDG 549		-			Complete
	MOC : COMPLIED WITH								
SL CAL-71-16	POWER PLANT - INSPECT THE INERTIAL SEPARATOR ROD FOR PROPER CLEARANCE AND REPLACETHE SPACER IF CHAFING IS FOUND		RECOMMENDED			-			
	MOC :								
SL CAL-71-17	POWER PLANT - INSPECT FOR PROPER CLEARANCE BETWEEN THE ENGINE MOUNT AND THE RIGHT FIREWALL FLANGE		RECOMMENDED			-			
	MOC :								
SI 07-2014 R02 E1	REPAIR OF OIL LEAK FROM EXHAUST CASE DRAIN HOLE					-			
	MOC :								
SL CAL-12-02	SERVICING - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN P&WC S.B. NO. 1001R29		INFORMATIONAL			-			
	MOC :								
SIL GEN-055 R08 E1	GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES (SUPERSEDED BY GEN-055 R09)		RECOMMENDED			-			
	MOC :								
SIL GEN-055 R09 E1	GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES (SUPERSEDED BY GEN-055 R10)		RECOMMENDED			-			
	MOC :								
SIL GEN-055 R10 E1	GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES		RECOMMENDED			-			
	MOC :								
SB PT6A-72-1001 R29 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY PT6A-72-1001 R30)			MTH		-			
	MOC :								
SB PT6A-72-1001 R30 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS					-			
	MOC :								
SB PT6A-72-1447 R04 E1	MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT (SUPERSEDED BY PT6A-72-1447 R05)					-			
	MOC :								
SB PT6A-72-1447 R05 E1	MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT (SUPERSEDED BY PT6A-72-1447 R06)					-			
	MOC :								
SB PT6A-72-1447 R06 E1	MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT					-			
	MOC :								
SB PT6A-72-1701 R01 E1	REPLACEMENT OF FUEL NOZZLE SHEATH					-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PT6A-72-1701 R02 E1	REPLACEMENT OF FUEL NOZZLE SHEATH CATEGORY 9				-			
	MOC :							
SB PT6A-72-1701 E1	REPLACEMENT OF FUEL NOZZLE SHEATH (SUPERSEDED BY PT6A-72-1701 R01)				-			
	MOC :							
SB PT6A-72-1710 E1	REPLACEMENT OF SINGLE PORT TURBINE EXHAUST DUCT ASSEMBLY				-			
	MOC :							
SB PT6A-72-1715 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (FOHE) CATEGORY 7	MTH	05-Feb-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PT6A-72-1717 E1	MODIFICATION/ REPLACEMENT OF FIRST STAGE CARRIER BALANCING ASSEMBLY	MTH	05-Feb-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PT6A-72-1718 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (FOHE)	MTH	05-Feb-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PT6A-72-1720 R01 E1	REPLACEMENT OF MOTIVE FLOW SOLENOID VALVE ((SUPERSEDED BY PT6A-72-1420 R02)	MTH	05-Feb-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PT6A-72-1720 R02 E1	REPLACEMENT OF MOTIVE FLOW SOLENOID VALVE				-			
	MOC :							
SB PT6A-72-1721 R01 E1	REPLACEMENT OF POWER TURBINE DISK CATEGORY 3				-			
	MOC :							
SB PT6A-72-1723 E1	REPLACEMENT OF COMPRESSOR STATOR ASSEMBLY				-			
	MOC :							
SB PT6A-72-1724 R02 E1	REPLACEMENT / MODIFICATION OF FUEL/OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PT6A-72-1724 R03)	MTH	05-Feb-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PT6A-72-1724 R03 E1	REPLACEMENT / MODIFICATION OF FUEL/OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PT6A-72-1724 R04)				-			
	MOC :							
SB PT6A-72-1724 R04 E1	REPLACEMENT / MODIFICATION OF FUEL/OIL HEAT EXCHANGER (FOHE) CATEGORY 5				-			
	MOC :							
SB PT6A-72-1725 R01 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS INDICATOR	MTH	05-Feb-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PT6A-72-1730 E1	REPLACEMENT OF COMPRESSOR TURBINE SHROUD HOUSING				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PT6A-72-1733 R01 E1	INSPECTION OF TORQUE LIMITER MNL		MTH 30-Jan-2015 HRS 163.4 LDG 154		-			Complete
	MOC : COMPLIED WITH							
SB PT6A-72-1735 E1	REPLACEMENT OF REAR REDUCTION GEARBOX HOUSING				-			
	MOC :							
SB PT6A-72-1736 R01 E1	INTRODUCTION OF FUEL AND OIL TEMPERATURE SENSOR (SUPERSEDED BY PT6A-72-1736 R02)				-			
	MOC :							
SB PT6A-72-1736 R02 E1	INTRODUCTION OF FUEL AND OIL TEMPERATURE SENSOR CATEGORY 5				-			
	MOC :							
SB PT6A-72-1736 R03 E1	INTRODUCTION OF FUEL AND OIL TEMPERATURE SENSOR CATEGORY 5				-			
	MOC :							
SB PT6A-72-1736 E1	INTRODUCTION OF FUEL AND OIL TEMPERATURE SENSOR (SUPERSEDED BY PT6A-72-1736 R01)				-			
	MOC :							
SB PT6A-72-1737 R01 E1	REPLACEMENT / MODIFICATION OF SINGLE PORT TURBINE EXHAUST DUCT ASSEMBLY CATEGORY 3				-			
	MOC :							
SB PT6A-72-1737 R02 E1	REPLACEMENT/MODIFICATION OF SINGLE PORT TURBINE EXHAUST DUCT ASSEMBLY CATEGORY 6				-			
	MOC :							
SB PT6A-72-1737 E1	REPLACEMENT/MODIFICATION OF SINGLE PORT TURBINE EXHAUST DUCT ASSEMBLY (SUPERSEDED BY PT6A-72-1737 R01)				-			
	MOC :							
SB PT6A-72-1740 E1	REPLACEMENT OF PROPELLER OVERSPEED GOVERNOR				-			
	MOC :							
SB PT6A-72-1743 E1	CONVERSION OF PT6A-140 (BS1294) ENGINE TO PT6A-140 (BS1342) ENGINE				-			
	MOC :							
SB PT6A-72-1750 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS INDICATOR PREFORMED PACKINGS				-			
	MOC :							
SB PT6A-72-1751 E1	REORIENTATION OF STRAIGHT HEADED PIN				-			
	MOC :							
SB PT6A-72-1752 R01 E1	INSPECTION OF FUEL NOZZLE TIPS (SUPERSEDED BY PT6A-72-1752 R02) MNL		MTH 21-May-2015 HRS 403.3 LDG 455		-			Complete
	MOC : COMPLIED WITH							
SB PT6A-72-1752 R02 E1	INSPECTION OF FUEL NOZZLE TIPS				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PT6A-72-1752 E1	INSPECTION OF FUEL NOZZLE TIPS (SUPERSEDED BY PT6A-72-1752 R01)		MTH			-			
	MOC :								
SB PT6A-72-1753 E1	REPLACEMENT OF COMPRESSOR TURBINE AIR BAFFLE					-			
	MOC :								
SB PT6A-72-1755 R01 E1	REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, POWER TURBINE STATOR AIR SEAL AND RETAINING RING		CATEGORY 7			-			
	MOC :								
SB PT6A-72-1755 E1	REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, POWER TURBINE STATOR AIR SEAL AND RETAINING RING					-			
	MOC :								
SB PT6A-72-1756 E1	REMOVAL OF REDUCTION GEARBOX TACHOMETER PAD WASHER					-			
	MOC :								
SB PT6A-72-1757 E1	REPLACEMENT/MODIFICATION OF 1ST AND 2ND STAGE REDUCTION CARRIER SET					-			
	MOC :								
SB PT6A-72-1765 R01 E1	REPLACEMENT OF OIL FILTER, OIL FILLER NECK AND RGB STRAINER - PREFORMED PACKINGS					-			
	MOC :								
SB PT6A-72-1765 E1	REPLACEMENT OF OIL FILTER, OIL FILLER NECK AND RGB STRAINER - PREFORMED PACKINGS (SUPERSEDED BY PT6A-72-1765 R01)					-			
	MOC :								
SB PT6A-72-1766 E1	INSPECTION OF INTERCONNECT ROD	MNL		MTH 02-Sep-2015 HRS 476.4 LDG 549		-			Complete
	MOC : COMPLIED WITH								
SB PT6A-72-1771 E1	REPLACEMENT OF PROPELLER REDUCTION GEARBOX FRONT AND REAR HOUSING ASSEMBLY					-			
	MOC :								
SB PT6A-72-1775 R01 E1	CONVERSION OF PT6A-140 ENGINE (BS1294) TO PT6A-140 ENGINE (BS1341)		CATEGORY 8			-			
	MOC :								
SB PT6A-72-1775 E1	CONVERSION OF PT6A-140 ENGINE (BS1294) TO PT6A-140 ENGINE (BS1341)					-			
	MOC :								
SB PT6A-72-1776 R01 E1	CONVERSION OF PT6A-140 ENGINE (BS1294) TO PT6A-140 ENGINE (BS1345)					-			
	MOC :								
SB PT6A-72-1776 E1	CONVERSION OF PT6A-140 ENGINE (BS1294) TO PT6A-140 ENGINE (BS1345) (SUPERSEDED BY PT61-72-1776 R01)					-			
	MOC :								
SB PT6A-72-1777 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER ASSEMBLY					-			
	MOC :								
SB PT6A-72-1778 E1	REPLACEMENT / MODIFICATION OF CARRIER BALANCING ASSEMBLY FIRST-STAGE					-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PT6A-72-1779 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER	CATEGORY 7			-			
	MOC :							
SB PT6A-72-1779 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER				-			
	MOC :							
SB PT6A-72-1783 E1	REPLACEMENT / MODIFICATION OF POWER TURBINE STATOR AIR SEAL				-			
	MOC :							
SB PT6A-72-1785 R01 E1	REPLACEMENT OF POWER TURBINE STATOR AIR SEAL				-			
	MOC :							
SB PT6A-72-1785 E1	REPLACEMENT OF POWER TURBINE STATOR AIR SEAL (SUPERSEDED BY PT6A-72-1785 R01)				-			
	MOC :							
SB PT6A-72-1788 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY.				-			
	MOC :							
SB PT6A-72-1790 R01 E1	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY	CATEGORY 7			-			
	MOC :							
SB PT6A-72-1790 R02 E1	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY	CATEGORY 7			-			
	MOC :							
SB PT6A-72-1790 E1	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY				-			
	MOC :							
SB PT6A-72-1791 R01 E1	REPLACEMENT OF COMPRESSOR CENTER TOP FIRESEAL	CATEGORY 7			-			
	MOC :							
SB PT6A-72-1791 E1	REPLACEMENT OF COMPRESSOR CENTER TOP FIRESEAL	CATEGORY 7			-			
	MOC :							
SB PT6A-72-1796 R01 E1	REPLACEMENT/MODIFICATION OF SCAVENGE PUMP HOUSING	CATEGORY 7			-			
	MOC :							
SB PT6A-72-1796 E1	REPLACEMENT OF SCAVENGE PUMP HOUSING	CATEGORY 7			-			
	MOC :							
SB PT6A-72-1800 R01 E1	REPLACEMENT OF NUT OPTION (IC)	CATEGORY 9			-			
	MOC :							
SB PT6A-72-1800 E1	REPLACEMENT OF NUT OPTION (IC)	CATEGORY 9			-			
	MOC :							
SB PT6A-72-1804 E1	REPLACEMENT/MODIFICATION OF CENTRIFUGAL IMPELLER	CATEGORY 7			-			
	MOC :							
SB PT6A-72-1805 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) PREFORMED PACKING	CATEGORY 3			-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PT6A-72-1806 E1	REMOVAL OF FUEL OIL HEAT EXCHANGER (FOHE) TEMPERATURE SENSOR			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1807 R01 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1807 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1808 R01 E1	INTRODUCTION OF T5 TRIM-WIRING-HARNESS CLASSIFICATIONS			CATEGORY 9			-			
	MOC :									
SB PT6A-72-1808 E1	INTRODUCTION OF T5 TRIM-WIRING-HARNESS CLASSIFICATIONS			CATEGORY 9			-			
	MOC :									
SB PT6A-72-1811 R01 E1	INTRODUCTION OF SCAVENGE-PUMP DRIVE-SHAFT PLUG			CATEGORY 3	MTH		36		05-Dec-2022	-5 m 19 d
	MOC :									Over Due
SB PT6A-72-1811 E1	INTRODUCTION OF SCAVENGE-PUMP DRIVE-SHAFT PLUG			CATEGORY 5			-			
	MOC :									
SB PT6A-72-1824 E1	REPLACEMENT OF REDUCTION GEARBOX FIRST STAGE RING GEAR AND PLANET GEAR SET			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1831 R01 E1	REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE-ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1831 R02 E1	REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE-ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1831 R03 E1	REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE-ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1831 E1	REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE-ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1833 E1	INTRODUCTION OF ALTERNATE BALL BEARING			CATEGORY 9			-			
	MOC :									
SB PT6A-72-1834 E1	REPLACEMENT OF FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLIES			CATEGORY 7			-			
	MOC :									
SB PT6A-72-1903 R03 E1	OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
	MOC :									
SL CAL-73-05	TRANSMITTAL OF P&WC S.B. NO. 1748			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CAL-73-06	FUEL NOZZLE TIP ASSEMBLY REPLACEMENT			RECOMMENDED						
	MOC :									
SB PT6A-74-1819 R01 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7						
	MOC :									
SB PT6A-74-1819 R02 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7						
	MOC :									
SB PT6A-74-1819 R03 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7						
	MOC :									
SB PT6A-74-1819 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7						
	MOC :									
SB PT6A-74-1835 E1	INSPECTION/REPLACEMENT OF IGNITION CABLE ASSEMBLY			CATEGORY 5						
	MOC :									
SB CAB-77-01 R01	ENGINE INDICATING - FAST ENGINE TREND MONITORING INSTALLATION FOR AIRPLANES WITH PROVISIONS			RECOMMENDED MTH						
	MOC :									
SB CAB-77-01	FAST ENGINE TREND MONITORING INSTALLATION FOR AIRPLANES WITH PROVISIONS (SUPERSEDED BY CAB-77-01 R01)	MNL		RECOMMENDED	MTH 21-May-2015					Complete
					HRS 403.3					
					LDG 455					
	MOC :									
SB CAB-77-02	ENGINE INDICATING - NEW CONFIGURATION FILE FOR ADAS SYSTEMS			OPTIONAL						
	MOC :									
SB CAB-77-03	ENGINE INDICATING - FAST HARDWARE AND SOFTWARE UPDATE FOR 4G NETWORK CONNECTIVITY			OPTIONAL						
	MOC :									
SL CAL-77-01	INSPECTION OF THE PRESSURE LINE AND VENT LINE FOR THE TORQUE INDICATOR GAUGE	MNL		MANDATORY	MTH 22-May-2015					Complete
					HRS 403.3					
					LDG 455					
	MOC :									
SL CAL-77-02	ENGINE INDICATING - FAST HARDWARE AND SOFTWARE UPDATE AVAILABLE FOR 3G NETWORK CONNECTIVITY			OPTIONAL						
	MOC :									
SB PT6A-77-1820 E1	REPLACEMENT OF TORQUE PRESSURE TRANSDUCER			CATEGORY 7						
	MOC :									
SB CAB-78-02	EXHAUST - HANGER BRACKET LOCATIONS			RECOMMENDED						
	MOC :									
COM ME-P-002	EXHAUST - MULTI-ENGINE PISTON COMMUNIQUE									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
STC SA02080AK-D	EXHAUST DEFLECTOR - AERO TWIN				MTH 09-Mar-2014		-			Complete
					HRS 1.3					
					LDG 1					
	MOC : COMPLIED WITH - INSTALLED AERO TWIN EXHAUST DEFLECTOR P/N ED8-100 PER STC SA02080AK-D. INSTALLATION WAS INCORPORATED DURING PRODUCTION.									
SL CAL-79-01	OIL - C100490-1 OIL COOLER SYSTEM CHECK VALVE ASSEMBLY REPAIR KIT INSTALLATION						-			
	OPTIONAL									
	MOC :									
SL CAL-79-02 R01	INTRODUCTION OF OIL - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PT6A-72-1811 - TURBOPROP ENGINE SCAVENGE-PUMP DRIVE-SHAFT PLUG						-			
	MOC :									
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	INFORMATIONAL									
	MOC :									
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	INFORMATIONAL									
	MOC :									
SB CAB-80-01	300 AMPERE STARTER/GENERATOR INSTALLATION FOR 208B EX (867SHP) AIRPLANES						-			
	OPTIONAL									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 1997-25-04	POWER LEVER POSITIONING KICT	MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY AFM REVISION (SECTION 2)								
FAA 2001-10-09	HONEYWELL KC225-FLGT CONTROL SYSTEM KICT	MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		A/R			N/A
MOC : NOT APPLICABLE - HONEYWELL KC225 AUTOPILOT. PARTS NOT INSTALLED.								
FAA 2004-17-01	INSP FLAP BELLCRANK WELD KICT	MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		A/R			N/A
MOC : NOT APPLICABLE - SUBJECT PARTS NOT INSTALLED.								
FAA 2009-10-14	IDENTIFICATION AND REMOVAL OF ALL PROPELLER BLADE COUNTERWEIGHT SLUG BOLTS, P/N B-3386-14H, KICT	MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		A/R			N/A
MOC : NOT APPLICABLE - SUBJECT PARTS NOT INSTALLED								
FAA 2008-13-06	DETECT AND CORRECT DAMAGED WIRING OF THE AUTO-CONTROL WING DE-ICE SYSTEM, FUEL QUANTITY INDICATION, AND LOW FUEL ANNUNCIATION SYSTEMS KICT	MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.								
EASA 2014-0187 PARA (1)	INSPECT THE SAFETY BELT ATTACHMENT BOLTS MANDATORY				-			
MOC :								
EASA 2014-0187 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DETACHED OR LOOSENED SAFETY BELT ATTACHMENT BOLTS ARE FOUND, BEFORE NEXT FLIGHT, RE-TORQUE THE AFFECTED BOLTS TO THE VALUE AS DEFINED IN, AND IN ACCORDANCE WITH THE INSTRUCTIONS OF, GEVEN SB NO. D103-25-004 REVISION 2. MANDATORY				-			
MOC :								
EASA 2014-0187 PARA (3)	FOR SPECIFIC D1-03 SEAT ASSEMBLIES (P/N AS IDENTIFIED IN TABLE 1.1.1 OF GEVEN SB NO. D103-25-004 REVISION 2, EFF CODE FROM AAA TO AUC), WITHIN 6 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY THE SEAT BELT ATTACHMENT ASSEMBLY ON THE AISLE SIDE SPREADER OF STANDARD AND LAST ROW SEATS IN ACCORDANCE WITH THE INSTRUCTIONS OF GEVEN SB NO. D103-25-004 REVISION 2. MANDATORY				-			
MOC :								
EASA 2014-0187 PARA (4)	AS AN ALTERNATIVE TO THE CORRECTIVE ACTIONS AS REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, BEFORE NEXT FLIGHT, BLOCK EACH AFFECTED SEAT FOR OCCUPANCY, PENDING ACCOMPLISHMENT OF THE APPLICABLE CORRECTIVE ACTION(S). MANDATORY				-			
MOC :								
EASA 2014-0187	APPLIANCE AD - EQUIPMENT & FURNISHINGS – SAFETY BELT ATTACHMENT BOLTS – INSPECTION / REPLACEMENT MANDATORY		MTH		-			
MOC :								
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE RPLB	MANDATORY	MTH 10-Apr-2021 HRS 3781.6 LDG 6454		-			N/A
MOC : NOT APPLICABLE - DUE TO DIFFERENT PART NO. AND NO CRACK FOUND								



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE RPLB	MANDATORY	MTH 10-Apr-2021 HRS 3781.6 LDG 6454		-			N/A
MOC : NOT APPLICABLE - DUE TO DIFFERENT PART NO. AND VANE LESS THAN .125 INCH								
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER RPLB	MANDATORY	MTH 10-Apr-2021 HRS 3781.6 LDG 6454		-			N/A
MOC : NOT APPLICABLE - DUE TO DIFFERENT PART NO. AND NO CRACK FOUND								
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	MANDATORY	MTH 10-Apr-2021 HRS 3781.6 LDG 6454		-			N/A
MOC : NOT APPLICABLE - DUE TO DIFFERENT PART NO. AND NO CRACK FOUND								
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART	MANDATORY	DAYS 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE								
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2	MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE								
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3	MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE								
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1	MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE								
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'	MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE								
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT	MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE								



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2016-0044 PARA (1)	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1		MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED									
EASA 2016-0044 PARA (2)	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1).		MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED									
EASA 2016-0044 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REVISION 14, OR OF KG CMM 26-21-52 REVISION 13, AS APPLICABLE TO FIRE EXTINGUISHER P/N		MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED									
EASA 2016-0044	ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL		MANDATORY	MTH 14-Jan-2019 HRS 2994.6 LDG 5009		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED									
FAA 1988-19-06	PREVENT POSSIBLE ELEVATOR FLUTTER KICT		MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		A/R			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.									
FAA 1990-05-01	TO PREVENT FAILURE OF THE PART NUMBER (P/N) 2622083-18 BELLCRANK ASSEMBLY AND THE RESULTING UNEXPECTED RETRACTION OF THE FLAPS KICT		MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		A/R			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.									
FAA 2009-05-12	MODIFY THE AILERON CARRY-THROUGH CABLE ATTACHMENT TO THE AILERON UPPER QUADRANT WITH PARTS OF IMPROVED DESIGN KICT		MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		-			N/A
MOC : NOT APPLICABLE - PER PARAGRAPH (C) OF THIS AD.									
FAA 2009-15-05	MEASURE AND ADJUST AS NECESSARY, THE ROLL BRIDLE CABLE TENSION AND YAW BRIDLE CABLE TENSION, AND TORQUE THE 12 BRIDLE CABLE CLAMP SCREWS KICT		MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT IN SERIAL RANGE.									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 1997-01-13	TO PREVENT FUEL, OIL, OR HYDRAULIC SYSTEMS FAILURE CAUSED BY A COLLAPSED HOSE									
	KICT		MANDATORY		MTH 09-Mar-2014		A/R			N/A
					HRS 1.3					
					LDG 1					
	MOC : NOT APPLICABLE - SUBJECT PARTS NOT INSTALLED									
FAA 1996-09-15	TO MINIMIZE THE POTENTIAL HAZARDS ASSOCIATED WITH OPERATING THE AIRPLANE IN SEVERE ICING CONDITIONS									
	KICT		MANDATORY		MTH 09-Mar-2014		A/R			Complete
					HRS 1.3					
					LDG 1					
	MOC : COMPLIED WITH - COMPLIED WITH BY AFM REVISION (SECTION 2)									
FAA 2006-01-11 R01	DEICE BOOT/ASSIST HANDLE		MANDATORY		MTH 09-Mar-2014		A/R			Complete
	KICT				HRS 1.3					
					LDG 1					
	MOC : COMPLIED WITH - AD WAS INCORPORATED DURING PRODUCTION									
FAA 2007-10-15	KNOWN ICING EQUIPMENT AFM SUPPLEMENT				MTH 09-Mar-2014		A/R			N/A
	KICT		MANDATORY		HRS 1.3					
					LDG 1					
	MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED ON ACFT.									
FAA 2021-23-12	INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS									
	RPLB		MANDATORY		MTH 15-Dec-2021		-			Complete
					HRS 3814.2					
					LDG 6497					
	MOC : COMPLIED WITH									
FAA 1990-05-04	TO PREVENT NOSE LANDING GEAR SHIMMY AND FAILURE OF THE ENGINE MOUNT RING									
	KICT		MANDATORY		MTH 09-Mar-2014		A/R			N/A
					HRS 1.3					
					LDG 1					
	MOC : NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.									
EASA 2006-0265- CN	APPLIANCE AD - CANCELLED: NAVIGATION SYSTEMS - MODE S AND C TRANSPONDERS - CHECK									
	CANCELLED						-			
	MOC :									
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)									
			MANDATORY		MTH 14-Jan-2019		-			N/A
					HRS 2994.6					
					LDG 5009					
	MOC : NOT APPLICABLE - GARMNIN 1000 INUSE									
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD									
			MANDATORY		MTH 14-Jan-2019		-			N/A
					HRS 2994.6					
					LDG 5009					
	MOC : NOT APPLICABLE - GARMNIN 1000 INUSE									
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT									
			MANDATORY		MTH 14-Jan-2019		-			N/A
					HRS 2994.6					
					LDG 5009					
	MOC : NOT APPLICABLE - GARMNIN 1000 INUSE									



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRs UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD	MANDATORY	MTH 14-Jan-2019		-			N/A
			HRS 2994.6					
			LDG 5009					
	MOC : NOT APPLICABLE - GARMNIN 1000 INUSE							
EASA 2015-0093	APPLIANCE AD - NAVIGATION - ATTITUDE HEADING REFERENCE SYSTEM - MODIFICATION / REPLACEMENT	MANDATORY	MTH 14-Jan-2019		-			N/A
			HRS 2994.6					
			LDG 5009					
	MOC : NOT APPLICABLE - GARMNIN 1000 INUSE							
FAA 1998-25-02	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS	MANDATORY	MTH 09-Mar-2014		A/R			N/A
	KICT		HRS 1.3					
			LDG 1					
	MOC : NOT APPLICABLE - AD 98-25-02 BF GOODRICH AVIONICS SYSTEMS, THIS AD IS NOT APPLICABLE DUE TO PARTS ARE NOT INSTALLED.							
FAA 2005-01-19	APPLIANCE AD - GTX 33/33D/330/330D SOFTWARE UPGRADE	MANDATORY	MTH 09-Mar-2014		A/R			N/A
	KICT		HRS 1.3					
			LDG 1					
	MOC : NOT APPLICABLE - DUE TO LATER REVISION OF SOFTWARE INSTALLED IN THE GTX 33 TRANSPONDER.							
FAA 2006-16-18 R01	APPLIANCE AD - SANDEL ST3400 TAWS/RMI PLACARD	MANDATORY	MTH 09-Mar-2014		A/R			N/A
	KICT		HRS 1.3					
			LDG 1					
	MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED ON ACFT.							
FAA 2008-10-02	INSPECT THE ALTERNATE STATIC AIR SOURCE SELECTOR VALVE TO ASSURE THAT THE PART NUMBER IDENTIFICATION PLACARD IS NOT OBSTRUCTING THE PORT	MANDATORY	MTH 09-Mar-2014		-			N/A
	KICT		HRS 1.3					
			LDG 1					
	MOC : NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.							
FAA 2008-26-10	INSPECT ALTERNATE STATIC AIR SOURCE SELECTOR VALVE FOR OBSTRUCTION BY PLACARD.	MANDATORY	MTH 09-Mar-2014		A/R			N/A
	KICT		HRS 1.3					
			LDG 1					
	MOC : NOT APPLICABLE - PER PARAGRAPH (C) OF THIS AD.							
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	MANDATORY	MTH		-			
	MOC :							
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	MANDATORY			-			
	MOC :							
FAA 2015-10-51	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	MANDATORY	MTH 02-Sep-2015		-			N/A
	MNL		HRS 476.4					
			LDG 549					
	MOC : NOT APPLICABLE - NOT APPLICABLE							



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	RPLL		MANDATORY	MTH 21-Jul-2016 HRS 922.8 LDG 1184		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	RPLL		MANDATORY	MTH 21-Jul-2016 HRS 922.8 LDG 1184		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	RPLB		MANDATORY	MTH 06-Jul-2017 HRS 1464.3 LDG 2146		-			N/A
MOC : NOT APPLICABLE - NO PBE INSTALLED.										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12			MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	RPLB		MANDATORY	MTH 26-Oct-2017 HRS 1742.5 LDG 2603		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE DUE PBE NOT INSTALLED										
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES			MANDATORY			-			
MOC :										
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016	RPLB		MANDATORY	MTH 06-Jul-2017 HRS 1464.3 LDG 2146		-			N/A
MOC : NOT APPLICABLE - SERIAL NUMBER INSTALLED IS 502525.										
FAA 2021-04-10 PARA (G)	INSPECTION AND FASTENER REPLACEMENT			MANDATORY	MTH		-			
MOC :										
FAA 2021-04-10 PARA (H)	FAA REPORTING REQUIREMENT			MANDATORY	DAYS		-			
MOC :										
FAA 2021-04-10	ELEVATOR STRUCTURE - TORQUE TUBE ATTACH FASTENERS - INSPECTION/REPLACEMENT			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **TEXTRON FINANCIAL CORPORATION**
 Aircraft Model: **208B CARAVAN - TBIP**
 Aircraft Serial: **208B-5098**
 Unit: Reg No: **RP-C1087**
 Airworthiness: **09-Mar-2014**
 Print Date: **24-May-2023 2:06AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4001.7	6734	28-Mar-2023	.9
ENG	4001.7	6734	28-Mar-2023	.9
PROP 1	1676.9		28-Mar-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2004-08-17	STRUT ATTACMENT BOLTS AND NUTS KICT			MANDATORY	MTH 09-Mar-2014 HRS 1.3 LDG 1		A/R			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.										
FAA 1983-08-01 R02	HARTZELL PROPELLER INC. (FORMERLY TRW HARTZELL PROPELLER) MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, AND HC-B5MP-3 TURBOPROPELLERS									
P1		UNK		MANDATORY	MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH										
FAA 1996-18-14	PROPELLER - HARTZELL MODELS HC-A3V, HC-B3M, HC-B3T, HC-B4M, HC-B4T, AND HC-B5M HUB - INSPECT / REPLACE									
P1		UNK		MANDATORY	MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH										
FAA 2003-13-17	PROPELLERS - MAINTENANCE ACTIONS ON HARTZELL PROPELLER, INC., MCCAULEY PROPELLER SYSTEMS, SENSENICH PROPELLER MANUFACTURING COMPANY, INC., AND RAYTHEON AIRCRAFT COMPANY PROPELLERS RETURNED TO SERVICE BY T AND W PROPELLERS, INC., OF CHINO CA									
P1		UNK			MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH										
FAA 2005-14-11	PROPELLER - HARTZELL, MCCAULEY AND SENSENICH PROPELLERS RETURNED TO SERVICE BY SOUTHERN CALIFORNIA PROPELER SERVICE OF INGLEWODD, CA - MAINTENANCE ACTIONS AMOUNTING TO AN OVERHAUL									
P1		UNK		MANDATORY	MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH										
FAA 2005-14-12	PROPELLER - HARTZELL PROPELLER MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B3MN-3, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, HC-B4MP-3, HC-B4MP-5, AND HC-B5MP-3 MOUNTING BOLTS - INSPECT / REPLACE									
P1		UNK		MANDATORY	MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH										
FAA 2006-24-07	HARTZELL PROPELLER INC. PROPELLERS AND MCCAULEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS									
P1		UNK		MANDATORY	MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH										
FAA 2009-10-14	IDENTIFICATION AND REMOVAL OF ALL PROPELLER BLADE COUNTERWEIGHT SLUG BOLTS, P/N B-3386-14H,LFC MANUFACTURING LOT 224, FROM SERVICE									
P1		UNK		MANDATORY	MTH 03-Nov-2021 HRS 3798.6		-			Complete
MOC : COMPLIED WITH										