

# N2130L

## 1976 Beech 58TC Baron

---

# LH Prop Logbook

**Aircraft S/N: TK-25**



**RidgeAire**  
WORLDWIDE  
aviation specialists

*Prepared by the worldwide aviation specialists at RidgeAire, Inc.*

N2130L

HARTZELL

**LEFT  
PROPELLER LOGBOOK**

PROPELLER MODEL PHC-J3YF-2UF/FC7663DR

PROPELLER S/N ED5311B

LOGBOOK # 1



SEE OTHER SIDE


## Maintenance Release

Part Hartzell

Model PHC J3YF 2UF

The component identified above was repaired/  
~~overhauled~~ and inspected in accordance with  
current Federal air regulations and was found  
air-worthy for return to service. Pertinent details  
of the repair are on file at this agency under Work  
Order No. 15472

Date 6-24-08

Signed   
Authorized Individual

### PRECISION PROPELLER SERVICE, INC.

Weld County Municipal Airport  
631 Buss Ave., Greeley, CO 80631

(970) 352-8578

FAA APPROVED REPAIR STATION  
NO. UB3R887L

**DESCRIPTION OF WORK ACCOMPLISHED**

Make Hartzell Model PHC-J3YF-2UF

S/N ED5311B Blades 1 \_\_\_\_\_ 2 \_\_\_\_\_ 3 \_\_\_\_\_ 4 \_\_\_\_\_

Overhauled \_\_\_\_\_ Blades Rep. \_\_\_\_\_ Blade Repair \_\_\_\_\_ Reseal \_\_\_\_\_

Repitch \_\_\_\_\_ Other \_\_\_\_\_ Service Manual \_\_\_\_\_

Service Letters \_\_\_\_\_

Service Bulletins \_\_\_\_\_

AD's \_\_\_\_\_ Boot P/N SMR1601-7

Remarks install new de-icers.

Pitch Settings: Low \_\_\_\_\_ High \_\_\_\_\_ Reverse \_\_\_\_\_

TSO \_\_\_\_\_ TT \_\_\_\_\_ Feather \_\_\_\_\_ Latch \_\_\_\_\_







Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				Hartzell(Left) Model# PHC-J3YF-2UF SER# ED5311B 02/05/2018 SPOH 802 This date performed an annual inspection, removed all nicks and painted back of blades flat black. Inspected and determined that this prop was found to be in airworthy condition. <i>David J. Smith IA3036512</i>
				Hartzell (Left) model PHCJ3YF2-U Ser# ED 5311 B 10/20/20 SPOH 1683.3 c/w annual inspection w/retro Beech 587C motor checked A/D TRAV FAD Reserve Recently this propeller is Bw Inspected JLA/W An annual inspection and it is airworthy condition Show these ATP JLA 3962901

11/9/23		1779		Annual inspection c/w Fwd Accessory Z-Sign IA3071998
<p><b>EAST TEXAS FLYING SERVICE INC. 903 571-0116</b>  <b>LEFT PROP N2130L 1/16/2025 1779 Hobbs.</b>  <b>I CERTIFY THAT I HAVE INSPECTED THIS PROPELLER</b>  <b>I AW THE MANUFACTURER'S PERIODIC INSPECTION</b>  <b>RECOMMENDATIONS AND THAT IT IS IN AN AIRWORTHY</b>  <b>CONDITION.</b></p> <p><b>PATRICIA BURCH</b>  <b>3524230/AP/IA</b></p> <p><i>Patricia Burch</i></p>				

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	---

**PEARCE AIRCRAFT SERVICES, INC.**

MEADOW LAKE AIRPORT 8264 CESSNA DR PEYTON, CO 80831 719 683 3314

DATE	TYPE	SERIAL	HOBBS	TIS / TSOH	REGISTRATION
02-19-2026	PHC-J3YF-2UF	ED5311B LT	1909.4	610.6 / N/A	N2130L

1. 2026 100 hour/ annual inspection. See N2130L airframe log.

Robert K Taylor Robert K Taylor A&P 3786170 IA

**PEARCE AIRCRAFT SERVICES, INC.**

MEADOW LAKE AIRPORT 8264 CESSNA DR PEYTON, CO 80831 719 683 3314

DATE	TYPE	SERIAL	HOBBS	TIS / TSOH	REGISTRATION
02-19-2026	PHC-J3YF-2UF	ED3412 RT	1909.4	4942.9 / 1909.4	N2130L

1. 2026 100 hour/ annual inspection. See N2130L airframe log.

Robert K Taylor Robert K Taylor A&P 3786170 IA
