

N207RA

2014 Cessna 208B

Airworthiness Directives

Aircraft S/N: 208B-5098



RidgeAire
WORLDWIDE
aviation specialists

Prepared by the worldwide aviation specialists at RidgeAire, Inc.

Textron (Cessna) 208B

Airworthiness Directives
Compliance Report

Date: 9/12/2025
Airframe: Textron (Cessna) 208B
Engine: Pratt & Whitney PT6A-140
Propeller: Hartzell HC-B3TN-3

Tail #: N207RA
S/N: 208B-5098
S/N: PCE-VA0103
S/N:

Hours: 4056.7
Hours: 4056.7
Hours:

AD#	Category	Subject	Amdt#	Eff Date	Rec	Remarks
Date/Hours Compliance	Next Due	Name	Signature			Part#
Airframe: Textron (Cessna) 208B						
88-19-06	Airframe	Elevator Balance Brackets	39-8014	09/30/88		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
90-05-01	Airframe	Bellcrank	39-5543	03/05/90		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
90-05-04	Airframe	Engine Mount Ring	39-5512	03/23/90		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
96-09-15	Airframe	AFM - Limitations Section - Icing	39-3591	06/11/96		Airplane not approved for flights known icing conditions A&P24922625IA
N/A			Jacques Raissiguer			
97-01-13	Airframe	Collapsed Fuel, Oil, Hydraulic Hoses	39-1884	02/03/97		N/A by hose P/N installed A&P24922625IA
N/A		N/A	Jacques Raissiguer			
97-25-04	Airframe	Power Lever Positioning	39-16227	01/21/98		C/W by AFM Revision (Section 2) A&P24922625IA
N/A			Jacques Raissiguer			
When built						Superseded
2002-22-17	Airframe	Superseded By 04-17-01				A&P24922625IA
N/A		N/A	Jacques Raissiguer			Superseded
2003-21-04	Airframe	Superseded By 04-17-01				A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2004-08-17	Airframe	Wing Strut Attachment Bolts	39-10587	05/17/04		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2004-17-01	Airframe	Flap Bellcranks	39-13772	09/25/04	Yes* (Terminating Action)	N/A by serial number A&P24922625IA
N/A			Jacques Raissiguer			Superseded
2005-07-01	Airframe	Superseded By 06-06-05				A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2005-01-11 R1	Airframe	Operation in Icing Conditions	39-14575	02/22/06		A&P24922625IA
N/A		N/A	Jacques Raissiguer			Superseded
When built						A&P24922625IA
2006-06-06	Airframe	Superseded By 07-10-15				Kit installed when built A&P24922625IA
N/A			Jacques Raissiguer			
2007-10-15	Airframe	Operations in Icing Conditions	39-15058	06/21/07		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
When built						
2008-10-02	Airframe	Alternate Static Air Source Selector Valve	39-15508	05/42/08		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2008-13-06	Airframe	Chafed Wiring	39-15568	07/30/08		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2008-26-10	Airframe	Alternate Static Air Source Selector Valve	39-15776	07/10/09		N/A by P/N installed A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2009-05-12	Airframe	Aileron Control System "Catch"	39-15836	04/15/09		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2009-15-05	Airframe	Loose Bndle Cable Clamps	39-15958	07/27/09		N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2021-04-10	Airframe	Elevator Torque Tube Fasteners	39-21431	04/12/21	Yes	N/A by serial number A&P24922625IA
N/A		N/A	Jacques Raissiguer			
Propeller: Hartzell HC-B3TN-3						
71-26-04	Propeller	Superseded By 72-08-04				Superseded A&P24922625IA
N/A			Jacques Raissiguer			
72-08-04	Propeller	Dye Penetrant Inspection For Blade Cracks	39-1427	04/11/72	Yes* (Terminating Action)	N/A by blades S/N A&P24922625IA
N/A			Jacques Raissiguer			
74-14-01	Propeller	Blade Crack Inspection	39-1924	08/22/74		N/A L blades installed A&P24922625IA
N/A		N/A	Jacques Raissiguer			Superseded
78-18-01	Propeller	Superseded By 83-08-01				A&P24922625IA
N/A			Jacques Raissiguer			
83-08-01 R2	Propeller	Propeller Attaching Bolt Failures	39-14043	05/11/05		Propper hardware installed A&P24922625IA
09/12/2025 TT = 4056.7		N/A	Jacques Raissiguer			
96-15-04	Propeller	Blade Shank Cracks	39-9697	07/29/96		N/A blades not listed in ASB HC-ASB-61-220 A&P24922625IA
N/A		N/A	Jacques Raissiguer			
96-18-14	Propeller	Hub Replacement	39-9738	10/16/96		N/A by hub S/N A&P24922625IA
N/A		N/A	Jacques Raissiguer			
2003-13-17	Propeller	T and W Serviced Propellers	39-13219	07/18/03		N/A No work performed by this shop A&P24922625IA
N/A			Jacques Raissiguer			
2005-14-11	Propeller	Southern California Propeller Serviced	39-14188	08/17/06		A&P24922625IA
N/A		N/A	Jacques Raissiguer			

Page 2 is for engine N/A



Master AD/SI Report

208B CARAVAN - TBIP
S/N 208B-5098 RP-C1087

OWNER: TEXTRON FINANCIAL CORPORATION
ADDRESS: TWO CESSNA BOULEVARD
WICHITA KS 67215-1423

OPERATOR: AIR JUAN AVIATION INC.
ADDRESS: UNIT 501-505 C2 BLDG. 28TH CORNER
7TH AVENUE
BONIFACIO GLOBAL CITY, TAGUIG CITY

OPERATOR: GALEO EQUIPMENT CORPORATION
ADDRESS: UNIT 501-505 C2 BLDG. 28TH STREET
TAGUIG CITY

PHONE:
FAX:

PHONE: 63-917-528-1676
FAX:

PHONE:
FAX:

ANALYST: KINA MENDOZA
EMAIL: KMENDOZA@CAMPSYSTEMS.COM

+1-316-462-2461 (DIRECT)
1-866-581-2267 (OFFICE)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; For: Airframe,Engine,APU Etc;

AIRCRAFT SERIAL/REGNO: 208B-5098/RP-C1087 **MODEL:** 208B CARAVAN - TBIP **MANUFACTURER:** TEXTRON AVIATION INC.

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 09-MAR-2014	4001.7 A/C HRS	as of 28-MAR-2023	_____ A/C HRS	as of ____/____/____
	6734 AFL	as of 28-MAR-2023	_____ AFL	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: PCE-VA0103/3076226-01 **MODEL:** PT6A-140 **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 05-FEB-2014	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS 0 A/C HRS	4001.7 ENG. HRS	as of 28-MAR-2023	_____ ENG. HRS	as of ____/____/____
0 ENC	6734 ENC	as of 28-MAR-2023	_____ ENC	as of ____/____/____

PROPELLER NO SERIAL/PART: BUA33576/HC-B3TN-3AF **MODEL:** HC-B3TN-3AF **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 30-SEP-2018	LAST ACTUALS		CURRENT ACTUAL	
320 PROP HRS 2643.5 A/C HRS	1676.9 PROP HRS	as of 28-MAR-2023	_____ PROP HRS	as of ____/____/____



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 208B-5098/RP-C1087							
EASA 2016-0044	ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL					MANDATORY	NOT APPLICABLE - NOT INSTALLED
		MOS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0044 PARA (1)	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N 57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1					MANDATORY	NOT APPLICABLE - NOT INSTALLED
		MOS		14-JAN-2019			
22-MAR-2016		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0044 PARA (2)	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1).					MANDATORY	NOT APPLICABLE - NOT INSTALLED
		MOS		14-JAN-2019			
22-MAR-2016		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0044 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REVISION 14, OR OF KG CMM 26-21-52 REVISION 13, AS APPLICABLE TO FIRE EXTINGUISHER P/N					MANDATORY	NOT APPLICABLE - NOT INSTALLED
		MOS		14-JAN-2019			
22-MAR-2016		HRS/MSC -		2994.6			
		AFL		5009			
FAA 1988-19-06	PREVENT POSSIBLE ELEVATOR FLUTTER					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.
		MOS		09-MAR-2014			
30-SEP-1988		HRS/MSC A/R		1.3			
		AFL		1			
FAA 1990-05-01	TO PREVENT FAILURE OF THE PART NUMBER (P/N) 2622083-18 BELLCRANK ASSEMBLY AND THE RESULTING UNEXPECTED RETRACTION OF THE FLAPS					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.
		MOS		09-MAR-2014			
05-MAR-1990		HRS/MSC A/R		1.3			
		AFL		1			
FAA 1990-05-04	TO PREVENT NOSE LANDING GEAR SHIMMY AND FAILURE OF THE ENGINE MOUNT RING					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.
		MOS		09-MAR-2014			
23-MAR-1990		HRS/MSC A/R		1.3			
		AFL		1			
FAA 1996-09-15	TO MINIMIZE THE POTENTIAL HAZARDS ASSOCIATED WITH OPERATING THE AIRPLANE IN SEVERE ICING CONDITIONS					MANDATORY	COMPLIED WITH - COMPLIED WITH BY AFM REVISION (SECTION 2)
		MOS		09-MAR-2014			
11-JUN-1996		HRS/MSC A/R		1.3			
		AFL		1			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 1997-01-13	TO PREVENT FUEL, OIL, OR HYDRAULIC SYSTEMS FAILURE CAUSED BY A COLLAPSED HOSE					MANDATORY	NOT APPLICABLE - SUBJECT PARTS NOT INSTALLED
03-FEB-1997		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 1997-25-04	POWER LEVER POSITIONING					MANDATORY	COMPLIED WITH - COMPLIED WITH BY AFM REVISION (SECTION 2)
		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2001-10-09	HONEYWELL KC225-FLGT CONTROL SYSTEM					MANDATORY	NOT APPLICABLE - HONEYWELL KC225 AUTOPILOT. PARTS NOT INSTALLED.
		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2004-08-17	STRUT ATTACMENT BOLTS AND NUTS					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.
17-MAY-2004		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2004-17-01	INSP FLAP BELLCRANK WELD					MANDATORY	NOT APPLICABLE - SUBJECT PARTS NOT INSTALLED.
		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2006-01-11 R01	DEICE BOOT/ASSIST HANDLE					MANDATORY	COMPLIED WITH - AD WAS INCORPORATED DURING PRODUCTION
		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2007-10-15	KNOWN ICING EQUIPMENT AFM SUPPLEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED ON ACFT.
		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2008-10-02	INSPECT THE ALTERNATE STATIC AIR SOURCE SELECTOR VALVE TO ASSURE THAT THE PART NUMBER IDENTIFICATION PLACARD IS NOT OBSTRUCTING THE PORT					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.
12-MAY-2008		MOS HRS/MSC AFL	-	09-MAR-2014 1.3 1			
FAA 2008-13-06	DETECT AND CORRECT DAMAGED WIRING OF THE AUTO-CONTROL WING DE-ICE SYSTEM, FUEL QUANTITY INDICATION, AND LOW FUEL ANNUNCIATION SYSTEMS					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.
		MOS HRS/MSC AFL	-	09-MAR-2014 1.3 1			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2008-26-10	INSPECT ALTERNATE STATIC AIR SOURCE SELECTOR VALVE FOR OBSTRUCTION BY PLACARD.					MANDATORY	NOT APPLICABLE - PER PARAGRAPH (C) OF THIS AD.
05-JAN-2009		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2009-05-12	MODIFY THE AILERON CARRY-THROUGH CABLE ATTACHMENT TO THE AILERON UPPER QUADRANT WITH PARTS OF IMPROVED DESIGN					MANDATORY	NOT APPLICABLE - PER PARAGRAPH (C) OF THIS AD.
		MOS HRS/MSC AFL	-	09-MAR-2014 1.3 1			
FAA 2009-10-14	IDENTIFICATION AND REMOVAL OF ALL PROPELLER BLADE COUNTERWEIGHT SLUG BOLTS, P/N B-3386-14H,					MANDATORY	NOT APPLICABLE - SUBJECT PARTS NOT INSTALLED
		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2009-15-05	MEASURE AND ADJUST AS NECESSARY, THE ROLL BRIDLE CABLE TENSION AND YAW BRIDLE CABLE TENSION, AND TORQUE THE 12 BRIDLE CABLE CLAMP SCREWS					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT IN SERIAL RANGE.
		MOS HRS/MSC AFL	-	09-MAR-2014 1.3 1			
FAA 2015-10-51	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS					MANDATORY	NOT APPLICABLE - NOT APPLICABLE
		MOS HRS/MSC AFL	-	02-SEP-2015 476.4 549			
FAA 2021-04-10	ELEVATOR STRUCTURE - TORQUE TUBE ATTACH FASTENERS - INSPECTION/REPLACEMENT					MANDATORY	
12-APR-2021		MOS HRS/MSC AFL	- (s)				
FAA 2021-04-10 PARA (G)	INSPECTION AND FASTENER REPLACEMENT					MANDATORY	
12-APR-2021		MOS HRS/MSC AFL	-	(EFF)			
FAA 2021-04-10 PARA (H)	FAA REPORTING REQUIREMENT					MANDATORY	
12-APR-2021		DAYS HRS/MSC AFL	- (s)				
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE - DUE TO DIFFERENT PART NO. AND VANE LESS THAN .125 INCH
		MOS HRS/MSC AFL	-	10-APR-2021 3781.6 6454			
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	NOT APPLICABLE - DUE TO DIFFERENT PART NO. AND NO CRACK FOUND
		MOS HRS/MSC AFL	-	10-APR-2021 3781.6 6454			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-23-12	INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	COMPLIED WITH
09-DEC-2021		MOS HRS/MSC - AFL		15-DEC-2021 3814.2 6497			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - 208B-5098/RP-C1087							
EASA 2006-0265-CN	APPLIANCE AD - CANCELLED: NAVIGATION SYSTEMS - MODE S AND C TRANSPONDERS - CHECK					CANCELLED	
17-APR-2013		MOS HRS/MSC - AFL					
EASA 2014-0187	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / REPLACEMENT			(EFF)		MANDATORY	
03-SEP-2014		MOS HRS/MSC - AFL					
EASA 2014-0187 PARA (1)	INSPECT THE SAFETY BELT ATTACHMENT BOLTS					MANDATORY	
03-SEP-2014		MOS HRS/MSC - AFL					
EASA 2014-0187 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DETACHED OR LOOSENED SAFETY BELT ATTACHMENT BOLTS ARE FOUND, BEFORE NEXT FLIGHT, RE-TORQUE THE AFFECTED BOLTS TO THE VALUE AS DEFINED IN, AND IN ACCORDANCE WITH THE INSTRUCTIONS OF, GEVEN SB NO. D103-25-004 REVISION 2.					MANDATORY	
03-SEP-2014		MOS HRS/MSC - AFL					
EASA 2014-0187 PARA (3)	FOR SPECIFIC D1-03 SEAT ASSEMBLIES (P/N AS IDENTIFIED IN TABLE 1.1.1 OF GEVEN SB NO. D103-25-004 REVISION 2, EFF CODE FROM AAA TO AUC), WITHIN 6 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY THE SEAT BELT ATTACHMENT ASSEMBLY ON THE AISLE SIDE SPREADER OF STANDARD AND LAST ROW SEATS IN ACCORDANCE WITH THE INSTRUCTIONS OF GEVEN SB NO. D103-25-004 REVISION 2.					MANDATORY	
03-SEP-2014		MOS HRS/MSC - AFL					
EASA 2014-0187 PARA (4)	AS AN ALTERNATIVE TO THE CORRECTIVE ACTIONS AS REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, BEFORE NEXT FLIGHT, BLOCK EACH AFFECTED SEAT FOR OCCUPANCY, PENDING ACCOMPLISHMENT OF THE APPLICABLE CORRECTIVE ACTION(S).					MANDATORY	
03-SEP-2014		MOS HRS/MSC - AFL					
EASA 2015-0093	APPLIANCE AD - NAVIGATION - ATTITUDE HEADING REFERENCE SYSTEM - MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - GARMNIN 1000 INUSE
10-JUN-2015		MOS HRS/MSC - AFL		14-JAN-2019 2994.6 5009			
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)					MANDATORY	NOT APPLICABLE - GARMNIN 1000 INUSE
10-JUN-2015		MOS HRS/MSC - AFL		14-JAN-2019 2994.6 5009			
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHSR UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD					MANDATORY	NOT APPLICABLE - GARMNIN 1000 INUSE
10-JUN-2015		MOS HRS/MSC - AFL		14-JAN-2019 2994.6 5009			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT					MANDATORY	NOT APPLICABLE - GARMNIN 1000 INUSE
10-JUN-2015		MOS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRN UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD					MANDATORY	NOT APPLICABLE - GARMNIN 1000 INUSE
10-JUN-2015		MOS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART					MANDATORY	NOT APPLICABLE
01-FEB-2016		DAYS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS		14-JAN-2019			
		HRS/MSC -		2994.6			
		AFL		5009			
FAA 1998-25-02	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS					MANDATORY	NOT APPLICABLE - AD 98-25-02 BF GOODRICH AVIONICS SYSTEMS, THIS AD IS NOT APPLICABLE DUE TO PARTS ARE NOT INSTALLED.
22-DEC-1998		MOS		09-MAR-2014			
		HRS/MSC A/R		1.3			
		AFL		1			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2005-01-19	APPLIANCE AD - GTX 33/33D/330/330D SOFTWARE UPGRADE					MANDATORY	NOT APPLICABLE - DUE TO LATER REVISION OF SOFTWARE INSTALLED IN THE GTX 33 TRANSPONDER.
23-FEB-2005		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2006-16-18 R01	APPLIANCE AD - SANDEL ST3400 TAWS/RMI PLACARD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED ON ACFT.
18-JUL-2008		MOS HRS/MSC AFL	A/R	09-MAR-2014 1.3 1			
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	
14-OCT-2014		MOS HRS/MSC AFL	-	(EFF)			
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.					MANDATORY	
18-MAY-2015		MOS HRS/MSC AFL	-				
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	
15-JUL-2016		MOS HRS/MSC AFL	-				
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE
15-JUL-2016		MOS HRS/MSC AFL	-	21-JUL-2016 922.8 1184			
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE
15-JUL-2016		MOS HRS/MSC AFL	-	21-JUL-2016 922.8 1184			
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - NO PBE INSTALLED.
15-JUL-2016		MOS HRS/MSC AFL	-	06-JUL-2017 1464.3 2146			
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016					MANDATORY	NOT APPLICABLE - SERIAL NUMBER INSTALLED IS 502525.
07-APR-2017		MOS HRS/MSC AFL	-	06-JUL-2017 1464.3 2146			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	
16-OCT-2017		MOS HRS/MSC - (s) AFL					
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	
16-OCT-2017		MOS HRS/MSC - (s) AFL					
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	
16-OCT-2017		MOS HRS/MSC - (s) AFL					
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	NOT APPLICABLE - NOT APPLICABLE DUE PBE NOT INSTALLED
16-OCT-2017		MOS HRS/MSC - AFL		26-OCT-2017 1742.5 2603			
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - DUE TO DIFFERENT PART NO. AND NO CRACK FOUND
11-MAY-2021		MOS HRS/MSC - AFL		10-APR-2021 3781.6 6454			
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE - DUE TO DIFFERENT PART NO. AND NO CRACK FOUND
11-MAY-2021		MOS HRS/MSC - AFL		10-APR-2021 3781.6 6454			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 208B-5098/RP-C1087							
COM ME-P-002	EXHAUST - MULTI-ENGINE PISTON COMMUNIQUE, COMMUNIQUE						
01-JAN-2018		MOS	HRS/MSC -	AFL			
COM SE-TP-002	SINGLE-ENGINE TURBOPROP COMMUNIQUÉ - MAIN LANDING GEAR (MLG) BUILDUP-SPARES ASSEMBLY , COMMUNIQUE						
01-JUL-2017		MOS	HRS/MSC -	AFL			
COM SE-TP-003	SINGLE ENGINE TURBOPROP COMMUNIQUE - TASK BASED INSPECTION PROGRAM CONVERSION, CARAVAN PTT SWITCH CAP REPLACEMENT, ROSEN SUNVISOR, COMMUNIQUE						
01-AUG-2017		MOS	HRS/MSC -	AFL			
COM SE-TP-004	SINGLE-ENGINE TURBOPROP COMMUNIQUÉ - (AFFECTS MULTIPLE SYSTEMS/SUBSYSTEMS), COMMUNIQUE						COMPLIED WITH
01-DEC-2018		MOS	HRS/MSC -	AFL	20-JAN-2019 3014.6 5053		
COM SE-TP-007	INSPECTION PROGRAMS / BASE SOFTWARE CARDS AND SOFTWARE UNLOCK CARDS, COMMUNIQUE						
01-APR-2020		MOS	HRS/MSC -	AFL	(EFF)		
SB CAB-21-03	AIR CONDITIONING - R134A AIR CONDITIONER SYSTEM INSTALLATION FOR AIRPLANES EQUIPPED WITH G1000 AND 675 SHP ENGINE, SERVICE BULLETIN					OPTIONAL	
31-MAY-2017		MOS	HRS/MSC -	AFL			
SB CAB-21-04	AIR CONDITIONING - R134A AIR CONDITIONER SYSTEM INSTALLATION FOR AIRPLANES EQUIPPED WITH G1000 AND 867 SHP ENGINE, SERVICE BULLETIN					OPTIONAL	
01-JUN-2017		MOS	HRS/MSC -	AFL			
SB CAB-21-05	AIR CONDITIONING - REPLACEMENT OF P3 HEATER (FLOW) CONTROL VALVE, SERVICE BULLETIN					OPTIONAL	
13-APR-2017		MOS	HRS/MSC -	AFL			
SB CAB-21-06	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR DRIVE BELT INSTALLATION, SERVICE BULLETIN					OPTIONAL	
10-AUG-2022		MOS	HRS/MSC -	AFL			
SB CAB-24-02	ELECTRICAL POWER - GENERATOR CONTROL UNIT (GCU) WIRING IMPROVEMENTS, SERVICE BULLETIN					OPTIONAL	
09-AUG-2018		MOS	HRS/MSC -	AFL			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB CAB-24-04	ELECTRICAL POWER - PLACARD INSTALLATION FOR STANDBY ALTERNATOR, SERVICE BULLETIN					RECOMMENDED	
		MOS		(EFF)			
	01-OCT-2020	HRS/MSC -					
		AFL					
SB CAB-25-03	EQUIPMENT/FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER ELT 1000 INSTALLATION, SERVICE BULLETIN					OPTIONAL	
		MOS					
	12-MAY-2022	HRS/MSC -					
		AFL					
SB CAB-26-01	FIRE PROTECTION - REPLACEMENT OF THE HALON TYPE 1211 PORTABLE FIRE EXTINGUISHERS, SERVICE BULLETIN					OPTIONAL	
		MOS					
	10-JUN-2022	HRS/MSC -					
		AFL					
SB CAB-27-01	RUDDER TRIM INSPECTION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - NOT APPLICABLE
		MOS		01-MAY-2015			
	09-FEB-2015	HRS/MSC -		364.9			
		AFL		401			
SB CAB-27-03	FLIGHT CONTROLS - INSPECTION OF AILERON CABLE INTERFERENCE, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - C/OUT FLIGHT CONTROLS - INSPECTION OF AILERON CABLE INTERFERENCE IAW SB CAB 27-03 , SATISFACTORY
		MOS		02-SEP-2016			
	04-AUG-2016	HRS/MSC -		985.4			
		AFL		1283			
SB CAB-27-05	FLIGHT CONTROLS - FLAP FOLLOW-UP BARREL WASHER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS		(EFF)			
	05-JUN-2018	HRS/MSC -					
		AFL					
SB CAB-27-06	FLIGHT CONTROLS - ELEVATOR TORQUE TUBE INSPECTION FOR LOOSE RIVETS, SERVICE BULLETIN						
		MOS					
	14-OCT-2019	HRS/MSC -					
		AFL					
SB CAB-30-03	TKS FILL CAP PLACARD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - NOT APPLICABLE
		MOS		02-SEP-2015			
	10-SEP-2014	HRS/MSC -		476.4			
		AFL		549			
SB CAB-30-05 R01	SINGLE FILTER ELEMENT FOR TKS AIRCRAFT, SERVICE BULLETIN					OPTIONAL	
		MOS					
	03-MAR-2015	HRS/MSC -					
		AFL					
SB CAB-30-07	TKS ICE WARNING PLACARD REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - NOT APPLICABLE
		MOS		02-SEP-2015			
	10-SEP-2014	HRS/MSC -		476.4			
		AFL		549			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB CAB-31-01	INDICATING / RECORDING SYSTEMS - CVDR INSTALLATION (SUPERSEDED BY CAB-31-01 R01), SERVICE BULLETIN					OPTIONAL	
	21-OCT-2015	MOS	HRS/MSC -				
		AFL					
SB CAB-31-01 R01	INDICATING/RECORDING SYSTEMS - CVDR INSTALLATION (SUPERSEDED BY CAB-31-01 R02), SERVICE BULLETIN					OPTIONAL	
	14-AUG-2017	MOS	HRS/MSC -				
		AFL					
SB CAB-31-01 R02	INDICATING/RECORDING SYSTEMS - CVDR INSTALLATION, SERVICE BULLETIN					OPTIONAL	
	06-MAY-2019	MOS	HRS/MSC -				
		AFL					
SB CAB-32-04	LANDING GEAR - MAIN LANDING GEAR TRUNNION AND FAIRING INSPECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
	11-JAN-2016	MOS		16-JAN-2017			
		HRS/MSC -		1125.6			
		AFL		1607			
SB CAB-32-05	LANDING GEAR - NOSE LANDING GEAR FAIRING INSPECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
	15-SEP-2016	MOS		14-APR-2017			
		HRS/MSC -		1219.6			
		AFL		1750			
SB CAB-33-01	LIGHTS - LED BEACON INSTALLATION, SERVICE BULLETIN					OPTIONAL	
	15-JAN-2021	MOS	HRS/MSC -				
		AFL					
SB CAB-33-02	LIGHTS - LED NAVIGATION AND ANTI-COLLISION LIGHT ASSEMBLIES INSTALLATION, SERVICE BULLETIN					OPTIONAL	
	09-MAR-2020	MOS	HRS/MSC -				
		AFL					
SB CAB-33-04	LIGHTS - LED LANDING AND TAXI RECOGNITION LIGHT INSTALLATION, SERVICE BULLETIN					OPTIONAL	
	15-JAN-2021	MOS	HRS/MSC -				
		AFL					
SB CAB-33-05	LIGHTS - LED COURTESY LIGHT INSTALLATION, SERVICE BULLETIN					OPTIONAL	
	15-JAN-2021	MOS	HRS/MSC -				
		AFL					
SB CAB-33-06	LIGHTS - LED WING INSPECTION LIGHT INSTALLATION, SERVICE BULLETIN					OPTIONAL	
	15-JAN-2021	MOS	HRS/MSC -				
		AFL					
SB CAB-33-07	LIGHTS - LED NAV/ANTI-COLLISION LIGHT WIRING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
	25-MAR-2020	MOS		(EFF)			
		HRS/MSC -					
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB CAB-34-03	NAVIGATION - GARMIN G 1000 SYSTEM SOFTWARE UPGRADE TO VERSION 0767.23, SERVICE BULLETIN					RECOMMENDED	DECLINED
		MOS		10-APR-2018			
	01-NOV-2016	HRS/MSC -		2193.9			
		AFL		3361			
SB CAB-34-03 R01	NAVIGATION - GARMIN G1000 SYSTEM SOFTWARE UPGRADE TO VERSION 0767.25, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	08-JAN-2019	HRS/MSC -					
		AFL					
SB CAB-34-04	NAVIGATION - GARMIN G1000 ADS-B OUT ACTIVATION, SERVICE BULLETIN					OPTIONAL	
		MOS					
	09-NOV-2016	HRS/MSC -					
		AFL					
SB CAB-34-04 R01	NAVIGATION - GARMIN G1000 ADS-B OUT ACTIVATION, SERVICE BULLETIN					OPTIONAL	
		MOS					
	08-JAN-2019	HRS/MSC -					
		AFL					
SB CAB-34-06	NAVIGATION - INSTALL KRA-405B RADAR ALTIMETER, SERVICE BULLETIN					OPTIONAL	
		MOS					
	17-NOV-2016	HRS/MSC -					
		AFL					
SB CAB-34-11	NAVIGATION - STALL WARNING HORN REPLACEMENT, SERVICE BULLETIN						
		MOS					
	25-MAY-2021	HRS/MSC -					
		AFL					
SB CAB-36-01	PNEUMATIC - VENTILATION AND DRAINAGE IMPROVEMENTS - TAILCONE (SUPERSEDED BY CAB-36-01 R01), SERVICE BULLETIN					OPTIONAL	
		MOS					
	15-DEC-2016	HRS/MSC -					
		AFL					
SB CAB-36-01 R01	PNEUMATIC - VENTILATION AND DRAINAGE IMPROVEMENTS - TAILCONE, SERVICE BULLETIN					OPTIONAL	
		MOS					
	28-JUL-2017	HRS/MSC -					
		AFL					
SB CAB-55-01	STABILIZERS - INSPECTION / MODIFICATION OF GAP BETWEEN VERTICAL FORWARD SPAR CAPS AND CANTED BULKHEAD, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		22-SEP-2015			
	09-SEP-2015	HRS/MSC -		479.5			
		AFL		555			
SB CAB-57-02	SPAR FITTING AND ATTACH BRACKET INSPECTION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		24-AUG-2015			
		HRS/MSC -		476.4			
		AFL		549			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB CAB-77-01	FAST ENGINE TREND MONITORING INSTALLATION FOR AIRPLANES WITH PROVISIONS (SUPERSEDED BY CAB-77-01 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - HAWKER PACIFIC ASIA PTE. LTD
09-JUN-2014		MOS		21-MAY-2015			
		HRS/MSC -		403.3			
		AFL		455			
SB CAB-77-01 R01	ENGINE INDICATING - FAST ENGINE TREND MONITORING INSTALLATION FOR AIRPLANES WITH PROVISIONS, SERVICE BULLETIN					RECOMMENDED	
01-JUN-2018		MOS					
		HRS/MSC -					
		AFL					
SB CAB-77-02	ENGINE INDICATING - NEW CONFIGURATION FILE FOR ADAS SYSTEMS, SERVICE BULLETIN					OPTIONAL	
18-FEB-2016		MOS					
		HRS/MSC -					
		AFL					
SB CAB-77-03	ENGINE INDICATING - FAST HARDWARE AND SOFTWARE UPDATE FOR 4G NETWORK CONNECTIVITY, SERVICE BULLETIN					OPTIONAL	
17-AUG-2021		MOS					
		HRS/MSC -					
		AFL					
SB CAB-78-02	EXHAUST - HANGER BRACKET LOCATIONS, SERVICE BULLETIN					RECOMMENDED	
17-OCT-2017		MOS					
		HRS/MSC -					
		AFL					
SB CAB-80-01	300 AMPERE STARTER/GENERATOR INSTALLATION FOR 208B EX (867SHP) AIRPLANES, SERVICE BULLETIN					OPTIONAL	
27-OCT-2014		MOS					
		HRS/MSC -					
		AFL					
SB CAB09-11 R01	GARMIN G1000 AVIONICS CHARTVIEW OPTION, SERVICE BULLETIN					OPTIONAL	
08-FEB-2022		MOS					
		HRS/MSC -					
		AFL					
SB CAB09-7 R01	GARMIN G1000 SYNTHETIC VISION INSTALLATION FOR AIRPLANES NOT EQUIPPED WITH NXI, SERVICE BULLETIN					OPTIONAL	
08-FEB-2022		MOS					
		HRS/MSC -					
		AFL					
SB CAB11-5 R01	TIME LIMITS/MAINTENANCE CHECKS - NEW 208/208B TASK-BASED INSPECTION PROGRAM, SERVICE BULLETIN					OPTIONAL	
16-MAY-2014		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB CAB11-5 R02	TIME LIMITS/MAINTENANCE CHECKS - NEW 208/208B TASK-BASED INSPECTION PROGRAM, SERVICE BULLETIN					OPTIONAL	
20-MAR-2020		MOS					
		HRS/MSC -					
		AFL					



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CAL-05-01	TASK-BASED INSPECTION PROGRAM - TASK 0A FOR 14CFR PART 91.409 (A) AND (B), SERVICE LETTER					INFORMATIONAL	
	03-OCT-2014	MOS	HRS/MSC -				
			AFL				
SL CAL-05-01 R01	TIME LIMITS/MAINTENANCE CHECKS - INSPECTION DOCUMENT 0A FOR 14 CFR PART 91.409 (A) AND (B), SERVICE LETTER					INFORMATIONAL	
	17-MAR-2020	MOS	HRS/MSC -				
			AFL				
SL CAL-05-02	TIME LIMITS/MAINTENANCE CHECKS - NEW C100490-1 OIL COOLER CHECK VALVE (CHECK VALVE ASSEMBLY REPAIR) RESTORATION INTERVAL IMPLEMENTATION GRACE PERIOD, SERVICE LETTER					INFORMATIONAL	
	09-MAY-2019	MOS	HRS/MSC -	(EFF)			
			AFL				
SL CAL-12-02	SERVICING - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN P&WC S.B. NO. 1001R29, SERVICE LETTER					INFORMATIONAL	
	04-AUG-2014	MOS	HRS/MSC -				
			AFL				
SL CAL-20-01	LISTING OF NONDESTRUCTIVE TESTING FACILITIES, SERVICE LETTER					INFORMATIONAL	
	09-OCT-2014	MOS	HRS/MSC -				
			AFL				
SL CAL-24-03	ELECTRICAL POWER - SUPPLEMENTS TO ADDRESS ELECTRICAL REQUIREMENTS FOR OPERATION OF SINGLE-ENGINE PASSENGER-CARRYING AIRCRAFT FOR COMPENSATION OR HIRE, SERVICE LETTER					INFORMATIONAL	
	23-DEC-2015	MOS	HRS/MSC -				
			AFL				
SL CAL-24-04	ELECTRICAL POWER - INSPECT ELECTRICAL GROUND STUDS IN THE ENGINE COMPARTMENT FOR CORRECT PAINT AND SEALANT APPLICATION, SERVICE LETTER					RECOMMENDED	
	27-FEB-2020	MOS	HRS/MSC -				
			AFL				
SL CAL-24-05	ELECTRICAL POWER - WIRE BUNDLE ID TAG INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
	25-MAY-2021	MOS	HRS/MSC -	13-JUN-2021			
			AFL	3790			
				6464			
SL CAL-25-02	EQUIPMENT/FURNISHINGS - CREW SEAT FRAME INSPECTION AND WELD REPAIR, SERVICE LETTER					RECOMMENDED	
	02-OCT-2020	MOS	HRS/MSC -				
			AFL				
SL CAL-27-05	FLIGHT CONTROLS - ELEVATOR PRE-FLIGHT CHECK FOR FREE PLAY, SERVICE LETTER					INFORMATIONAL	
	11-AUG-2017	MOS	HRS/MSC -				
			AFL				



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CAL-27-06	FLIGHT CONTROLS - INSTALL MISSING CATERPILLAR GROMMETS IN THE BULKHEAD CUTOUTS, SERVICE LETTER					RECOMMENDED	
11-JAN-2019		MOS HRS/MSC - AFL					
SL CAL-27-07	FLIGHT CONTROLS - REPLACE AILERON TRIM TAB PUSHROD ASSEMBLIES, SERVICE LETTER			(EFF)		MANDATORY	
10-JAN-2019		MOS HRS/MSC - AFL					
SL CAL-27-07 R01	FLIGHT CONTROLS - REPLACE AILERON TRIM TAB PUSHROD ASSEMBLIES, SERVICE LETTER					MANDATORY	
08-FEB-2019		MOS HRS/MSC - AFL					
SL CAL-27-09	FLIGHT CONTROLS - REMOVE AND REINSTALL INVERTED LEFT AILERON TRIM TAB PUSHRODS, SERVICE LETTER					RECOMMENDED	
17-SEP-2019		MOS HRS/MSC - AFL					
SL CAL-27-10	FLIGHT CONTROLS - INSPECTION OF THE ELEVATOR UP TRAVEL RIGGING, SERVICE LETTER					MANDATORY	
15-AUG-2019		MOS HRS/MSC - AFL					
SL CAL-28-01	FUEL - INSPECTION / REPLACEMENT OF LEFT LOW FUEL LEVEL SWITCH COVER ASSEMBLY (SUPERSEDED BY CAL-28-01 R01), SERVICE LETTER					MANDATORY	COMPLIED WITH - NEXT DUE WILL BE NOVEMBER 2016
12-NOV-2015		MOS HRS/MSC - AFL		12-JAN-2016 713.9 884			
SL CAL-28-01 R01	FUEL - INSPECTION/ REPLACEMENT OF LEFT LOW FUEL LEVEL SWITCH COVER ASSEMBLY, SERVICE LETTER					MANDATORY	COMPLIED WITH - C/OUT INSP. IAW SL CAL-28-01 R1 FUEL INSPECTION / REPLACEMENT OF LEFT LOW FUEL LEVEL SWITCH COVER ASSEMBLY. SATISFACTORY
12-JAN-2016		MOS HRS/MSC - AFL		11-AUG-2017 713.9 884			
SL CAL-28-02	FUEL - FUEL LINE COVER ASSEMBLIES SEALANT INSPECTION, SERVICE LETTER					MANDATORY	
12-FEB-2016		MOS HRS/MSC - AFL					
SL CAL-30-01 R03	ICE AND RAIN PROTECTION - TRANSMITTAL OF CAV AEROSPACE SERVICE LETTER SL 13120-10-30-001 CESSNA 208B CARAVAN TKS ICE PROTECTION SYSTEM FILTER ELEMENT REPLACEMENT (SUPERSEDED BY CAL-30-01 R04), SERVICE LETTER					INFORMATIONAL	
30-AUG-2018		MOS HRS/MSC - AFL					
SL CAL-30-01 R04	ICE AND RAIN PROTECTION - TRANSMITTAL OF CAV AEROSPACE SERVICE LETTER SL 13120-10-30-001 CESSNA 208B CARAVAN TKS ICE PROTECTION SYSTEM FILTER ELEMENT REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
25-SEP-2018		MOS HRS/MSC - AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CAL-30-02	ICE AND RAIN PROTECTION - TRAVEL TUBE BRACKET WELDMENT REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
	22-OCT-2015	HRS/MSC -					
		AFL					
SL CAL-32-02	TRANSMITTAL OF PARKER SERVICE BULLETIN SB7105, SERVICE LETTER					INFORMATIONAL	
		MOS					
	14-MAY-2015	HRS/MSC -					
		AFL					
SL CAL-32-04	LANDING GEAR - BRAKE CYLINDER INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - SATISFACTORY.
		MOS		03-FEB-2022			
	25-JAN-2022	HRS/MSC -		3854.6			
		AFL		6539			
SL CAL-33-01	LIGHTS - FERRULE INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
	10-AUG-2020	HRS/MSC -					
		AFL					
SL CAL-34-02	NAVIGATION - REPLACEMENT OF NONCONFORMING DIAPHRAGM ASSEMBLIES IN AFFECTED ALTIMETERS, SERVICE LETTER					MANDATORY	NOT APPLICABLE
		MOS		13-JUN-2017			
	15-SEP-2016	HRS/MSC -		1403			
		AFL		2043			
SL CAL-34-03	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL (SUPERSEDED BY CAL-34-03 R01), SERVICE LETTER					INFORMATIONAL	
		MOS					
	04-AUG-2016	HRS/MSC -					
		AFL					
SL CAL-34-03 R01	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL, SERVICE LETTER					INFORMATIONAL	
		MOS					
	26-SEP-2016	HRS/MSC -					
		AFL					
SL CAL-34-03 R02	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 1612 REVISION E, 2020 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL, SERVICE LETTER					INFORMATIONAL	
		MOS					
	25-JAN-2021	HRS/MSC -					
		AFL					
SL CAL-34-03 R03	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 1612 REVISION F, 2020 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL, SERVICE LETTER					INFORMATIONAL	
		MOS					
	24-MAY-2021	HRS/MSC -					
		AFL					
SL CAL-34-04	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS), SERVICE LETTER					INFORMATIONAL	
		MOS					
	19-JAN-2021	HRS/MSC -					
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CAL-35-01	OXYGEN - ALTITUDE COMPENSATED REGULATOR INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - DUE TO NON OXYGEN SYSTEM INSTALLED
		MOS		02-DEC-2014			
	19-SEP-2014	HRS/MSC -		132.6			
		AFL		103			
SL CAL-35-01 PART A	PERFORM OXYGEN - ALTITUDE COMPENSATED REGULATOR INSPECTION, SERVICE LETTER THE OPERATIONAL TEST OF THE ALTITUDE COMPENSATED REGULATOR(S)					MANDATORY	NOT APPLICABLE - DUE TO NON OXYGEN SYSTEM INSTALLED
		MOS		02-DEC-2014			
	19-SEP-2014	HRS/MSC -		132.6			
		AFL		103			
SL CAL-35-01 PART B	INSPECTION OXYGEN - ALTITUDE COMPENSATED REGULATOR INSPECTION, SERVICE LETTER OF THE ALTITUDE COMPENSATED REGULATOR(S)					MANDATORY	NOT APPLICABLE - DUE TO NON OXYGEN SYSTEM INSTALLED
		MOS		02-DEC-2014			
	19-SEP-2014	HRS/MSC -		132.6			
		AFL		103			
SL CAL-57-03	WINGS - IDENTIFICATION PLATE INSPECTION/REPLACEMENT (SUPERSEDED BY CAL-57-03 R01), SERVICE LETTER					MANDATORY	NOT APPLICABLE
		MOS		13-JUN-2017			
	23-MAY-2017	HRS/MSC -		1403			
		AFL		2043			
SL CAL-57-03 R01	WINGS - IDENTIFICATION PLATE INSPECTION/REPLACEMENT, SERVICE LETTER					MANDATORY	
		MOS					
	30-OCT-2018	HRS/MSC -					
		AFL					
SL CAL-57-04	WINGS - CORRECT IMPROPERLY TORQUED AFT SPAR ATTACH BOLTS, SERVICE LETTER					MANDATORY	
		MOS					
	21-MAY-2019	HRS/MSC -					
		AFL					
SL CAL-61-02	PROPELLER - INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - PERFORMED PROPELLER - INSPECTION, SERVICE LETTER SLCAL-61-02 PROVIDES PARTS AND INSTRUCTIONS TO DO AN INSPECTION OF THE PROPELLER MOUNTING BOLT WASHERS.
		MOS		06-NOV-2014			
	18-JUN-2014	HRS/MSC -		122.9			
		AFL		90			
SL CAL-61-03	PROPELLER - MCCAULEY TKS NOZZLE BRACKET INSPECTION/REPLACEMENT, SERVICE LETTER					MANDATORY	
		MOS					
	14-NOV-2019	HRS/MSC -					
		AFL					
SL CAL-61-04	PROPELLER - B-40755A SPRAY HEAD ASSEMBLY REPLACEMENT, SERVICE LETTER					MANDATORY	
		MOS					
	02-JUN-2020	HRS/MSC -					
		AFL					
SL CAL-61-05	PROPELLER - TRANSMITTAL OF MCCAULEY SERVICE LETTER SL2022-1 MCCAULEY B-6422 AND B-4743 ACTUATING LINK ASSEMBLY INSPECTION, SERVICE LETTER					MANDATORY	
		MOS	12	(EFF)	16-AUG-2023		
	16-AUG-2022	HRS/MSC	100/DUE		4076.4		
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CAL-71-12	TRANSMITTAL OF P&WC S.I.L. NO. PT6A-196R1, S.I.L. NO. GEN-123R2, S.I.L. NO. GEN-134, PT6A SPB NO. 185, PT6A SPB NO. 186, S.B. NO. 1002R29, S.B. NO. 1455R3, S.B. NO. 1521R5, S.B. NO. 1568R7, S.B. NO. 1588R2, S.B. NO. 1731, S.B. NO. 1733, SERVICE LETTER					INFORMATIONAL	
26-MAR-2014		MOS					
		HRS/MSC	-				
		AFL					
SL CAL-71-13	TRANSMITTAL OF P&WC S.I.L. NO. GEN-PT6-034, S.B. NO. 1447R4, S.B. NO. 1703R10, S.B. NO. 1705R1, S.B. NO. 1722R1, S.B. NO. 1729, S.B. NO. 1737, SERVICE LETTER					INFORMATIONAL	
09-JUN-2014		MOS					
		HRS/MSC	-				
		AFL					
SL CAL-71-14	POWER PLANT - TRANSMITTAL OF P&WC S.I.L. NO. PT6A-221, SERVICE LETTER					INFORMATIONAL	
15-SEP-2014		MOS					
		HRS/MSC	-				
		AFL					
SL CAL-71-15	ENGINE MOUNT INSPECTION FOR SUFFICIENT PAINT COVERAGE, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
06-MAR-2015		MOS		02-SEP-2015			
		HRS/MSC	-	476.4			
		AFL		549			
SL CAL-71-16	POWER PLANT - INSPECT THE INERTIAL SEPARATOR ROD FOR PROPER CLEARANCE AND REPLACE THE SPACER IF CHAFING IS FOUND, SERVICE LETTER					RECOMMENDED	
21-MAY-2019		MOS					
		HRS/MSC	-				
		AFL					
SL CAL-71-17	POWER PLANT - INSPECT FOR PROPER CLEARANCE BETWEEN THE ENGINE MOUNT AND THE RIGHT FIREWALL FLANGE, SERVICE LETTER					RECOMMENDED	
10-APR-2019		MOS					
		HRS/MSC	-				
		AFL					
SL CAL-73-05	TRANSMITTAL OF P&WC S.B. NO. 1748, SERVICE LETTER					INFORMATIONAL	
13-AUG-2014		MOS					
		HRS/MSC	-				
		AFL					
SL CAL-73-06	FUEL NOZZLE TIP ASSEMBLY REPLACEMENT, SERVICE LETTER					RECOMMENDED	
22-MAY-2015		MOS					
		HRS/MSC	-				
		AFL					
SL CAL-77-01	INSPECTION OF THE PRESSURE LINE AND VENT LINE FOR THE TORQUE INDICATOR GAUGE, SERVICE LETTER					MANDATORY	COMPLIED WITH
04-DEC-2014		MOS		22-MAY-2015			
		HRS/MSC	-	403.3			
		AFL		455			
SL CAL-77-02	ENGINE INDICATING - FAST HARDWARE AND SOFTWARE UPDATE AVAILABLE FOR 3G NETWORK CONNECTIVITY, SERVICE LETTER					OPTIONAL	
04-JUN-2018		MOS					
		HRS/MSC	-				
		AFL					



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CAL-79-01	OIL - C100490-1 OIL COOLER SYSTEM CHECK VALVE ASSEMBLY REPAIR KIT INSTALLATION, SERVICE LETTER					OPTIONAL	
		MOS					
	09-MAY-2019	HRS/MSC -					
		AFL					
SL CAL-79-02 R01	INTRODUCTION OF OIL - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PT6A-72-1811 - TURBOPROP ENGINE SCAVENGE-PUMP DRIVE-SHAFT PLUG, SERVICE LETTER					RECOMMENDED	
		MOS					
	14-APR-2022	HRS/MSC -					
		AFL					
SL CAL-99-01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW, SERVICE LETTER					INFORMATIONAL	
		MOS					
	29-JAN-2016	HRS/MSC -					
		AFL					
SL SEL-20-01	LISTING OF NONDESTRUCTIVE TESTING FACILITIES, SERVICE LETTER					INFORMATIONAL	
		MOS					
	07-OCT-2014	HRS/MSC -					
		AFL					
SL SEL-20-01 R01	LISTING OF NONDESTRUCTIVE TESTING FACILITIES, SERVICE LETTER					INFORMATIONAL	
		MOS					
	22-OCT-2014	HRS/MSC -					
		AFL					
SL SEL-61-01	PROPELLER GOVERNOR INSPECTION IN ACCORDANCE WITH MCCAULEY ASB273, SERVICE LETTER					MANDATORY	NOT APPLICABLE
		MOS		22-MAR-2021			
	16-NOV-2018	HRS/MSC -		3753.6			
		AFL		6381			
STC SA02080AK-D	EXHAUST DEFLECTOR - AERO TWIN, SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH - INSTALLED AERO TWIN EXHAUST DEFLECTOR P/N ED8-100 PER STC SA02080AK-D. INSTALLATION WAS INCORPORATED DURING PRODUCTION.
		MOS		09-MAR-2014			
		HRS/MSC -		1.3			
		AFL		1			
STC SA3649NM	FABRICATION AND INSTALLATION OF AERO TWIN, INC. RUDDER GUST LOCK KIT NO. AT-RL-1001., SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH - STC SA3649NM, AERO TWIN RUDDER GUST LOCK KIT, P/N AT-RL-1001 WAS INCORPORATED DURING PRODUCTION.
		MOS		09-MAR-2014			
		HRS/MSC -		1.3			
		AFL		1			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - PCE-VA0103/3076226-01							
SB	PT6A-72-1001 R29	NO. 1 ENGINE - APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY PT6A-72-1001 R30), SERVICE BULLETIN					
	08-JUL-2014	MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB	PT6A-72-1001 R30	NO. 1 ENGINE - APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN					
	20-MAR-2015	MOS					
		HRS/MSC -					
		ENC					
SB	PT6A-72-1447 R04	NO. 1 ENGINE - MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT (SUPERSEDED BY PT6A-72-1447 R05), SERVICE BULLETIN					
	21-FEB-2014	MOS					
		HRS/MSC -					
		ENC					
SB	PT6A-72-1447 R05	NO. 1 ENGINE - MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT (SUPERSEDED BY PT6A-72-1447 R06), SERVICE BULLETIN					
	23-DEC-2014	MOS					
		HRS/MSC -					
		ENC					
SB	PT6A-72-1447 R06	NO. 1 ENGINE - MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT, SERVICE BULLETIN					
	27-MAY-2016	MOS					
		HRS/MSC -					
		ENC					
SB	PT6A-72-1701	NO. 1 ENGINE - REPLACEMENT OF FUEL NOZZLE SHEATH (SUPERSEDED BY PT6A-72-1701 R01), SERVICE BULLETIN					
	08-FEB-2017	MOS					
		HRS/MSC -					
		ENC					
SB	PT6A-72-1701 R01	NO. 1 ENGINE - REPLACEMENT OF FUEL NOZZLE SHEATH, SERVICE BULLETIN					
	06-MAR-2017	MOS					
		HRS/MSC -					
		ENC					
SB	PT6A-72-1701 R02	NO. 1 ENGINE - REPLACEMENT OF FUEL NOZZLE SHEATH, SERVICE BULLETIN				CATEGORY 9	
	29-DEC-2021	MOS					
		HRS/MSC -					
		ENC					
SB	PT6A-72-1710	NO. 1 ENGINE - REPLACEMENT OF SINGLE PORT TURBINE EXHAUST DUCT ASSEMBLY, SERVICE BULLETIN					
	14-FEB-2017	MOS					
		HRS/MSC -					
		ENC					
SB	PT6A-72-1715	NO. 1 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (FOHE), SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
	03-MAY-2013	MOS		05-FEB-2014			
		HRS/MSC -					
		ENC					



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-1717	NO. 1 ENGINE - MODIFICATION/ REPLACEMENT OF FIRST STAGE CARRIER BALANCING ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
25-SEP-2013		MOS		05-FEB-2014			
		HRS/MSC -		0			
		ENC		0			
SB PT6A-72-1718	NO. 1 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (FOHE), SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
12-JUL-2013		MOS		05-FEB-2014			
		HRS/MSC -		0			
		ENC		0			
SB PT6A-72-1720 R01	NO. 1 ENGINE - REPLACEMENT OF MOTIVE FLOW SOLENOID VALVE ((SUPERSEDED BY PT6A-72-1420 R02), SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
13-JUN-2013		MOS		05-FEB-2014			
		HRS/MSC -		0			
		ENC		0			
SB PT6A-72-1720 R02	NO. 1 ENGINE - REPLACEMENT OF MOTIVE FLOW SOLENOID VALVE, SERVICE BULLETIN						
22-DEC-2015		MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-1721 R01	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE DISK, SERVICE BULLETIN					CATEGORY 3	
05-SEP-2017		MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-1723	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN						
15-OCT-2014		MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-1724 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FUEL/OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PT6A-72-1724 R03), SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
18-NOV-2013		MOS		05-FEB-2014			
		HRS/MSC -		0			
		ENC		0			
SB PT6A-72-1724 R03	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FUEL/OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PT6A-72-1724 R04), SERVICE BULLETIN						
18-AUG-2016		MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-1724 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FUEL/OIL HEAT EXCHANGER (FOHE), SERVICE BULLETIN					CATEGORY 5	
13-NOV-2017		MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-1725 R01	NO. 1 ENGINE - REPLACEMENT OF FUEL FILTER IMPENDING BYPASS INDICATOR, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
06-NOV-2013		MOS		05-FEB-2014			
		HRS/MSC -		0			
		ENC		0			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-1730	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SHROUD HOUSING, SERVICE BULLETIN						
	17-APR-2015	MOS	HRS/MSC -	ENC			
SB PT6A-72-1733 R01	NO. 1 ENGINE - INSPECTION OF TORQUE LIMITER, SERVICE BULLETIN						COMPLIED WITH
	27-JAN-2015	MOS	HRS/MSC -	ENC	30-JAN-2015 163.4 154		
SB PT6A-72-1735	NO. 1 ENGINE - REPLACEMENT OF REAR REDUCTION GEARBOX HOUSING, SERVICE BULLETIN						
	24-APR-2014	MOS	HRS/MSC -	ENC			
SB PT6A-72-1736	NO. 1 ENGINE - INTRODUCTION OF FUEL AND OIL TEMPERATURE SENSOR (SUPERSEDED BY PT6A-72-1736 R01), SERVICE BULLETIN						
	20-MAR-2015	MOS	HRS/MSC -	ENC			
SB PT6A-72-1736 R01	NO. 1 ENGINE - INTRODUCTION OF FUEL AND OIL TEMPERATURE SENSOR (SUPERSEDED BY PT6A-72-1736 R02), SERVICE BULLETIN						
	18-AUG-2016	MOS	HRS/MSC -	ENC			
SB PT6A-72-1736 R02	NO. 1 ENGINE - INTRODUCTION OF FUEL AND OIL TEMPERATURE SENSOR, SERVICE BULLETIN						CATEGORY 5
	05-SEP-2017	MOS	HRS/MSC -	ENC			
SB PT6A-72-1736 R03	NO. 1 ENGINE - INTRODUCTION OF FUEL AND OIL TEMPERATURE SENSOR, SERVICE BULLETIN						CATEGORY 5
	09-JAN-2019	MOS	HRS/MSC -	ENC			
SB PT6A-72-1737	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SINGLE PORT TURBINE EXHAUST DUCT ASSEMBLY (SUPERSEDED BY PT6A-72-1737 R01), SERVICE BULLETIN						
		MOS	HRS/MSC -	ENC			
SB PT6A-72-1737 R01	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF SINGLE PORT TURBINE EXHAUST DUCT ASSEMBLY, SERVICE BULLETIN						CATEGORY 3
	07-SEP-2017	MOS	HRS/MSC -	ENC			
SB PT6A-72-1737 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SINGLE PORT TURBINE EXHAUST DUCT ASSEMBLY, SERVICE BULLETIN						CATEGORY 6
	05-JAN-2018	MOS	HRS/MSC -	ENC			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-1740	NO. 1 ENGINE - REPLACEMENT OF PROPELLER OVERSPEED GOVERNOR, SERVICE BULLETIN						
	24-APR-2014	MOS	HRS/MSC -	ENC			
SB PT6A-72-1743	NO. 1 ENGINE - CONVERSION OF PT6A-140 (BS1294) ENGINE TO PT6A-140 (BS1342) ENGINE, SERVICE BULLETIN						
	23-DEC-2014	MOS	HRS/MSC -	ENC			
SB PT6A-72-1750	NO. 1 ENGINE - REPLACEMENT OF FUEL FILTER IMPENDING BYPASS INDICATOR PREFORMED PACKINGS, SERVICE BULLETIN						
	12-NOV-2014	MOS	HRS/MSC -	ENC			
SB PT6A-72-1751	NO. 1 ENGINE - REORIENTATION OF STRAIGHT HEADED PIN, SERVICE BULLETIN						
	25-MAR-2015	MOS	HRS/MSC -	ENC			
SB PT6A-72-1752	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS (SUPERSEDED BY PT6A-72-1752 R01), SERVICE BULLETIN						
	09-DEC-2014	MOS		(EFF)			
		HRS/MSC -					
		ENC					
SB PT6A-72-1752 R01	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS (SUPERSEDED BY PT6A-72-1752 R02), SERVICE BULLETIN						COMPLIED WITH
	09-DEC-2014	MOS		21-MAY-2015			
		HRS/MSC -		403.3			
		ENC		455			
SB PT6A-72-1752 R02	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN						
	28-OCT-2016	MOS	HRS/MSC -	ENC			
SB PT6A-72-1753	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE AIR BAFFLE, SERVICE BULLETIN						
	26-JUN-2015	MOS	HRS/MSC -	ENC			
SB PT6A-72-1755	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, POWER TURBINE STATOR AIR SEAL AND RETAINING RING, SERVICE BULLETIN						
	13-APR-2015	MOS	HRS/MSC -	ENC			
SB PT6A-72-1755 R01	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, POWER TURBINE STATOR AIR SEAL AND RETAINING RING, SERVICE BULLETIN						CATEGORY 7
	22-OCT-2019	MOS	HRS/MSC -	ENC			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-1756	NO. 1 ENGINE - REMOVAL OF REDUCTION GEARBOX TACHOMETER PAD WASHER, SERVICE BULLETIN	MOS					
25-FEB-2015		HRS/MSC -					
		ENC					
SB PT6A-72-1757	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF 1ST AND 2ND STAGE REDUCTION CARRIER SET, SERVICE BULLETIN	MOS					
26-MAR-2015		HRS/MSC -					
		ENC					
SB PT6A-72-1765	NO. 1 ENGINE - REPLACEMENT OF OIL FILTER, OIL FILLER NECK AND RGB STRAINER - PREFORMED PACKINGS (SUPERSEDED BY PT6A-72-1765 R01), SERVICE BULLETIN	MOS					
13-JUL-2015		HRS/MSC -					
		ENC					
SB PT6A-72-1765 R01	NO. 1 ENGINE - REPLACEMENT OF OIL FILTER, OIL FILLER NECK AND RGB STRAINER - PREFORMED PACKINGS, SERVICE BULLETIN	MOS					
15-AUG-2016		HRS/MSC -					
		ENC					
SB PT6A-72-1766	NO. 1 ENGINE - INSPECTION OF INTERCONNECT ROD, SERVICE BULLETIN					COMPLIED WITH	
13-JUL-2015		MOS		02-SEP-2015			
		HRS/MSC -		476.4			
		ENC		549			
SB PT6A-72-1771	NO. 1 ENGINE - REPLACEMENT OF PROPELLER REDUCTION GEARBOX FRONT AND REAR HOUSING ASSEMBLY, SERVICE BULLETIN	MOS					
30-JUL-2015		HRS/MSC -					
		ENC					
SB PT6A-72-1775	NO. 1 ENGINE - CONVERSION OF PT6A-140 ENGINE (BS1294) TO PT6A-140 ENGINE (BS1341), SERVICE BULLETIN	MOS					
17-SEP-2015		HRS/MSC -					
		ENC					
SB PT6A-72-1775 R01	NO. 1 ENGINE - CONVERSION OF PT6A-140 ENGINE (BS1294) TO PT6A-140 ENGINE (BS1341), SERVICE BULLETIN					CATEGORY 8	
19-OCT-2018		MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-1776	NO. 1 ENGINE - CONVERSION OF PT6A-140 ENGINE (BS1294) TO PT6A-140 ENGINE (BS1345) (SUPERSEDED BY PT61-72-1776 R01), SERVICE BULLETIN	MOS					
15-SEP-2015		HRS/MSC -					
		ENC					
SB PT6A-72-1776 R01	NO. 1 ENGINE - CONVERSION OF PT6A-140 ENGINE (BS1294) TO PT6A-140 ENGINE (BS1345), SERVICE BULLETIN	MOS					
16-SEP-2015		HRS/MSC -					
		ENC					



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-1777	NO. 1 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER ASSEMBLY, SERVICE BULLETIN						
08-FEB-2016		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1778	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF CARRIER BALANCING ASSEMBLY FIRST-STAGE, SERVICE BULLETIN						
17-DEC-2015		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1779	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN						
18-OCT-2016		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1779 R01	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN					CATEGORY 7	
13-NOV-2020		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1783	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF POWER TURBINE STATOR AIR SEAL, SERVICE BULLETIN						
11-DEC-2015		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1785	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE STATOR AIR SEAL (SUPERSEDED BY PT6A-72-1785 R01), SERVICE BULLETIN						
14-JAN-2016		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1785 R01	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE STATOR AIR SEAL, SERVICE BULLETIN						
11-FEB-2016		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1788	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY., SERVICE BULLETIN						
18-JAN-2016		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1790	NO. 1 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN						
17-OCT-2016		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1790 R01	NO. 1 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
07-JUL-2017		MOS		HRS/MSC -			
				ENC			
SB PT6A-72-1790 R02	NO. 1 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
13-NOV-2020		MOS		HRS/MSC -			
				ENC			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-1791	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR CENTER TOP FIRESEAL, SERVICE BULLETIN					CATEGORY 7	
	01-DEC-2017	MOS	HRS/MSC -	ENC			
SB PT6A-72-1791 R01	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR CENTER TOP FIRESEAL, SERVICE BULLETIN					CATEGORY 7	
	16-SEP-2019	MOS	HRS/MSC -	ENC			
SB PT6A-72-1796	NO. 1 ENGINE - REPLACEMENT OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CATEGORY 7	
	02-MAR-2018	MOS	HRS/MSC -	ENC			
SB PT6A-72-1796 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CATEGORY 7	
	04-MAY-2019	MOS	HRS/MSC -	ENC			
SB PT6A-72-1800	NO. 1 ENGINE - REPLACEMENT OF NUT OPTION (IC), SERVICE BULLETIN					CATEGORY 9	
	24-AUG-2018	MOS	HRS/MSC -	ENC			
SB PT6A-72-1800 R01	NO. 1 ENGINE - REPLACEMENT OF NUT OPTION (IC), SERVICE BULLETIN					CATEGORY 9	
	03-OCT-2018	MOS	HRS/MSC -	ENC			
SB PT6A-72-1804	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF CENTRIFUGAL IMPELLER, SERVICE BULLETIN					CATEGORY 7	
	23-MAR-2019	MOS	HRS/MSC -	ENC			
SB PT6A-72-1805	NO. 1 ENGINE - INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) PREFORMED PACKING, SERVICE BULLETIN					CATEGORY 3	
	21-JAN-2019	MOS	HRS/MSC -	ENC			
SB PT6A-72-1806	NO. 1 ENGINE - REMOVAL OF FUEL OIL HEAT EXCHANGER (FOHE) TEMPERATURE SENSOR, SERVICE BULLETIN					CATEGORY 7	
	09-JAN-2019	MOS	HRS/MSC -	ENC			
SB PT6A-72-1807	NO. 1 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 7	
	13-MAR-2019	MOS	HRS/MSC -	ENC			
SB PT6A-72-1807 R01	NO. 1 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 7	
	15-SEP-2020	MOS	HRS/MSC -	ENC			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-1808	NO. 1 ENGINE - INTRODUCTION OF T5 TRIM-WIRING-HARNESS CLASSIFICATIONS, SERVICE BULLETIN					CATEGORY 9	
	19-FEB-2020	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1808 R01	NO. 1 ENGINE - INTRODUCTION OF T5 TRIM-WIRING-HARNESS CLASSIFICATIONS, SERVICE BULLETIN					CATEGORY 9	
	01-APR-2020	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1811	NO. 1 ENGINE - INTRODUCTION OF SCAVENGE-PUMP DRIVE-SHAFT PLUG, SERVICE BULLETIN					CATEGORY 5	
	05-DEC-2019	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1811 R01	NO. 1 ENGINE - INTRODUCTION OF SCAVENGE-PUMP DRIVE-SHAFT PLUG, SERVICE BULLETIN					CATEGORY 3	
	23-DEC-2021	MOS	36	(EFF)	05-DEC-2022		
		HRS/MSC					
		ENC					
SB PT6A-72-1824	NO. 1 ENGINE - REPLACEMENT OF REDUCTION GEARBOX FIRST STAGE RING GEAR AND PLANET GEAR SET, SERVICE BULLETIN					CATEGORY 7	
	09-SEP-2021	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1831	NO. 1 ENGINE - REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE-ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
	22-MAR-2022	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1831 R01	NO. 1 ENGINE - REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE-ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
	07-APR-2022	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1831 R02	NO. 1 ENGINE - REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE-ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
	11-JUL-2022	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1831 R03	NO. 1 ENGINE - REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE-ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
	18-OCT-2022	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1833	NO. 1 ENGINE - INTRODUCTION OF ALTERNATE BALL BEARING, SERVICE BULLETIN					CATEGORY 9	
	11-OCT-2022	MOS		HRS/MSC -			
		ENC					
SB PT6A-72-1834	NO. 1 ENGINE - REPLACEMENT OF FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	
	21-JUL-2022	MOS		HRS/MSC -			
		ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-1903 R03	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						
27-NOV-2015		MOS		HRS/MSC -			
				ENC			
SB PT6A-74-1819	NO. 1 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 7	
18-FEB-2021		MOS		HRS/MSC -			
				ENC			
SB PT6A-74-1819 R01	NO. 1 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 7	
26-MAR-2021		MOS		HRS/MSC -			
				ENC			
SB PT6A-74-1819 R02	NO. 1 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 7	
29-APR-2021		MOS		HRS/MSC -			
				ENC			
SB PT6A-74-1819 R03	NO. 1 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 7	
19-MAY-2021		MOS		HRS/MSC -			
				ENC			
SB PT6A-74-1835	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF IGNITION CABLE ASSEMBLY, SERVICE BULLETIN					CATEGORY 5	
13-DEC-2022		MOS		HRS/MSC -			
				ENC			
SB PT6A-77-1820	NO. 1 ENGINE - REPLACEMENT OF TORQUE PRESSURE TRANSDUCER, SERVICE BULLETIN					CATEGORY 7	
08-NOV-2021		MOS		HRS/MSC -			
				ENC			
SI 07-2014 R02	NO. 1 ENGINE - REPAIR OF OIL LEAK FROM EXHAUST CASE DRAIN HOLE, SERVICE INSTRUCTIONS						
20-FEB-2014		MOS		HRS/MSC -			
				ENC			
SIL GEN-055 R08	NO. 1 ENGINE - GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES (SUPERSEDED BY GEN-055 R09), SERVICE INFORMATION LETTER					RECOMMENDED	
06-NOV-2018		MOS		HRS/MSC -			
				ENC			
SIL GEN-055 R09	NO. 1 ENGINE - GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES (SUPERSEDED BY GEN-055 R10), SERVICE INFORMATION LETTER					RECOMMENDED	
08-NOV-2018		MOS		HRS/MSC -			
				ENC			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

AIRCRAFT
All Bulletins
Report Date: 24-May-2023

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SIL GEN-055 R10	NO. 1 ENGINE - GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES, SERVICE INFORMATION LETTER					RECOMMENDED	
13-NOV-2018		MOS HRS/MSC - ENC					
SIL GEN-153 R09	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
18-JAN-2022		MOS HRS/MSC - ENC					
SIL GEN-153 R10	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
31-OCT-2022		MOS HRS/MSC - ENC					



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
PROPELLER NO. 1 - AD - BUA33576/HC-B3TN-3AF							
FAA 1983-08-01 R02	NO. 1 PROPELLER - HARTZELL PROPELLER INC. (FORMERLY TRW HARTZELL PROPELLER) MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, AND HC-B5MP-3 TURBOPROPELLERS					MANDATORY	COMPLIED WITH
39-14043 11-MAY-2005		MOS HRS/MSC - ENC		03-NOV-2021 1473.8			
FAA 1996-18-14	NO. 1 PROPELLER - PROPELLER - HARTZELL MODELS HC-A3V, HC-B3M, HC-B3T, HC-B4M, HC-B4T, AND HC-B5M HUB - INSPECT / REPLACE					MANDATORY	COMPLIED WITH
39-9738 16-OCT-1996		MOS HRS/MSC -		03-NOV-2021 1473.8			
FAA 2003-13-17	NO. 1 PROPELLER - PROPELLERS - MAINTENANCE ACTIONS ON HARTZELL PROPELLER, INC., MCCAULEY PROPELLER SYSTEMS, SENSENICH PROPELLER MANUFACTURING COMPANY, INC., AND RAYTHEON AIRCRAFT COMPANY PROPELLERS RETURNED TO SERVICE BY T AND W PROPELLERS, INC., OF CHINO CA						COMPLIED WITH
39-13219 18-JUL-2003		MOS HRS/MSC -		03-NOV-2021 1473.8			
FAA 2005-14-11	NO. 1 PROPELLER - PROPELLER - HARTZELL, MCCAULEY AND SENSENICH PROPELLERS RETURNED TO SERVICE BY SOUTHERN CALIFORNIA PROPELER SERVICE OF INGLEWODD, CA - MAINTENANCE ACTIONS AMOUNTING TO AN OVERHAUL					MANDATORY	COMPLIED WITH
39-14188 17-AUG-2005		MOS HRS/MSC -		03-NOV-2021 1473.8			
FAA 2005-14-12	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B3MN-3, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, HC-B4MP-3, HC-B4MP-5, AND HC-B5MP-3 MOUNTING BOLTS - INSPECT / REPLACE					MANDATORY	COMPLIED WITH
39-14189 29-JUL-2005		MOS HRS/MSC -		03-NOV-2021 1473.8			
FAA 2006-24-07	NO. 1 PROPELLER - HARTZELL PROPELLER INC. PROPELLERS AND MCCAULEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS					MANDATORY	COMPLIED WITH
39-14836 03-JAN-2007		MOS HRS/MSC -		03-NOV-2021 1473.8			
FAA 2009-10-14	NO. 1 PROPELLER - IDENTIFICATION AND REMOVAL OF ALL PROPELLER BLADE COUNTERWEIGHT SLUG BOLTS, P/N B-3386-14H,LFC MANUFACTURING LOT 224, FROM SERVICE					MANDATORY	COMPLIED WITH
04-JUN-2009		MOS HRS/MSC -		03-NOV-2021 1473.8			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
PROPELLER NO. 1 - SB - BUA33576/HC-B3TN-3AF							
ASB HC-ASB-30-358 R02	NO. 1 PROPELLER - ANTI-ICE - TRAVEL TUBE BRACKET WELDMENT REPLACEMENT, ALERT SERVICE BULLETIN						NOT APPLICABLE
01-FEB-2016		MOS HRS/MSC -		03-NOV-2021			
ASB HC-ASB-30-358 R02 PARA E(1)	NO. 1 PROPELLER - INSPECTION ANTI-ICE - TRAVEL TUBE BRACKET WELDMENT REPLACEMENT, ALERT SERVICE BULLETIN OF BRACKET WELDMENT						NOT APPLICABLE
01-FEB-2016		MOS HRS/MSC -		03-NOV-2021			
ASB HC-ASB-30-358 R02 PARA E(2)	NO. 1 PROPELLER - REPLACEMENT ANTI-ICE - TRAVEL TUBE BRACKET WELDMENT REPLACEMENT, ALERT SERVICE BULLETIN OF BRACKET (TERMINATING ACTION)						NOT APPLICABLE
01-FEB-2016		MOS HRS/MSC -		03-NOV-2021			
ASB HC-ASB-61-279 R04	NO. 1 PROPELLER - PROPELLER - PROPELLER MOUNTING BOLT INSPECTION, ALERT SERVICE BULLETIN						COMPLIED WITH
04-OCT-2005		MOS HRS/MSC -		03-NOV-2021 1473.8			
ASB HC-ASB-61-313 R03	NO. 1 PROPELLER - PROPELLER - COUNTERWEIGHT SLUG BOLT INSPECTION, ALERT SERVICE BULLETIN						COMPLIED WITH
15-JUL-2009		MOS HRS/MSC -		03-NOV-2021 1473.8			
ASB HC-ASB-61-337 R01	NO. 1 PROPELLER - A-880-1 PISTON NUT INSPECTION, ALERT SERVICE BULLETIN						COMPLIED WITH
27-AUG-2012		MOS HRS/MSC -		03-NOV-2021 1473.8			
ASB HC-ASB-61-381 R01	NO. 1 PROPELLER - PROPELLER - BLADE BEARING RACES, ALERT SERVICE BULLETIN					MANDATORY	COMPLIED WITH
16-AUG-2018		MOS HRS/MSC -		03-NOV-2021 1473.8			
ASB HC-ASB-61-381 R01 PARA (E)(1)	NO. 1 PROPELLER - ACCOMPLISH PROPELLER - BLADE BEARING RACES, ALERT SERVICE BULLETIN OVERHAUL THE PROPELLER AND INSTALL ALL NEW A-1851 BLADE RETENTION BEARINGS (WHICH INCLUDE THE BEARING BALLS) IN ACCORDANCE WITH HARTZELL PROPELLER INC. STEEL HUB TURBINE PROPELLER MAINTENANCE MANUAL 118F (61-10-18). (NEW PROPELLERS AND PROPELLERS THAT HAD ALL NEW A-1851-() BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)					MANDATORY	
16-AUG-2018		MOS HRS/MSC -					
ASB HC-ASB-61-381 R01 PARA (E)(2)(A)	NO. 1 PROPELLER - ACCOMPLISH PROPELLER - BLADE BEARING RACES, ALERT SERVICE BULLETIN OVERHAUL THE PROPELLER AND INSTALL ALL NEW A-1851 BLADE RETENTION BEARINGS (WHICH INCLUDE THE BEARING BALLS) IN ACCORDANCE WITH HARTZELL PROPELLER INC. STEEL HUB TURBINE PROPELLER MAINTENANCE MANUAL 118F (61-10-18) (PROPELLERS THAT HAD ANY OVERHAULED A-1851-() BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)					MANDATORY	
16-AUG-2018		MOS HRS/MSC -					



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB HC-ASB-61-381 R01 PARA (E)(2)(B-D) OPT 1 PT 1	NO. 1 PROPELLER - ACCOMPLISH PROPELLER - BLADE BEARING RACES, ALERT SERVICE BULLETIN INSPECT THE A-1851-() BLADE RETENTION BEARINGS AND B-6144-2 BEARING BALLS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS IN THIS ALERT SERVICE BULLETIN (PROPELLERS THAT HAD ANY OVERHAULED A-1851-() BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)					MANDATORY	
16-AUG-2018		MOS HRS/MSC -					
ASB HC-ASB-61-381 R01 PARA (E)(2)(B-D) OPT 1 PT 2	NO. 1 PROPELLER - ACCOMPLISH PROPELLER - BLADE BEARING RACES, ALERT SERVICE BULLETIN OVERHAUL THE PROPELLER AND INSTALL ALL NEW A-1851 BLADE RETENTION BEARINGS (WHICH INCLUDE THE BEARING BALLS) IN ACCORDANCE WITH HARTZELL PROPELLER INC. STEEL HUB TURBINE PROPELLER MAINTENANCE MANUAL 118F (61-10-18). (PROPELLERS THAT HAD ANY OVERHAULED A-1851-() BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)					MANDATORY	
16-AUG-2018		MOS HRS/MSC -					
ASB HC-ASB-61-381 R01 PARA (E)(2)(B-D) OPT 2	NO. 1 PROPELLER - ACCOMPLISH PROPELLER - BLADE BEARING RACES, ALERT SERVICE BULLETIN INSTALL ALL NEW A-1851 BLADE RETENTION BEARINGS (WHICH INCLUDE THE BEARING BALLS) IN ACCORDANCE WITH HARTZELL PROPELLER INC. STEEL HUB TURBINE PROPELLER MAINTENANCE MANUAL 118F (61-10-18). (PROPELLERS THAT HAD ANY OVERHAULED A-1851-() BLADE RETENTION BEARINGS INSTALLED AT THE MOST RECENT OVERHAUL)					MANDATORY	
16-AUG-2018		MOS HRS/MSC -					
ASB HC-ASB-61-399	NO. 1 PROPELLER - PROPELLERS OVERHAULED BY CHINA FLYING DRAGON GENERAL AVIATION, ALERT SERVICE BULLETIN						NOT APPLICABLE
03-AUG-2022		MOS HRS/MSC -		13-SEP-2022 1653.8			
ASB HC-ASB-61-399 R01	NO. 1 PROPELLER - PROPELLERS OVERHAULED BY CHINA FLYING DRAGON GENERAL AVIATION, ALERT SERVICE BULLETIN						
05-OCT-2022		MOS HRS/MSC -					
ASB HC-ASB-61-402	NO. 1 PROPELLER - TRINITY SPECIALIZED SERVICES/MID AMERICA PROPELLER, ALERT SERVICE BULLETIN						
08-MAR-2023		DAYS 60 HRS/MSC 10		(EFF)	07-MAY-2023 1719.78		
SB 137A	NO. 1 PROPELLER - REPLACEMENT OF A-282 INNER CLAMP SCREW, SERVICE BULLETIN						COMPLIED WITH
31-MAR-1995		MOS HRS/MSC -		03-NOV-2021 1473.8			
SB HC-SB-61-136 REV I	NO. 1 PROPELLER - BLADES - ADDITIONAL OVERHAUL AND INSPECTION PROCEDURES FOR SINGLE- AND DOUBLE-SHOULDER BLADE BORES, SERVICE BULLETIN						COMPLIED WITH
25-APR-2003		MOS HRS/MSC -		03-NOV-2021 1473.8			
SB HC-SB-61-261 R01	NO. 1 PROPELLER - PROPELLER - HUB REPLACEMENT, BLADE AND BLADE CLAMP INSPECTION, SERVICE BULLETIN						COMPLIED WITH
21-MAY-2003		MOS HRS/MSC -		03-NOV-2021 1473.8			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB HC-SB-61-280	NO. 1 PROPELLER - PROPELLER - A-1464 LINK PIN UNIT, SERVICE BULLETIN						COMPLIED WITH
	04-OCT-2005	MOS		03-NOV-2021	1473.8		
		HRS/MSC	-				
SB HC-SB-61-294 R01	NO. 1 PROPELLER - PROPELLER - LINK ARM INSPECTION, SERVICE BULLETIN						COMPLIED WITH
	07-AUG-2007	MOS		03-NOV-2021	1473.8		
		HRS/MSC	-				
SB HC-SB-61-363 R01	NO. 1 PROPELLER - INTRODUCTION OF A-2051-1 BOLT WITH THREE-DIRECTION SAFETY WIRE HOLES, SERVICE BULLETIN						COMPLIED WITH
	01-JUL-2015	MOS		03-NOV-2021	1473.8		
		HRS/MSC	-				
SB HC-SB-61-374 R01	NO. 1 PROPELLER - BLADE BEARING RACE INSPECTION CRITERIA, SERVICE BULLETIN						COMPLIED WITH
	01-AUG-2017	MOS		03-NOV-2021	1473.8		
		HRS/MSC	-				
SB HC-SL-61-277 R04	NO. 1 PROPELLER - GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS, SERVICE BULLETIN					OPTIONAL	
	03-OCT-2016	MOS					
		HRS/MSC	-				
SB HC-SL-61-370	NO. 1 PROPELLER - BETA SYSTEM CLEANING PROCEDURE, SERVICE BULLETIN						COMPLIED WITH
	07-JUL-2021	MOS		03-NOV-2021	1473.8		
		HRS/MSC	-				
SL HC-SL-30-259 R14	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. MOUNTED ICE PROTECTION COMPONENTS, SERVICE LETTER						NOT APPLICABLE
	15-MAR-2016	MOS		03-NOV-2021			
		HRS/MSC	-				
SL HC-SL-30-259 R15	NO. 1 PROPELLER - HARTZELL PROPELLER INC. MOUNTED ICE PROTECTION COMPONENTS, SERVICE LETTER						
	09-MAR-2022	MOS					
		HRS/MSC	-				
SL HC-SL-30-260 R22	NO. 1 PROPELLER - DE-ICE BOOTS, ANTI-ICING BOOTS, AND AIRFRAME MOUNTED ICE PROTECTION SYSTEM COMPONENTS, SERVICE LETTER						NOT APPLICABLE
	27-OCT-2014	MOS		03-NOV-2021			
		HRS/MSC	-				
SL HC-SL-30-260 R23	NO. 1 PROPELLER - DE-ICE BOOTS, ANTI-ICING BOOTS, AND AIRFRAME MOUNTED ICE PROTECTION SYSTEM COMPONENTS, SERVICE LETTER						
	01-SEP-2022	MOS					
		HRS/MSC	-				



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL HC-SL-61-165	NO. 1 PROPELLER - PROPELLER - ABNORMAL VIBRATION OR GREASE LEAKAGE, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	07-DEC-1995	HRS/MSC	-	1473.8			
SL HC-SL-61-167	NO. 1 PROPELLER - PROPELLER - INTRODUCTION OF LINKARM BUSHING, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	07-DEC-1995	HRS/MSC	-	1473.8			
SL HC-SL-61-172 R01	NO. 1 PROPELLER - HARTZELL POLICY - NEW FEE FOR PARTS EVALUATION, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	15-MAR-2000	HRS/MSC	-	1473.8			
SL HC-SL-61-177	NO. 1 PROPELLER - BALL BEARINGS - NEW PART NUMBER/USAGE, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	04-FEB-1997	HRS/MSC	-	1473.8			
SL HC-SL-61-185 R03	NO. 1 PROPELLER - TACHOMETERS, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE
		MOS		03-NOV-2021			
	21-OCT-2016	HRS/MSC	-				
SL HC-SL-61-187 R04	NO. 1 PROPELLER - PROPELLER - ALTERNATE LUBRICATION FITTINGS, SERVICE LETTER						
		MOS					
	18-NOV-2021	HRS/MSC	-				
SL HC-SL-61-187 R05	NO. 1 PROPELLER - PROPELLER - ALTERNATE LUBRICATION FITTINGS, SERVICE LETTER						
		MOS					
	09-MAR-2022	HRS/MSC	-				
SL HC-SL-61-188	NO. 1 PROPELLER - PROPELLER - BLADE/CLAMP SEALING ON AGRICULTURAL AIRCRAFT, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
		MOS		03-NOV-2021			
	08-JUN-2000	HRS/MSC	-	1473.8			
SL HC-SL-61-217	NO. 1 PROPELLER - PROPELLER - REPLACEMENT OF HARDWARE AT PROPELLER OVERHAUL, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	21-MAR-2003	HRS/MSC	-	1473.8			
SL HC-SL-61-244	NO. 1 PROPELLER - PROPELLER - SPARE PARTS RELEASE, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	28-FEB-2005	HRS/MSC	-	1473.8			
SL HC-SL-61-248	NO. 1 PROPELLER - PROPELLER - NEW 101224() AND 101225() START LOCK BRACKETS, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	15-SEP-2005	HRS/MSC	-	1473.8			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL HC-SL-61-249	NO. 1 PROPELLER - PROPELLER - SPINNER BULKHEADS AFFECTED BY BRAZILIAN AD, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	13-JAN-2006	HRS/MSC	-	1473.8			
SL HC-SL-61-253	NO. 1 PROPELLER - INSPECTION OF STEEL HUB PROPELLERS INSTALLED ON AGRICULTURAL AIRCRAFT, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	11-MAY-2006	HRS/MSC	-	1473.8			
SL HC-SL-61-254	NO. 1 PROPELLER - PROPELLER - PROPELLER OPERATING RESTRICTIONS, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	24-FEB-2006	HRS/MSC	-	1473.8			
SL HC-SL-61-256	NO. 1 PROPELLER - PROPELLER - SPARE PARTS RELEASE, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	16-MAR-2006	HRS/MSC	-	1473.8			
SL HC-SL-61-258 R01	NO. 1 PROPELLER - PROPELLERS - BLADE CLAMP SEALING PROCEDURE, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	12-JAN-2007	HRS/MSC	-	1473.8			
SL HC-SL-61-270	NO. 1 PROPELLER - PROPELLER - PART NUMBER STAMPING, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	07-AUG-2007	HRS/MSC	-	1473.8			
SL HC-SL-61-277 R05	NO. 1 PROPELLER - GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS, SERVICE LETTER					OPTIONAL	
		MOS					
	01-FEB-2017	HRS/MSC	-				
SL HC-SL-61-277 R06	NO. 1 PROPELLER - GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS, SERVICE LETTER					OPTIONAL	
		MOS					
	16-SEP-2020	HRS/MSC	-				
SL HC-SL-61-324	NO. 1 PROPELLER - BLADE - ALUMINUM BLADE FIELD REPAIR, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	21-OCT-2011	HRS/MSC	-	1473.8			
SL HC-SL-61-329	NO. 1 PROPELLER - PROPELLER BLADES - BLADE PAINT, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	27-AUG-2012	HRS/MSC	-	1473.8			
SL HC-SL-61-343	NO. 1 PROPELLER - PRODUCT CATEGORY - LUBRICATION PROCEDURE, SERVICE LETTER						COMPLIED WITH
		MOS		03-NOV-2021			
	01-APR-2014	HRS/MSC	-	1473.8			



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL HC-SL-61-351	NO. 1 PROPELLER - ALTERNATE BOLT (A-2051-1) FOR ATTACHING THE SPINNER MOUNTING PLATE, SERVICE LETTER	MOS HRS/MSC -		03-NOV-2021 1473.8		COMPLIED WITH	
SL HC-SL-61-353	NO. 1 PROPELLER - PROPELLER - AEROSHELL GREASE 5, SERVICE LETTER	MOS HRS/MSC -		03-NOV-2021		NOT APPLICABLE	
	11-NOV-2015						
SL HC-SL-61-355	NO. 1 PROPELLER - BLADE - COMPOSITE BLADE MINOR REPAIR KITS, SERVICE LETTER	MOS HRS/MSC -					
	01-AUG-2016						
SL HC-SL-61-356	NO. 1 PROPELLER - PRIMER SEALER COLOR CHANGE, SERVICE LETTER	MOS HRS/MSC -		03-NOV-2021		NOT APPLICABLE	
	13-JUL-2016						
SL HC-SL-61-359	NO. 1 PROPELLER - POLANE PAINT (SILVER) CM163, SERVICE LETTER	MOS HRS/MSC -		03-NOV-2021 1473.8		COMPLIED WITH	
	02-OCT-2017						
SL HC-SL-61-362	NO. 1 PROPELLER - PROPELLER - A-1851-T BLADE RETENTION BEARINGS, SERVICE LETTER	MOS HRS/MSC -		03-NOV-2021 1473.8		COMPLIED WITH	
	05-SEP-2018						
SL HC-SL-61-364	NO. 1 PROPELLER - PROPELLER - CORROSION INHIBITOR ON COUNTERWEIGHTS, SERVICE LETTER	MOS HRS/MSC -		03-NOV-2021 1473.8		COMPLIED WITH	
	03-APR-2020						
SL HC-SL-61-366	NO. 1 PROPELLER - PROPELLER - NYCO GN3058 GREASE, SERVICE LETTER	MOS HRS/MSC -		03-NOV-2021 1473.8		COMPLIED WITH	
	06-JAN-2020						
SL HC-SL-61-367 R01	NO. 1 PROPELLER - 107995-() COUNTERWEIGHT MOUNTING BOLTS, SERVICE LETTER	MOS HRS/MSC -		03-NOV-2021 1473.8		COMPLIED WITH	
	17-DEC-2020						
SL HC-SL-61-372	NO. 1 PROPELLER - HARTZELL PROPELLER INC. BLADE DECALS, SERVICE LETTER	MOS HRS/MSC -					
	07-DEC-2022						
SL HC-SL-61-373	NO. 1 PROPELLER - SPLIT BEARING RACE ADHESIVE, SERVICE LETTER	MOS HRS/MSC -					
	07-DEC-2022						



Master AD/SI Report

208B CARAVAN - TBIP S/N 208B-5098 (RP-C1087): 4001.7HRS, 6734 AFL as of 28-Mar-2023

**AIRCRAFT
All Bulletins
Report Date: 24-May-2023**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL HC-SL-61-374	NO. 1 PROPELLER - ONLINE PRODUCT REGISTRATION, SERVICE LETTER	MOS					
08-MAR-2023		HRS/MSC	-				
SL HC-SL-61-61Y R14	NO. 1 PROPELLER - PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS FOR HARTZELL PROPELLER INC. AVIATION COMPONENTS - PROPELLERS, GOVERNORS, ACCUMULATORS, AND PROPELLER DAMPER ASSEMBLIES, SERVICE LETTER	MOS			03-NOV-2021		COMPLIED WITH
07-JUL-2021		HRS/MSC	-		1473.8		