

# RIDGEAIRE

AIRCRAFT SALES · ACQUISITIONS · APPRAISALS

## LEFT PROPELLER LOGBOOK



**1973 Beechcraft King Air C90**

**N 5 9 K A**


SERIAL NUMBER LJ-589

---

**LEFT PROPELLER  
LOGBOOK**

---

**JORDAN PROPELLER**



**SERVICE**

**INC.**

---

103 E. Rhapsody • San Antonio, Texas 78216 • (210) 344-3064 • (866) 344-7767 • Fax (210) 344-9433 • CRS EK2R797K

**Propeller Logbook**

Hub Model HC-B3TN-3B

Blade Design T10173NB-8 CAT Z

Diameter 93 INCH

Hub Serial No. BUA 22561

Blade Serial Nos. \_\_\_\_\_

No. 1 J 33570

No. 2 J 33563

No. 3 J 33568

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

High — Low 20.2°  
Feather 87.0° Reverse ~~87.0°~~ -11.0°  
Latch Angle —

| DATE | TACH<br>TIME | DESCRIPTION OF WORK                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|------|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|      |              | <p>JORDAN PROPELLER SERVICE, INC.<br/> 103 East Rhapsody San Antonio, Texas 78216<br/> Certificated Repair Station No. EK2R797K</p> <p>PROPELLER S/N <u>BUA22561</u> HAS BEEN <u>OVERHAULED</u></p> <p>I/A/W <u>Hartzell Manuals 118F Rev. 24 &amp; 133C Rev. 31</u><br/> Supplied New Hub Mounting Bolts P/N B-3339 To Satisfy A. D. Note 83-08-01R2.</p> <p>C/W Service Bulletins 137A, 61-136R1, 61-279R4, 61-280, 61-285R1, 61-294R1,<br/> 61-337R1 and Service Letters 61-167, 61-177, 61-189R2, 61-217, 61-229R2, 61-238,<br/> 61-244 &amp; 154.</p> <p>PERTINENT DETAILS ON FILE UNDER WORK ORDER NUMBER <u>17045-1</u></p> <p>SIGNED <u><i>Barry L. Jordan</i></u> DATE <u>01-27-15</u></p> <p>MECHANIC MAKING INSTALLATION ON A/C MUST C/W FAR 43.9</p> |