


N7EV

1998 A36 Bonanza Turbine

Airworthiness Directive



MSN: E-3162

Prepared by the worldwide aviation specialists at RidgeAir, Inc.

SERVICE INFORMATION

Search Criteria

22 Records Found.

N7EV A36 E3162

Pub Number	Title Description	Model/Variant	Serial Number
		36/A36 Bonanza (E-Serials)	E-3162

AD Number	Compliance	ATA Chapter	Publication Type
	Mandatory		

It is the responsibility of the owner/operator to ensure that a Service Bulletin is applicable to their airplane before performing an inspection or modification. Warranty adjudication will not be administered based on search results. If necessary, contact Customer Support for technical assistance: 800-429-5372.

Pub No.	Rev No.	AD No.	Chapter	Date	Compliance	Title Description
SEL-71-17	2	NATO ENGINE	71	3/17/2023	Mandatory	POWER PLANT - TRANSMITTAL OF CONTINENTAL AEROSPACE TECHNOLOGIES MSB23-01A
SEL-74-07		NATO ENGINE	74	11/4/2022	Mandatory	IGNITION - TRANSMITTAL OF CONTINENTAL SERVICE BULLETIN CSB673C
SEL-24-11	-	NATO ENGINE ROLLS ROYCE	24	10/4/2021	Mandatory	ELECTRICAL POWER - TRANSMITTAL OF CONTINENTAL AEROSPACE TECHNOLOGIES CRITICAL SERVICE BULLETIN CSB19-06
SEL-79-03		NATO ENGINE	79	4/21/2021	Mandatory	OIL - TRANSMITTAL OF CONTINENTAL AEROSPACE TECHNOLOGIES CSB07-1A CONNECTING ROD PISTON PIN BUSHING INSPECTION
SEL-71-10		NATO ENGINE	71	1/26/2021	Mandatory	POWER PLANT - TRANSMITTAL OF CONTINENTAL MOTORS SB18-04A REPLACEMENT OF FLANGED NUT
SEL-74-06	1	NATO ENGINE	74	3/24/2020	Mandatory	IGNITION - TRANSMITTAL OF CONTINENTAL MOTORS SB19-02A, LYCOMING SB 637, AND CHAMPION AEROSPACE SLICK SERVICE BULLETIN SB1-19
SEL-61-01		NATO GOVERNOR	61	11/1/2018	Mandatory	Propeller - Propeller Governor Inspection in Accordance with McCauley ASB273

N7EV A36 E3162

Pub No.	Rev No.	AD No.	Chapter	Date	Compliance	Title Description
SB 32-4172	1		32	11/17/2017	Mandatory	Landing Gear - Inspection of Brake Master Cylinder Assemblies (Online release of the Owner's Advisory has a date of October 4, 2017, hard copy of the Owner's Advisory has a date of October 4, 2018. No other data changes were made.)
SB 27-3459	2		27	11/1/2016	Mandatory	Flight Controls - Flight Control Gust Lock Inspection/Replacement (RECURRING INSP)
SB 27-4136			27	11/1/2014	Mandatory	Flight Controls - Control Column Hardware Replacement
SB 32-4125			32	5/1/2013	Mandatory	Landing Gear - Nose Landing Gear Forward Retract Plunger Rod Inspection/Replacement
SB 71-4006	-		71	11/1/2009	Mandatory	Power Plant - Announcement of Teledyne Continental ® Motors (TCM) Mandatory Service Bulletin MSB09-8 - Inspection and Removal of Certain TCM Engine Hydraulic Lifters
SB 32-3990			32	10/1/2009	Mandatory	Landing Gear - Replacement of Nose Landing Gear Retract Plunger Assembly
SB 76-3763				3/1/2006	Mandatory	Engine Controls - Throttle Warning/Gear Retraction Prevention Cam Inspection/Installation
SB 53-3341	2	2000-26-16	53-00	10/1/2002	Mandatory	Fuselage - Inspection/Installation of RH Fuselage Missing Rivets
SB 52-2693	2	97-14-15	52-10	1/1/2002	Mandatory	Doors - Inspection of the Interior Door Handles (RECURRING INSP)
SB 11-3482			11-00	1/1/2002	Mandatory	Placards & Markings - Baggage/cargo Compartment Placard Replacement
SB 27-3478		2001-23-10	27-00	9/1/2001	Mandatory	Flight Controls - Flap Flex Shaft (Cable) Assembly Inspection/replacement
SB 53-3375			53-00	12/1/1999	Mandatory	Fuselage - Inspection/Installation of Firewall Sealant
SB 53-3159			53-00	8/1/1999	Mandatory	Fuselage - 5th and 6th Seat Attachment Improvement
SB 27-3232			27-00	3/1/1999	Mandatory	Flight Controls - Inspection For Control Column Interference With Wiring Behind The Instrument Panel

N7EV A3 E3162

Pub No.	Rev No.	AD No.	Chapter	Date	Compliance	Title Description
SB 34-3267			~~34-00~~	3/1/1999	Mandatory	Navigation - KA-33 Cooling Blower Power Circuit Breaker Replacement

6/19/15 NEW OXYGEN BOTTLE LIFE DUE 3/29
 8/7/20 OXYGEN BOTTLE HYDRO CW - NEXT DUE 8/25
 11/29/23 NEW G247 BATTERY SN G03207860
 10/6/22 IFR CERTS CW NEXT DUE 10/24
 LEFT BATTERY DUE Dec 24