N2702L

1981 Cessna 414A Ram IV

#1 (LH) Prop Logbook SMOH 2021 - 2022

Aircraft S/N: 414A-0608



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



PROPELLER MAINTENANCE RECORDS

Aircraft Registration
Propeller Position
Propeller Serial No.

N2702L B/H EB-1542



PROPELLER MAINTENANCE RECORDS

	Log No
Aircraft Registration No. N2702L	•
Propeller Manufacturer	
Hub Model PHC-C34F-2UF	
Blade Design No	
Hub Serial No	
Blade Serial No's.	
1	
2	
3 4	
Pitch Range:	
High Low	
Feather Reverse	
Governor Manufacturer	
Model No	
Serial No	
Date installed on aircraft	
Time Between Overhauls (TBO) Ho	ours
If used on multi-engine aircraft:	
☑ Left	
L Flont L Rear	

(All applicable information must be filled in)

Waco Regional Airport • P.O. Box 5219 • Waco, Texas 76708 FAX 254-752-3307

TOTALS—Carry forward to next page

	Page No
TOTAL TOTAL TACH OR	grade of the control
_	는 사람들은 사람들이 되었다. 그 사람들은 사람들은 사람들은 사람들이 되었다.
N2702	2L, PROP- S/N EB-1542
Date 3/5/2012	
Hobbs 4546.0	-
Left Side	_
SPOH, 817.3	
Removed spinner dome, filled nitrogen to spe for compliance to date.	ecs (43 PSI) Lubricated hub and dressed blades. AD's checked
I certify that this propeller has been inspected to be in airworthy condition.	in accordance with a 100/annual inspection and is determined
AD's checked for compliance to date.	_
1.04	
Delly K. Gray AP1643753AI	
Bill Gray	
•	
Twelve Stone Aviation 802 Airport Ave. 1	Janger 5 Springdale, AR 72764 479-799-8065
N2702L HOBBS: 4719.8 LEFT PS	OH: 976.8 S.N. EB1542 04/01/2013
NOTED. 21 HOURS ACCUMULATED ON HOBINOT COUNT TOWARD TIME SPOH, ENGINES	EKPLATE IAW ANNUAL INSPECTION. NO DEFECTS BS DUE TO FAILURE OF SQUAT SWITCH THAT DOES WERE NOT RUNNING. I CERTIFY THAT THIS RDANCE WITH AN ANNUAL INSPECTION AND WAS TION. KEVIN S. DAVIS AP4314761481A
Twelve Stone Aviation 802 Airport	Ave. Hanger 5 Springdale, AR 72764 479-799-8065
N2702L HOBBS: 4784.0 LE	FT PSOH: 1041.0 S.N. EB1542 03/28/2014
	D BACKPLATE IAW ANNUAL INSPECTION. I CERTIFY PECTED IN ACCORDANCE WITH AN ANNUAL TO BE IN AIRWORTHY CONDITION.
Ru I I	
AP431476148IA	
Sul	3-TOTALS this page
101	ALS—Carry forward to next page

Page M			~ ~	***	
Twelve Stone Aviation 802 Airport Ave. Hanger 5 Springdale, AR 72764 479-799-8065					Page
N2702L HOBBS: 330.0 LEFT PSOH: 1188.0 S.N. EB1542 05/10/2015	DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
INSPECTED PROPELLER, SPINNER, AND BACKPLATE IAW ANNUAL INSPECTION. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL		SERVICE	OVENNACE	11416	
INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	-			N2702L	PROP, P/N PHC-C3YF-2UF, S# EB1542
KEVIN S. DAVIS	<u> </u>	10/4/201		7,27022,	
finis I'm		Date 10/4/201 Left Side)	8		
ÅP431476148IA		lobbs 750.8 NEW 1608.8	:		
Twelve Stone Aviation LLC 802 Airport Rd. Hangar 5 Springdale, AR 72764		NEW 1608.8			I I I I I I I I I I I I I I I I I I I
Twelve Stone Aviation, LLC. 802 Airport Rd. Hangar 5 Springdale, AR 72764	a a	nspected Prop nd checked a	o front hub nd added A	tor proper at ero shell # 6	ir pressure and checked to specs per Hartzell Manual. Dressed blades grease. Repaired broken wire connector to boot and replaced blade
REGISTRATION: N2702L HOBBS: 484.6 DATE: 07/29/2016	- d	eicer boot on	another bla	ade. P/N 4E1	601-10
MODEL: PHC-C3YF-2UF PROP TSMO: 1342.6 LEFT SIDE SN: EB-1542	A	D's complia	nce to date.	10/4/2018	
REPLACED PROP HEAT WIRES AS NEEDED. ANNUAL INSPECTION	E	d Allen	BU_	A4431	D2934
I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH ANNUAL INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	I	certify that th	is propelle	r has been in	spected in accordance with a 100/annual inspection and is determined
KEVIN S DAVIS	to	be in airwor	thy condition	on.	KE ODVOTA
(261)~		Sim!	Sague S	1	436231276
AP431476148IA	1	im Rogers	O		
	_				
Twelve Stone Aviation, LLC. 802 Airport Rd. Hangar 5 Springdale, AR 72764					
REGISTRATION: N2702L HOBBS: 622.2 DATE: 09/01/2017 MODEL: PHC-C3YF-2UF PROP TSMO: 1480.2 LEFT SIDE SN: EB-1542		10/5/201	8, New Hob	os time is 994.	.8
		Left, SPO	H 1608.8		
ANNUAL INSPECTION		Due to m	aintenance r	ew Hobbs tim	ne is 994.8. This time reflects the same
I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH ANNUAL INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.					
KEVIN S DAVIS					eading of 750.8
		Ed Allen_		JV	Cert# 4413602834
AP431476148fA	2020				
	75 mary		1714.2	1100.2	ANNUAL INSPECTION COMPLIED WITH PER FAR 43
					ADDENOXO. QUOL AND 3528389 IA
					myer day : Zees = // Jacobs / Ex
	2021				
	5 MAY		1846.9	1232.9	SERVICED PROPERLER WITH AEROSHELL 6.
	_				ANNUAL INSPECTION COMPLIED WITH PER FAR 43
					APPENDIX D. Will AND 3529389 IA
SUB-TOTALS this page					SUB-TOTALS this page
TOTALS—Carry forward to next page					TOTALS—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	,
				TOTALS brought forward from previous page	
In	Waco, Te CRS No. A	rl May Dr. exas 76708 AK6R541N rha <u>uled prop</u> el	ler on lest engi	Prop SMOH:	
	Toky	ons, Inc.	rk order 5256.		
		Waco,	Karl May Dr. Texas 76708 o. AK6R541N	I certify this Propeller has been inspected in accordance with a 100 HR Inspection and has been determined to be in an airworthy condition. DATE 10/04/2021 HM 1246.1 PROPELLER SMOH 00.0 (8/2021) WORK ORDER #5256	
				AIR IMPRESSIONS, INC REPAIR STATION # AK6R541N	

