

# N228HS

## 2003 Cessna T206H

---

# Airworthiness Directives

**MSN: T20608419**



*Prepared by the worldwide aviation specialists at RidgeAire, Inc.*

Date 07/10/2023  
 Make Model Textron (Cessna) T206H

Tail # N228HS

Serial # T206-8419

**Airworthiness Directive Compliance Report**

Airframe Hours: 3395.6

Misc:

Engine: Lycoming TIO-540-AJ1A

S/N: RL-11447-61E

Hours:

Propeller: McCauley B3D36C432

S/N: 020650

Hours:

AD#	Category	Subject	Amend #	Eff Date	Rec	Remarks
Date/Hours Compliance	Next Due	Name	Signature	Cert#		
<b>Airframe: Textron (Cessna) T206H</b>						
99-13-04	Airframe	Aileron Control Bellcrank	39-11197	07/13/99		N/A by date of manufacture
		Charles Crossman		3440359 IA		
01-09-06	Airframe	Horizontal Stabilizer Bracket	39-12211	05/18/01		N/A by date of manufacture
		Charles Crossman		3440359 IA		
04-15-18	Airframe	KAP 140 Autopilot	39-13752	09/12/04		N/A by Serial No.
		Charles Crossman		3440359 IA		
05-13-10	Airframe	Incorrect Circuit Breakers	39-14147	08/09/05		Previously Complied With
6/15/2005 464 Tach		Charles Crossman		3440359 IA		
07-05-10	Airframe	Crew Seat Back Cylinder Lock	39-14971	04/11/07		Previously Complied With
03-23-2007 882.6 Tach		Charles Crossman		3440359 IA		
07-08-03	Airframe	Fuel Hose Connections	39-15020	05/02/07		N/A by Serial No.
		Charles Crossman		3440359 IA		
08-05-09	Airframe	Seat Base/ Back Attach Brackets	39-15403	04/08/08		N/A by Serial No.
		Charles Crossman		3440359 IA		
08-10-02	Airframe	Alternate Static Air Source Selector Valve	39-15508	05/12/08		Previously Complied With
		Charles Crossman		3440359 IA		
08-26-10	Airframe	Alternate Static Air Source Selector Valve	39-15776	01/05/09		N/A by Model No.
		Charles Crossman		3440359 IA		
13-11-11	Airframe	Engine Oil Pressure Switch	39-17471	08/01/13	Yes	-Replaced oil pressure switch w new 83278 switch
07/10/2023 3395.6		Charles Crossman		3440359 IA		
23-09-09	Airframe	Exhaust Tailpipe V-Band Coupling	39 22432	07/17/23	Yes	new V Band coupling installed, next insp due July 31, 2024.
07/10/2023 3395.6		Charles Crossman		3440359 IA		

**Engine: Lycoming TIO-540-AJ1A**

71-13-01 R1	Engine	Rescission of AD 71-13-01	39-16909	03/08/12		N/A by date of manufacture
		Charles Crossman		3440359 IA		
75-09-15	Engine	Bendix Fuel Injector Flow Divider Cover Gasket	39-2187	04/30/75		N/A by date of manufacture
		Charles Crossman		3440359 IA		
78-23-10	Engine	Bendix RSA Series Fuel Injector Bellows Seal	39-3333	11/07/78		N/A by date of manufacture
		Charles Crossman		3440359 IA		
79-04-05	Engine	Bendix RSA Series Fuel Injectors Diaphragm	39-3570	09/28/79		N/A by date of manufacture
		Charles Crossman		3440359 IA		
91-08-07	Engine	Fuel Pump Vent Hose Fitting	39-6962	05/06/91		N/A by date of manufacture
		Charles Crossman		3440359 IA		
92-12-05	Engine	Piston Pin Failure	39-8265	07/10/92		N/A by date of manufacture
		Charles Crossman		3440359 IA		
93-11-11	Engine	Diaphragm Fuel Pumps Overhauled (by AAI)	39-8584	06/21/93		N/A by date of manufacture
		Charles Crossman		3440359 IA		
97-15-11	Engine	Piston Pin Failure	39-10085	08/12/97		N/A by date of manufacture
		Charles Crossman		3440359 IA		
02-19-03	Engine	Crankshaft Failure	39-12883	09/20/02		N/A by date of manufacture
		Charles Crossman		3440359 IA		
03-14-03	Engine	Rotary Fuel Pump Leaks	39-13222	08/14/03	Yes*	N/A by Date of Overhaul
		Charles Crossman		3440359 IA		
04-05-24	Engine	Crankshaft Gear Retaining Bolts	39-13519	03/30/04		N/A by Date of Overhaul
		Charles Crossman		3440359 IA		
04-10-14	Engine	Crankshaft Gear Retaining Bolt	39-13644	06/25/04		N/A by Date of Overhaul
		Charles Crossman		3440359 IA		
09-02-03	Engine	RSA-5 or RSA-10 Series - Fuel Injection Servo Plug Gasket	39-15793	02/09/09	Yes*	N/A by Date of Overhaul
		Charles Crossman		3440359 IA		
12-03-06	Engine	AVStar Fuel Servo Diaphragm	39-16947	02/24/12		N/A by Date
		Charles Crossman		3440359 IA		
12-19-01	Engine	Crankshaft Replacement	39-17196	10/24/12		N/A by Model No.
		Charles Crossman		3440359 IA		
15-10-06	Engine	Exhaust Pipe Cracks	39-18162	07/02/15		NA by ESN
		Charles Crossman		3440359 IA		
15-19-07	Engine	Fuel Injector Fuel Lines and Clamps	39-18269	11/03/15	Yes	C/W by INSP
6/17/2022 3334.0		3444.0 7/1/2023 Charles Crossman		3440359 IA		
17-11-10	Engine	Engine Exhaust System Leaks	39-18909	06/28/17	Yes	C/W by inspection and Performed torque check. No defects noted.
07/10/2023 3395.6		07/30/2024 3445.6 Charles Crossman		3440359 IA		

17-16-11	Engine	Connecting Rod Failure	39-18988	08/15/17	Not installed
		Charles Crossman		3440359 IA	

**Propeller: McCauley B3D36C432**

05-14-11	Propeller	Southern California Propeller Serviced Propellers	39-14188	08/17/05	last serviced by San Antonio Propellers,
07/10/2023 3395.6		Charles Crossman		3440359 IA	
06-24-07	Propeller	Oxford Aviation/CSE Aviation Serviced Propellers	39-14836	01/03/07	N/A by SN, last return to service by San Antonio Propellers
07/10/2023 3395.6		Charles Crossman		3440359 IA	

**Appliance: Avionics - Altimeters**

23-10-02	Appliance	Radio / Radar Altimeter - Interference	39-22438	05/26/23	
		Charles Crossman		3440359 IA	
23-11-07	Appliance	Radio / Radar Altimeter - Interference	39-22453	06/22/23	
		Charles Crossman		3440359 IA	

**Appliance: Avionics - Navigational**

22-03-15	Appliance	Garmin EFIS Fuel Quantity Disparities	39-21932	03/21/22	Previously Complied With
		Charles Crossman		3440359 IA	