

RIDGEAIRE

AIRCRAFT SALES · ACQUISITIONS · APPRAISALS

LEFT PROPELLER LOGBOOK



1961 Beechcraft 95-55 Baron

N1268Z

SERIAL NUMBER TC-84

LEFT PROPELLER LOGBOOK

N12682 Lt Prop



PROPELLER LOGBOOK

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
April 1, 1997	Hobbs 7.2	RFTotal Time 5333.3 HRS	I have inspected this propeller IAW a 100 HR inspection and found it to be airworthy	Terry Blodgett
		Serviced Prop Accumulator Bottle To 100 LBS	AP3684683742A	
		Nitrogen		
NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12				

M

Date L Prop

REG.

N1268Z

TYPE

2AF36C89

TACH

713 TSO

910.8

1994

Completed ANNUAL inspection IAW FAR 43 app D, AD's researched thru 07-12, 03-13-17, 05-14-11, 06-24-07 D/N/A by vendor. Determined to be in an airworthy condition.

Signature

Craig Bloomer AP391787114IA

Date

July 9, 2007

wo: WO_45

Propeller L - page 1 of 1



East Texas Flying Services - 321 County Rd 2355 - Mineola, TX 75773 - 888-369-5080

N1268Z

HOBBS: 893.9

McCauley (2AF36C89), S/N: 63486

PTSO: 1091.7

August 22, 2025

Inspect Propeller IAW MM. No defects noted. No applicable ADs See AD report

I certify that I have inspected this Propeller in accordance with an annual/100hr. Inspection & that it is in an airworthy condition.

NOTE:

Samuel Schatte A&P IA 3660575