

RIDGEAIRE

AIRCRAFT SALES · ACQUISITIONS · APPRAISALS

RIGHT PROPELLER LOGBOOK



1961 Beechcraft 95-55 Baron

N1268Z

SERIAL NUMBER TC-84

RIGHT PROPELLER LOGBOOK



N 12682 Rt Prop
Log #2

PROPELLER LOGBOOK

Owner Name _____

Address _____

Propeller Model 2AF36C89

Blade Model S78BFS-0

Hub Serial No. 631006

Blade Serial No. 1 DE214YS

2 DE220YS

3 _____

4 _____

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
6/30/86		0	THIS PROPELLER/ [REDACTED] HAS BEEN OVERHAULED/ [REDACTED] AS PER MAINTENANCE RELEASE TAG DATED 6/30/86 AND UNDER WORK ORDER # 16300 FOR: AIRCRAFT PROPELLER SERVICE, INC., WHEELING, ILLINOIS CRS # 2377 BY: <i>Robert R. Hendt</i>	

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
8/27/86	4027	Hobbs	Installed this prop on Beech N12682 Rt. Side After QA by Aircraft Propeller Service tag on preceding page Hobbs 4027 T.T. A/C 4027 T.T. R Prop - 0 - SMOH	

Signed *[Signature]* for
 KENOSHA AERO, INC.
 Repair Station Certificate No. C13-39
 Municipal Airport Kenosha, Wisconsin

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
April 1, 1997	Hobbs 7.2 HRS		AF Total Time	5333.3
			Installed this prop on RH of Beech N1268Z after overhaul 2AF36C89-B5-78 BFS-0 Hub S/N 631049	
			Serviced accumulator to 100 LBS	
			Turned bleed off AP 368468374IA	
			Nitrogen	

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Primeplanes Aircraft Services Inc.
 240 Aviation Drive North Suite 102
 Naples, Florida 34104 ph. 239-659-4005



R Prop
 REG. **N1268Z** TYPE **2AF36C89** TACH **713** TSO **705.8** 1997

Completed ANNUAL inspection IAW FAR 43 app D, AD's researched thru 07-12, 03-13-17, 05-14-11, 06-24-07 D/N/A by vendor, Determined to be in an airworthy condition.

Signature *Craig Bloomer* Date **July 9, 2007**
 Craig Bloomer AP391787114IA

wo: WO_45 Propeller R - page 1 of 1



East Texas Flying Services - 321 County Rd 2355 - Mineola, TX 75773 - 888-369-5080

N1268Z **McCauley (2AF36C89), S/N: 631006** **August 22, 2025**
 HOBBS: 893.9 PISO: 886.7

Inspect Propeller IAW MM. No defects noted. No applicable ADs See AD report

I certify that I have inspected this Propeller in accordance with an annual/100hr. inspection & that it is in an airworthy condition.

Samuel Schatte A&P IA 3660575 *Samuel Schatte*

Y
 tures
 ation
 bers
 11 & 12

N1268Z 12 Prop
Log #1



PROPELLER LOGBOOK

Owner Name _____

Address _____

Propeller Model 2AF36C89

Blade Model 578BFS-0

Hub Serial No. 631006

Blade Serial No. 1 DE216VS

2 DE206VS

3 _____

4 _____

THE NEXT REQUIRING ACTION
REQUIRED ON THIS COMPONENT
PER ~~REWORK~~ 5/13/97B
OR FACTORY RECOMMENDED
T.B.O. IS AT 1200 HRS OR
DATE 1/20/98

THE NEXT REQUIRING ACTION
REQUIRED ON THIS COMPONENT
PER ~~REWORK~~ 5/13/97B
OR FACTORY RECOMMENDED
T.B.O. IS AT 1200 HRS OR
DATE 1/20/98

5

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
6-20-85	3844 T.T. Prop	hobbs -0- smoth	Installed this Prop on Beech N12682 Rt. Side, After o/h by Aircraft Propeller, Serviceable tag on preceding Page.	Signed <u>[Signature]</u> for KENOSHA AERO, INC Repair Station Certificate No. Q13-39 Municipal Airport Kenosha, Wisconsin

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12