N2702L

1981 Cessna 414A

RH Prop Logbook SPOH 2016 - 2025

MSN: 414A-0608



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



PROPELLER MAINTENANCE RECORDS

Aircraft Registration
Propeller Position
Propeller Serial No.

N2702L R/H EB-1554



PROPELLER MAINTENANCE RECORDS

	Log No
Aircraft Registration No. N2702L	
Propeller Manufacturer	-
Hub Model PHC-C34F-24F	
Blade Design No	
Hub Serial No. EB-1554	
Blade Serial No's.	
1	
2	
3	
4	
Pitch Range:	
High Low	
Feather Reverse	
Governor Manufacturer	
Model No	
Serial No	
Date installed on aircraft	
Time Between Overhauls (TBO) Ho	ours
If used on multi-engine aircraft:	
☑ Left ☑ Right	
☐ Front ☐ Rear	

(All applicable information must be filled in)

Waco Regional Airport • P.O. Box 5219 • Waco, Texas 76708 FAX 254-752-3307

Page No. TACH OR TOTAL TIME DESCRIPTION OF WORK PERFORMED-RECORDING TIME DATE METER SINCE SIGNATURE & CERTIFICATE NO OF PERSON PERFORMING WORK N2702L, PROP- S/N EB-1554 Date 3/5/2012 Hobbs 4546.0 Right Side SPOH, 817.3 Removed spinner dome, filled nitrogen to specs (43 PSI) Lubricated hub and dressed blades. AD's checked for compliance to date. I certify that this propeller has been inspected in accordance with a 100/annual inspection and is determined to be in airworthy condition. AD's checked for compliance to date. Twelve Stone Aviation 802 Airport Ave. Hanger 5 Springdale, AR 72764 479-799-8065 N2702L HOBBS: 4719.8 RIGHT PSOH: 976.8 S.N. EB1554 04/01/2013 INSPECTED PROPELLER, SPINNER, AND BACKPLATE IAW ANNUAL INSPECTION, NO DEFECTS NOTED. 21 HOURS ACCUMULATED ON HOBBS DUE TO FAILURE OF SQUAT SWITCH THAT DOES NOT COUNT TOWARD TIME SPOH, ENGINES WERE NOT RUNNING. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION, KEVIN S. DAVIS Twelve Stone Aviation 802 Airport Ave. Hanger 5 Springdale, AR 72764 479-799-8065 N2702L HOBBS: 4784.0 RIGHT PSOH: 1041.0 S.N. EB1554 03/28/2014 INSPECTED PROPELLER, SPINNER, AND BACKPLATE IAW ANNUAL INSPECTION. REPLACED DE-ICE BRUSHES WITH NEW. OPS CK OK. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. KEYIN S. DAVIS

AP431476148IA

SUB-TOTALS this page

TOTALS-Carry forward to next page

age No.			1					
Twelve Stone Aviation	802 Airport Ave. Hanger 5 Springdal	le, AR 72764 479-799-8065				,		Page No
N2702L HOBBS: 330.0	RIGHT PSOH: 1188.0 S.N. E			DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO OF PERSON PERFORMING WORK
INSPECTED PROPELLER, SPI	NNER, AND BACKPLATE IAW ANNUA	L INSPECTION, I CERTIFY		7		,	,	
 THAT THIS PROPELLER HAS INSPECTION AND WAS DETI 	BEEN INSPECTED IN ACCORDANCE VERMINED TO BE IN AIRWORTHY CON	WITH AN ANNUAL DITION.					N2702L,	PROP, P/N, PHC-C3YF-2UF, S# EB1554
KEVIN S. DAVIS					Date 10/4/20	18		
- KisDvi					(Right Side) Hobbs 750.8			
AP431476148TA					SAPA 266.2			
			Į.		Inspected Procheck and ad	op front hub	o for proper a	air pressure and checked to specs per Hartzell Manual. Dressed blades,
Twelve Stone Aviation, LLC.	802 Airport Rd.	Hangar S Springdale, AR 72764	2004 2004	1				
			- 1945 - 1945 - 1945	-	AD's compli	•		
REGISTRATION N2702L MODEL: PHC-C3YF-2UF	HOBBS: 484 6 PROP TSMO: 1342.6 RIGHT SIDE	DATE: 06/29/2016 SN: EB-1554		(Ed Allen	Bu	941, 20	02934
						this propall	ar hac baan i	inspected in accordance with a 100/annual inspection and is determined
REMOVED PROP FOR OVERHAUL BY FO	STERS PROPELLER				to be in airwo	orthy condit	tion.	
KEVIN S DAVIS					<u>مر ک</u>	- FOR	I au	A 470 238276
Ki SD					Tim Rogers	δ		
AP431476148IA				,				
					and the second second			
		The state of the s		·			-	
Twelve Stone Aviation, LLC.	802 Airport Rd.	Hangar 5 Springdale, AR 72764		-		10/5/2018,	New Hobbs ti	me is 994.8
						Right, SPOH	266.2	
REGISTRATION: N2702L MODEL: PHC-C3YF-2UF	HOBBS: 484.6 PROP TSMO: 00 0 RIGHT SIDE	DATE: 07/29/2016 SN: EB-1554				Due to Main	tenance new	Hobbs time is 994.8. This time reflects the same
						Prop time as	previous Hot	obs time reading of 750.8.
 INSTALLED PROP AFTER OVERHAUL BY ANNUAL INSPECTION 	FOSTERS PROPELLER, USING NEW HARDWARE AND O	-RING				Ed Allen	ZLh	cent# A+P3602934
	N ACCORDANCE WITH ANNUAL INSPECTION AND WAS	FOUND TO BE IN AIRWORTHY CONDITION	N					,
KEVIN S DAVIS				2010				
Ki 5Di						7-46	1100.)	44
AP431476148IA				25 MARCH		371.6		ANNVAL INSAECTION COMPLIED WITH PER FAR 43,
The second secon			-					APPENOX D. QNQ AAP 3528389 IA
Twelve Stone Aviation, LLC.	802 Airport Rd.	Hangar 5 Springdale, AR 727	764					
				2021				
REGISTRATION: N2702L MODEL: PHC-C3YF-2UF	HOBBS: 622 2 PROP TSMO: 137 6 RIGHT SIDE	DATE: 09/01/2017 SN: EB-1554		5 MAY		5043	1232.9	SERVICED PROPERLER WITH AEROSHERL 6
								ANNUAL INSPECTION COMPLIED WITH PER FAR 43
 ANNUAL INSPECTION 								APPENDIX D. RRE ANP 3524349 TA
, ^	ED IN ACCORDANCE WITH ANNUAL INSPECTION AND V	WAS FOUND TO BE IN AIRWORTHY CONDI	ITION					SUB-TOTALS this page
KEVIN S DAVIS				-				
Kily								TOTALS—Carry forward to next page

AP431476148IA

Page No			TACH OR	DESCRIPTION OF WORK PERFORMING WORK	(
	TOTAL	TOTAL	RECORDING METER	DESCRIPTION OF WORK PERFORMING WORK	
DATE	I IN	SINCE	TIME		
	SERVICE	- (()	1 1	TOTALS brought forward from previous page	
			1	And the state of t	l
			† 1		
					1
			* -	<i>1</i>	
			1		ł
		All he	Ann. Sept.		
		AIR TOPR	PROPERTY TWANT		į
		79.	29 Karl May D	7. 98 Leartify this Propeller has been	
		Wa	co, Texas 7670	I certify this Propeller has been	
		CRS	S No. AK6R54	I certify this <u>Property</u> inspected in accordance with a 100 HR.	- 1
				Inspection and has been determined	
				to be in an airworthy condition.	1
				DATE 10/04/2021 HM 1240.1	
	1			PROPELLER SMOH51755 (/10)	
	+			WORK ORDER #5246	
				SICNED STATE	
	+			AIR IMPRESSIONS, INC	
				REPAIR STATION # AK6R541N	
	+				
1		1			
		+			
		i			
			1	The state of the s	
	1				
		4.			
	i			_	
	+-	AIR A PARS	NO TING		
	i	PROFESSION	The state of the s		
		7929 Ka	arl May Dr.		
1	1	Waco, T	exas 76708	Leartify this Propeller has been	
		CRS No.	AK6R541N		
Į.				inspected in accordance with a 100 HR.	
	+-			Inspection and has been determined	
1				to be in an airworthy condition.	
				DATE 12/12/2022 HM 1338.6	
1	1			PROPELLER SMOH 610.0 (7/16)	
				WORK ORDER #5597	
1				SIGNED	
				AIR IMPRESSIONS, INC	
1				REPAIR STATION # AK6R541N	
1					
1					
-				OUR TOTAL OUT	
			1	SUB-TOTALS this page	
			1	TOTALO 00000 400000 110000	
			1	TOTALS—Carry forward to next page	

TOTAL DATE SERVICE

TOTAL TIME SINCE OVERHAUL

TIME

TACH OR RECORDING METER

DESCRIPTION OF WORK PERFORMED-SIGNATURE & CERTIFICATE NO OF PERSON PERFORMING WORK

TOTALS brought forward from previous page

THE H COMPANY 1900 CARDIFF RD **BROOKSHIRE TX, 77423 Right Propeller**

11/17/2023 N421LK 421C1017 H/M 0 ACTT 6115.9

McCauley 3AF32C501-A S/N 804728 Prop TTIS 6032.0 Prop TTSMOH 244.9 Completed 100 Hour/Annual inspection this date in accordance with FAR 43 Appendix D and using Cessna 421C maintenance manual as reference inspect prop hub and all blades. Profile blade leading edges. Inspect spinner and spinner bulkhead. Inspect and functionally check deice system. All AD's checked thru bi-weekly 2023/22.

I certify that I have inspected this engine in accordance with current FAR's and a 100 Hour/Annual inspection and was found to be in airworthy condition at this time and is approved for return to service.

Kenneth Griffith AP4872843471A

THE H COMPANY 1900 CARDIFF RD **BROOKSHIRE TX, 77423**

Right Propeller

11/17/2023 N2702L 414A 414A-0608 H/M 1465.6 ACTT 6045.6 Hartzell PHC-C3YF-2UF S/N EB-1554 Prop TTSMOH 737.0

Completed 100 Hour/Annual inspection this date in accordance with FAR 43 Appendix D and using Cessna 421C maintenance manual as a reference. Inspect prop hub and all blades. Profile blade leading edges. Inspect spinner and spinner bulkhead. Inspect and functionally check deice system. All AD's checked thru bi-weekly 2023-22.

I certify that I have inspected this engine in accordance with current FAR's and a 100 Hour/Annual inspection and was found to be in airworthy condition at this time and is approved for return to service.

Kenneth Griffith AP4675543471A

wo: WO_1353

Propeller R - page 1 of 1

September 05, 2024

First Line Aero, LLC · 458 CR 1618 · Rusk, TX 75785 · 903-316-8331

N2702L TACH: 1826.6

SINCE NEW (TACH):

6406.6

Small nick found on RH Prop. Blended prop blade.

The listed maintenance was assited by the following apprentices: Ben Lightfoot

Work performed IRW AC 43.13.1b. Operational check performed, no defects noted at this time. This RH Propeller is approved for return to service.

Andrew Trampus A&P 4896008

SUB-TOTALS this page

TOTALS—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK			
				TOTALS brought forward from previous page			
Mingspan Aviation R/H prop 1322 County Road 1143 Tyler TX, 75704 Date: 18 Apr 25 Tach: Prop: Hartzell PHC-C3Y 1155.4 SN: EB-1554							
was has dete	completed i been inspec ermined to be	n accordance ted in accordance airworthy.	e with Cessna dance with an	r service for overhaul. Reinstalled prop, all work series 414/414A AMM. I certify that this propeller annual inspection guide and has been			
Nam	ne: Colton A	/laughan	Signature:	Cert. No: A&P3928436 IA			
		†					
		 					
		 					
			1				
	 	1					
			+				
			-				
		 	 				
	\						
	,						
·							
	-	 	 				
				SUB-TOTALS this page			
	1	1		TOTALS—Carry forward to next page			

