

# N228HS

## 2003 Cessna T206H

---

# Prop Logbook #2 of 2 | SPOH 2015 - 2024

**MSN: T20608419**



*Prepared by the worldwide aviation specialists at RidgeAire, Inc.*





PROPELLER  
11/16/2015  
REG. NO.: N228HS  
MODEL: B3D36C432-C  
S/N: 020650

McCREERY AVIATION CO., INC.  
P.O. BOX 1659  
McALLEN, TX 78505

TACH: 0724.5  
P.T.T.: 2609.1  
W.O.#: M-16-1927

- COMPLIED WITH AN ANNUAL INSPECTION IN ACCORDANCE WITH CESSNA MODEL T206H MAINTENANCE MANUAL AND INSPECTION CHECKLIST.
- RE-ALIGNED PROP BRUSHES WITH SLIP RING.
- COMPLIED WITH ALL APPLICABLE AD'S AND BI-WEEKLY THRU 2016-21.

I CERTIFY THAT THIS PROPELLER IDENTIFIED ABOVE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND CURRENT FEDERAL AVIATION REGULATIONS AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER NO.: M-16-1927.

DATE: 11/16/2016

SIGNED: \_\_\_\_\_

ANTHONY PRATS

McCREERY AVIATION CO., INC.  
FAA REPAIR STATION NO. CRSHLFR716E  
McALLEN, TX 78503

## Maintenance & Service History

Date	Total Propeller Time	Time Since Overhaul	MAC	of Work	Authorized Signatures & Certificate
PROPELLER 09/29/2017 REG. NO.: N228HS MODEL: B3D36C432-C S/N: 020650			McCREERY AVIATION CO., INC. P.O. BOX 1659 McALLEN, TX 78505		TACH: 0831.5 P.T.T.: 2716.1 W.O.#: M-17-3085
<ul style="list-style-type: none"> <li>→ COMPLIED WITH AN ANNUAL INSPECTION IN ACCORDANCE WITH CESSNA MODEL T206H MAINTENANCE MANUAL AND INSPECTION CHECKLIST.</li> <li>→ REMOVED ALL NICKS AND SCRATCHES TO A SMOOTH SURFACE. PAINTED BACK</li> <li>→ COMPLIED WITH ALL APPLICABLE AD'S AND BI-WEEKLY THRU 2017-19.</li> </ul>					
<p>I CERTIFY THAT THIS PROPELLER IDENTIFIED ABOVE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND CURRENT FEDERAL AVIATION REGULATIONS AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER NO.: M-17-3085.</p>					
DATE: 09/29/2017					
SIGNED: _____		ANTHONY PRATS		McCREERY AVIATION CO., INC. FAA REPAIR STATION NO. CRSHLFR716E McALLEN, TX 78503	





wo: WO\_116

Propeller - page 1 of 1

# FirstXLine

AERO

First Line Aero, LLC - 458 CR 1618 - Rusk, TX 75785 - 903-216-8331

**N228HS**  
Tach: 983.8


Hobbs: 3168.9

June 20, 2019

1. C/W propeller 100 HR inspection IAW FAR43 appendix D with reference to C206 MM.
2. Re-glue propeller de-ice leads and secure with tie-wraps.


Ops and leak checked, no defects noted. All MX performed IAW C206 MM as applicable. With respect to the work performed, this propeller is approved for return to service.

James Stewart A&P 3576016



I certify that this propeller has been inspected IAW an annual inspection and was found to be in an airworthy condition.

Charles Crossman A&P/IA 3440359



wo: WO\_306

Propeller - page 1 of 1

# FirstXLine

AERO

First Line Aero, LLC - 458 CR 1618 - Rusk, TX 75785 - 903-216-8331


**N228HS**  
Tach: 1039.8

Hobbs: 3232.1

July 17, 2020

Completed prop 100 HR insp. No defects noted, all work done in reference to McCauley and Cessna MM. With respect to the work performed, this propeller is approved for return to service.

T.J. Hunter A&P 3554398



Authorized  
Signatures &  
Certificate  
Numbers.



# FirstXLine

AERO

First Line Aero, LLC · 458 CR 1618 · Rusk, TX 75785 · 903-316-8331

**N228HS**


hobbs: 3238.4

tach: 1045.4

**August 19, 2021**

C/W Propeller 100 HR Insp. No defects noted. All work performed with reference to McCauley Propeller MM. With respect to the work performed, this propeller is approved for return to service.

T.J. Hunter A&amp;P/IA 3554698



## Maintenance & Service History

 Authorized  
Signatures &  
Certificate  
Numbers.

 Date  
Propeller  
Time Since  
Overhaul

Description of Work

 Total  
Propeller  
Time

 Date  
Propeller  
Time Since  
Overhaul

 Authorized  
Signatures &  
Certificate  
Numbers.

# FirstXLine

AERO

First Line Aero, LLC · 458 CR 1618 · Rusk, TX 75785 · 903-316-8331

**N228HS**

hobbs: 3334.0


tach: 1045.4

**June 17, 2022**

1. C/W Propeller 100HR inspection using a checklist meeting the requirements of FAR 43 Appendix D.
2. Removed propeller FOM, re-installed with new seal.

With respect to the work performed, this propeller is approved for return to service.

Kenneth Hale A&amp;P/IA 4190268



 ed  
s &  
te  
s.

# FirstXLine

AERO

First Line Aero, LLC · 458 CR 1618 · Rusk, TX 75785 · 903-316-8331

**N228HS**

hobbs: 3396.5

tach: 1119.7

**McCauley, B3D36C432-C, S/N: 020650****July 17, 2023**

C/W 100 HR Propeller Inspection using a prepared checklist IRW FAR 43 Appendix D. No defects noted. With respect to the work performed, this propeller is approved for return to service.

T.J. Hunter A&amp;P/IA 3554698

