


N444KK

2023 Cirrus SR22T

Prop Logbooks



MSN: SR22T-9584

Prepared by the worldwide aviation specialists at RidgeAir, Inc.

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3Y1F-1N

PROPELLER S/N NJ2896B

LOGBOOK # 1

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position ONE

PITCH RANGE

Propeller Model PHC-J3Y1F-IN

High/Feather _____

Propeller S/N NJ2896B

Start Lock _____

Blade Design N7605CB

Low _____

Blade S/N's

Reverse _____

No. 1 E2217

No. 2 E2317

Aircraft Manufacturer CIRRUS DESIGN CORP

No. 3 E2441

Aircraft Model SR22T

No. 4 _____



S/N 9584



No. 5 _____

Registration N444KK

No. 6 _____

Spinner Assembly Part No. _____

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				<div style="display: flex; justify-content: space-between;"> <div> <p>PROP MODEL: PHC-J3Y1F-1N PROP S/N: NJ2896B REG. NO: N444KK WORK ORDER: 6773-12-2024</p> </div> <div style="text-align: center;">  <p>Houston Aviation Center, LLC 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800</p> </div> <div> <p>DATE: 1/10/2025 A/C TSN: 145.3 PROP TT: 145.3 HOBBS: 183.2</p> </div> </div> <p>Prop Entries</p> <p>(Flight Meter: 145.3) Completed a 100 HR/Annual Inspection Ref. CDC SR22T AMM 5-20 and Hartzell Propeller Owner's Manual No. 145. Inspected propeller blades and ice feed shoes. Inspected and lubricated propeller hub. Checked blade track. Checked ADs thru BW 2025-01.... I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy condition.</p> <p>Maintenance Release</p> <p>The aircraft and/or component(s) on N444KK was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 6773-12-2024.</p> <div style="display: flex; justify-content: space-between;"> <p>DATE: 1/10/2025</p> <p>SIGNED:  Fouad Hussain, A&P: 3204861 IA</p> <p>Work Order: 6773-12-2024 Printed by EBis 3 (datcomedia.com)</p> </div>

				<div style="display: flex; justify-content: space-between;"> <div> <p>PROP MODEL: PHC-J3Y1F-1N PROP S/N: NJ2896B REG. NO: N444KK WORK ORDER: 6924-08-2025</p> </div> <div style="text-align: center;">  <p>Houston Aviation Center, LLC 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800</p> </div> <div> <p>DATE: 9/9/2025 A/C TSN: 236.3 PROP TT: 236.3 HOBBS: 295.4</p> </div> </div> <p>Prop Entries</p> <p>(Flight Meter: 236.3) Performed Propeller 100 HR Inspection IAW Cirrus AMM 5-20. Checked ADs thru BW 2025-18.</p> <p>Maintenance Release</p> <p>The aircraft and/or component(s) on N444KK was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 6924-08-2025.</p> <div style="display: flex; justify-content: space-between;"> <p>DATE: 9/9/2025</p> <p>SIGNED:  Benny Mai, A&P: 4657721</p> <p>Work Order: 6924-08-2025 Printed by EBis 3 (datcomedia.com)</p> </div>