

RIDGEAIRE

AIRCRAFT SALES · ACQUISITIONS · APPRAISALS

LEFT PROPELLER LOGBOOK




1961 Beechcraft 95-55 Baron

N1268Z

SERIAL NUMBER TC-84

LEFT PROPELLER LOGBOOK



LC #

**3861 Co. Rd. 140
Findlay, Ohio 45840
1-800-553-7767
Fax 419-299-3244**

Propeller Log Book

N/2682

Owner Name North Country Aviation

Address 1258 Vantyle Rd

Gaylord MI 49735

Propeller Make McCabe

Propeller Model 2AF36C24

Blade Model 570 BES-0

Hub Serial No. 63486 (R/R Hub S/N 63906)

Blade Serial No. 1 K2770045

2 K2774645

3

4

PITCH RANGE

High Latch 18.0 Low 15.0

Feather 79.0 Reverse

Maximum Hours or Service Life between overhaul required by Mfg. 1200 Hrs. or 5

years interval between overhauls.

Owner Name North Country Aviation

Address 1258 Vantyle Rd

Gaylord MI 49735

Propeller Make McCaughey

Propeller Model 2AF36C2.9

Blade Model 570 BES-D

Hub Serial No. 63486 (R/R Hub S/N 63906)

Blade Serial No. 1 K2770045

2 K2774645

3

4

PITCH RANGE

High Latch 18.0

Low 15.0

Feather 79.0

Reverse

Maximum Hours or Service Life between overhaul required by Mfg. 1200 Hrs. or 5

years interval between overhauls.

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Date <u>09-01-74</u> Propeller Total Time _____ Tach/Hobbs Time _____ Propeller Time Since Overhaul <u>0</u> <u>Completely Overhauled propeller Assembly and install Alcohol feed shoes in accordance with McCauley service Manual # 710930. Service Letters: 74-3, 77-4, 81-14, 83-2, 83-8-1, 7-3, 91-11A, 92-12, 93-3 & Service Bulletins: 93, 99, 99-1, 99-2, 99-3, 106, 110, 137E, 150 & End</u> Work Performed By Priebe Propeller Shop, Inc. Repair Station #IC5R930M. Work Order/Invoice # <u>11642</u> Signature <u>[Signature]</u>				

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
<u>9-8-94</u>	<u>Hobbs 5128</u>	<u>Install this prop on N12582</u>	<u>Left Engine. Wash tank & q's check OK.</u>	
		<u>High Chaffin 1A37 862787.</u>		
<u>6/22/2009</u>	<u>9116.4</u>	<u>PERFORMED</u>	<u>ANNUAL INSPECTION</u>	<u>[Signature]</u>
<u>IT 6039.4</u>	<u>ANNUAL</u>	<u>INSPECTION</u>	<u>326487057</u>	
<u>9/16/16</u>	<u>6162.7</u>	<u>CW ANNUAL INSPECTION</u>	<u>STW McCauley REQUIREMENTS. Found</u>	
		<u>TO BE IN AIR WORTHY CONDITION. RETURN TO SERVICE</u>	<u>[Signature]</u>	<u>FA326PTTS</u>

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Date <u>09-01-94</u> Propeller Total Time _____ Tach/Hobbs Time _____ Propeller Time Since Overhaul <u>0</u> <u>Completely Overhauled propeller Assembly and install Alcohol feed shoes in accordance with McCauley service Manual # 710430. Service Letters: 74-3, 77-4, 81-19, 83-9, 83-8-1, 87-3, 91-11A, 92-12, 93-3-1/2 Service Bulletins: 93, 99, 99-1, 99-2, 99-3, 106, 110, 137E, 150 K End</u> Work Performed By Priebe Propeller Shop, Inc. Repair Station #IC5R930M. Work Order/Invoice # <u>11600</u> Signature <u>[Signature]</u>				

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
<u>9-8-94</u>	<u>Hobbs 5128</u>	<u>Install this prop on</u>	<u>N12582</u>	
<u>Left</u>	<u>Engine</u>	<u>Wash ton</u>	<u>leak & q's check OK.</u>	
	<u>High Chaffin</u>	<u>TA37862787.</u>		
<u>6/22/2009</u>	<u>9116.4</u>	<u>PERFORMED</u>	<u>Annual</u>	<u>[Signature]</u>
<u>TT 6039.4</u>	<u>ANNUAL</u>	<u>INSPECTION</u>	<u>326487057</u>	
<u>9/13/16</u>	<u>6162.7</u>	<u>CW ANNUAL INSPECTION IAW McCAULEY REQUIREMENTS. Found</u>	<u>T. BE IN Air WORTHY COND.TION. RETURN TO SERVICE</u>	
		<u>Chal [Signature]</u>	<u>TA3268838</u>	